BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group Co, Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941

Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944

Sime Darby Busines Singapore 159944 Tel. 63190528 63190533/530 Fax. 64796601 64796624 (AfterSales)

Excess

Total GST @ 7%

Grand Total

206.85

3,161.85

GST REG. NO : M2 - 0020081 - X

ESTIMATE



Not reputed Rufer to today

Page No. : 1 of 1 Estimate No. : b1 46183 Date Estimated : 12/03/2018 Prepared By : Kevin Leong Wai Kit - ESTIMATE REPAIR FOR -- ACCOUNT -40000 Ong Seok Lian Aileen Cash Sales - Service 16A Butterfly Avenue Singapore Singapore 349781 REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE SDW5522J DX54049 26/06/2013 520iA 0 VALUE DESCRIPTION To making good on front bumper including remove and install all attachments to facilitate with repair work. 15 - 52 Painting on front bumper assembly -14 To check electrical wiring systems at the front section for proper function. Sundries. 40.00 Total Labour 1: 2,955.00 Claims OD / 3rd Party / Uninsured losses / Direct Settlement LKK Auto Consultants hence notify the Repairer of the following: 103/18 @1435 Date & Time 29 To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation 900100 68 Third party survey is on a "Without Prejudice" basis . No illegal modification(s) is allowed · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: Labour 1 2,955.00 Parts 0.00 0.00 Labour 2 0.00

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **