



GST / ROC Company No :

201101753C

Third Party Insurer :

INDIA

Insured's Veh No :

SH8184H

Date of accident :

15/03/2018

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

not submit
Mar
20/3/18
The photo before painting
4 day

Quotation No : AR/QO18/03-1021
Quotation Date : 16/03/2018

Estimate To Repair

MAZDA 5

Vehicle No :

SLV1875C

Chassis No :

JM6CW1071H0126624

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
SPARE PARTS			
1	1PC	REAR BUMPER	DD \$960.50
2	2PC	REAR BUMPER SIDE RETAINER @\$58.5	01524 \$117.00
3	10PC	REAR BUMPER CLIPS @\$5.50	122 \$58.00
4	1PC	REAR BUMPER TOP GARNISH	122
5	1PC	REAR BUMPER REFLECTOR RH	520 \$55.00
6	1PC	REAR BUMPER REINFORCEMENT	\$185.80
7	1PC	REAR TAIL LAMP RH	\$605.30
8	1PC	REAR END PANEL	\$495.50
9	1PC	END PANEL TOP GARNISH	11
10	8PC	TOP GARNISH CLIPS	11
11	1PC	REAR GATE	1 \$1,550.80
12	1PC	REAR GATE LOCK	11 \$325.50
13	1PC	REAR GATE LOGO	11 \$65.00
14	1PC	REAR GATE "MAZDA" PLATE	122 \$55.50
15	1PC	REAR GATE "5" PLATE	122 \$45.00
16	1PC	REAR GATE "SKYACTIVE TECHNOLOGY" PLATE	122 \$115.50
17	1PC	REAR GATE LAMP RH	11 \$429.90
			\$5,064.30
LESS 20%			\$1,012.86
			\$4,051.44
MISC ITEMS			
1		REAR NUMBER PLATE	11 \$40.00
2		REAR REVERSE SENSOR	122 \$250.00
3		REAR WINDSCREEN GUM	11 \$60.00
Total			\$350.00
LABOUR & MISC. CHARGES			
1		WIRE CHECKING	\$20.00
2		REMOVE & REFIX REAR WINDSCREEN	11 \$120.00
3		CAVITY PROTECTION ON ALL AFFECTED AREAS	\$100.00
4		LABOUR CHARGE	\$800.00
5		SPRAY PAINTING	\$800.00
Total			\$1,840.00

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883
GARY 8338 8418



GST / ROC Company No : 201101753C

Third Party Insurer : INDIA

Insured's Veh No : SH8184H

Date of accident : 15/03/2018

Grab Rentals Pte Ltd

18 Sin Ming Lane

#01-08 Midview City

Singapore 573960

Quotation No : AR/QO18/03-1021

Quotation Date : 16/03/2018

Estimate To Repair

MAZDA 5

Vehicle No :

SLV1875C

Chassis No :

JM6CW1071H0126624

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
		Sub Total	\$6,241.44
		GST (7.00%)	\$436.90
		Total	\$6,678.34
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418