

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3229C

DATE 16/3/2018 13:49

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ - 603.60
	Rear Bumper Reinforcement ?			\$ 1 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 2 360.00
	Rear Bumper Side Bracket ?		\$ 49.00	\$ 2 98.00
	Rear Bumper Clips ✓			\$ - 22.00
	Rear Bumper Sponge ?			\$ 2 143.40
	Rear Bumper Under Cover ✓			\$ - 225.00
	Rear Bumper Reflector Lamp (LH) ✓			\$ - 32.00
	Rear Panel X repair			\$ 592.30
	Rear Panel Garnish ?			\$ 2 57.70
	Rear Panel Lower Panel X repair			\$ 495.50
	Exhaust Pipe Insulator, LH ?			\$ 2 58.55
	Exhaust Silencer, LH ?			\$ 2 954.00
	Exhaust Pipe Hanger, LH ?			\$ 2 58.55
	Exhaust Pipe Centre ?			\$ 2 1,150.30
	Rear Fender (LH) X repair			\$ 2,020.10
	Rear Fender Inner Lining (LH) X			\$ 164.40
	Rear Windscreen Moulding X			\$ 60.00

Larry Ng

Kali 11064

16/3/18 1530h

3/2

After Repair p44