

Email on 29/3/18.

Fong Motors

1, Kaki Bukit Ave 6, #01-45/27, Autobay, Singapore 417883

Vehicle No. CB7067R
 Make/Model TOYOTA COMMUTER GL 3.0A
 Year :
 Chassis No. KDH2230026242

TP AIG.

Vic

DATE:

27/3/2018

KDH2230026242

PARTS LIST

			Unit Price		
1	1 pc	REAR BOOT LID <i>Painted</i>	\$ 2,150.70	\$	<u>2,150.70</u> 1824
2	1 pc	TOYOTA EMBLEM	\$ 48.60	\$	48.60 ✓
3	1 pc	HIACE EMBLEM	\$ 46.30	\$	46.30 ✓
4	1 pc	GL EMBLEM	\$ 41.90	\$	41.90 ✓
5	1 pc	REAR BOOT LID LOCK <i>Damaged</i>	\$ 269.60	\$	269.60 ✓
6	1 pc	REAR END PANEL <i>Repaired</i>	\$ 375.30	\$	375.30 ✓
7	1 pc	REAR BUMPER <i>Deformed</i>	\$ 384.70	\$	384.70 ✓
8	4 pc	REAR BUMPER BRACKET <i>Best</i>	\$ 25.40	\$	105.60 ✓
9	6 pc	REAR BUMPER CLIP <i>new</i>	\$ 3.80	\$	22.80 ✓
<i>2 piece Rear Bumper Side Holder new</i>			\$ 47.50 95 ✓	\$	<u>3,445.50</u>

LABOUR CHARGE

1SET STICKER *new*
 REAR WINDSCREEN GLASS SEALANT *new*
 REVERSE SENSOR *Damaged*
 TO REMOVE AND REFIT REAR WINDSCREEN GLASS
 TO REMOVE AND REPLACE REVERSE SENSOR
 TO CHECK WIRING
 TO KNOCK AND CHANGE PARTS
 TO SPRAY PAINT THE AFFECTED AREA
 TUFF KOTE

\$	100.00 SN	60 (SN)
\$	50.00 SN	✓
\$	360.40 SN	220
\$	150.00	120
\$	100.00	60
\$	120.00	30
\$	700.00	500
\$	700.00	450
\$	80.00	x
\$	<u>5,805.90</u>	

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FONG MOTORS

total: 3688.87
 L/S: 2.9K
 04 Days

2.9K

04 Days

67485648