

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0345/2018/GW
Date : 20-Mar-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Soh Heng Lye
Address : Blk 459 Segar Road
#16-185
Singapore 670459
Telephone : HP +65 97247674
Type of Claim : Third party claims
Policy No. :
Vehicle No : **SLM 929 K**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Feb-17
Engine No : CVN022712
Chassis No : WAUZZZF42HA063454
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Mar-18
Place of Accident : CTE TOWARDS SLE VEF AMK AVE 1 EXIT

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 929 K.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓	
2	To renew rhs 1/4 glass and rear windscreen to facillitate fender renewal.	S/N \$ 600.00 ✗	
3	To remove and trasnfer rear lid's convenience lock sys tem, wire harness for tail lights and rear wiper assy.	S/N \$ 480.00 ✓	
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00 ✗	
5	To rempve and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✗	
6	To dismantle rear bumper and rear lid. Cut out and weld rear and end panels, rhs rear fender tail lamp panel reinforcement. Renew rear bumper and rear lid. Re-oraganise rear crash management components. Reinstall all parts removed.	\$ 6,900.00 1250.	
7	To respray rear biumppe, rear lid, rhs rear fender, rhs sill panel, drain panel, roof channel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 4,900.00 2200.	
8	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 16,152.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 929 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Distorted</i>	\$ 1,907.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 63.00	✓
3	RREAR BUMP[ER SPOILER <i>cut</i>	\$ 216.00	✓
4	REAR BUMPER SECURING STRIP <i>distorted ?</i>	\$ 191.00	?
5	REAR BUMPER SENSOR <i>1 piece damaged</i>	2 \$ 421.00 210.50	
6	REAR BUMPER SENSOR SEAL RING <i>?</i>	4 \$ 15.00	?
7	REAR BUMPER WIRING SET <i>?</i>	\$ 598.00	?
8	REAR BUMPER CARRIER <i>Best</i>	\$ 786.00	✓
9	REAR BUMPER GUIDE SECTION-RH <i>?</i>	\$ 38.00	?
10	REAR BUMPER LOWER GUIDE SECTION-RH <i>?</i>	\$ 19.00	?
11	REAR LID <i>Distorted</i>	\$ 2,362.00	✓
12	REAR LID ATTCHMENT PART <i>new</i>	\$ 125.00	✓
13	REAR LID LOCK <i>new</i>	\$ 202.00	✓
14	REAR LID LOCK STRIKER <i>new</i>	\$ 29.00	✓
15	REAR LID GASKET FLAP <i>new</i>	\$ 176.00	✓
16	ADHESIVE PACKING <i>new</i>	\$ 15.00	✓
17	AUDI EMBLEM <i>new</i>	\$ 108.00	✓
18	LED TAILLIGHT-RH <i>cut</i>	2 \$ 1,731.00	✓
19	LED TAILLIGHT TRIM-RH	2 \$ 52.00	
20	REAR LIGHT REFLECTOR-RH <i>?</i>	\$ 35.00	?
SUB - TOTAL SPARE PARTS CHARGES		: \$ 9,089.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 929 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	SIDE PANEL -RH <i>Rp's</i>	\$ 2,347.00	*
22	SIDE PANEL REINFORCEMENT-RH <i>new</i>	\$ 180.00	*
23	VENT TRIM <i>new</i>	\$ 60.00	*
24	REAR WINDOW <i>new</i>	\$ 1,014.00	*
25	REAR SIDE WINDOW <i>new</i>	\$ 541.00	*
26	PRIMER <i>new</i>	2 \$ 37.00	*
27	REAR CROSS PANEL ?	\$ 230.00	?
28	REAR CROSS PANEL REINFORCEMENT ?	\$ 445.00	?
29	1/4 GLASS SEALANT <i>new</i>	S/N \$ 100.00	*
30	REAR WINSCREEN SEALANT <i>new</i>	S/N \$ 200.00	*
31	ACRYLIC SEALER ?	S/N \$ 180.00	?
32	CAVITY WAX ?	S/N \$ 140.00	?
33	STONE CHIP ?	S/N \$ 180.00	?
34	METAL FILLER POWDER ?	S/N \$ 280.00	?
35	SUNDRIES ?	\$ 600.00	?
TOTAL SPARE PARTS CHARGES		: \$ 15,623.00	
TOTAL LABOUR CHARGES		\$ 16,152.00	
GRAND TOTAL		<u>\$ 31,775.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 20/03/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant