

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	68411183
Reference	:	PA/TP/0349/2018/GW
Date	:	20-Mar-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Chong Aik Siew
Address	:	12 Ang Mo Kio Central 3 #08-17 Singapore 567746
Telephone	:	HP +65 98315881
Type of Claim	:	Thrid party claims
Policy No.	:	2100467933-0100
Vehicle No	:	SLC 8314 J
Model Code	:	Audi A3 Sedan 1.4 TFSI
Model / Year	:	May-16
Engine No	:	CZC 529704
Chassis No	:	WAUZZZ8V761084126
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	17-Mar-18
Place of Accident	:	Ang Mo Kio Street 22

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 8314 J.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rhs front and rear door's multi-lock systems and power window devices. Inspect for damages and renew if necessary.	S/N \$ 560.00	✓
2	To remove and reinstall rhs front seat assy, abcd pillar trims, sill trims, floor carpets, electronic components and fuse trays. Disengage rhs seat belt and head airbag.	S/N \$ 1,800.00	✓
3	To remove rhs front and rear doors, cut out and reweld rhs sill panel and B-pillar. Renew rhs front and rear doors, transfer old fittings and align to position. Reinstall all parts removed.	\$ 5,100.00 3000 .	
4	To repspray rhs front and rear doors, rhs sill panel, door entrances, B-pillar and rhs rear fender. To carry out joint sealer works and carry out stone chip treatment.	\$ 4,500.00 2750	
5	To renew rhs rear rim and carry out wheel alignment .	S/N \$ 280.00	X
6	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 12,432.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 8314 J.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR-RH <i>Distorted</i>	\$ 2,190.00	✓
2	FRONT OUTER DOOR SEAL-RH <i>new</i>	\$ 139.00	✓
3	BONDING AGENT <i>?</i>	\$ 43.00	?
4	FRONT DOOR CATCH-RH <i>new</i>	\$ 92.00	✓
5	FRONT EXTERIOIR DOOR HANDLE-RH <i>new</i>	\$ 207.00	✓
6	FRONT WINDOW REGULATOR <i>?</i>	\$ 232.00	?
7	DATA PLATE FOR TYRE PRESSURE <i>new</i>	\$ 25.00	✓
8	REAR DOOR-RH <i>Distorted</i>	\$ 2,190.00	✓
9	REAR OUTER DOOR SEAL-RH <i>new</i>	\$ 139.00	✓
10	BONDING AGENT <i>?</i>	\$ 43.00	?
11	REAR DOOR HINGE-RH <i>?</i>	\$ 73.00	✓
12	REAR DOOR UPPER HINGE-RH <i>new</i>	\$ 108.00	✓
13	REAR DOOR LOWER HINGE-RH <i>new</i>	\$ 72.00	✓
14	REAR DOOR CATCH-RH	\$ 82.00	✓
15	FRONT FENDER TOP COVER-LH <i>new</i>	\$ 24.00	✓
16	SIDE MEMBER -RH <i>Tested</i>	\$ 2,038.00	✓
17	REAR ALUMINIUM RIM-RH <i>new</i>	\$ 645.00	✓
18	RUBBER VALVE <i>new</i>	\$ 14.00	✓
19	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 8,656.00	
TOTAL LABOUR CHARGES		\$ 12,432.00	
GRAND TOTAL		\$ 21,088.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim.
Surveyed Date : 23/03/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 09 days

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant