

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person)

Peter Wong

of

ASM

Date/Time

19/3/18

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SBE 3300P

Insured:

at Workshop m/s

BH Auto

Tel:

6559 8944

of

Blk 1 Sec C # 01-111 Sin Ming Ind. Est

Policy No.

Claim No.

S8M00AMT

Sum Insured:

Excess:

NIL

Make of Veh:

D.O.A.

12/08/2008

(Client's Record)

☒ CA / REV / REP. / REV 24 HRS

20/03/2008

H.O.D. Endorsement:

Date/Time

3:12pm

Person Contacted:

Wenjheng

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

20/3-

SBE 3300P - CC3/AIG 09012377/Zq
upload 1A in SMART CLAIM

D.O.A: 30/5/2009

Part by Part \$7442/- (Red: 9249, 56%)

Form No.

REF: ASM(AXA) CS/ASM18005107/Ktd3

ASSIGNMENT

From:

Date:

2013/18

Estimated Cost:

☒ DD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SBE 3300P

at Workshop m/s

BH Auto

of Blk I, Sec C, Sin Ming Ind. Est. # 01-111

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$ NIL

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$ 83k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res.: Yes or No

Lum Sum:

1-13.1 %

3 Val.: Yes or No

☒ CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SBE 3300P

Yr Regn:

06 / 14

Type: ☒ M Car / ☐ M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen

Passat

1798

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading:

3359P

T/Radio: Insured / Std / NI / NA

Eng/No:

WVW 288307EE049675

C/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

12/13/18

D.O.I.

20/13/18

Survey held at

Des. of Damages: ☒ Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/3 13k pass to Carham

RECEIVED 3 5 17 2013

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

8

1) 9/15 Typist

☒

: Final Report

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Insp (\$

☐

: Weekend (\$

3) \$ + RS + SI

4) Photos

5) Others

Report Format :

OD

Lump Sum / (BY) (\$

7442

TOTAL

250



Service Request Details

Claim

S8M00AMT

Reference

None 

Loss Date

March 12, 2018

Request Date

March 19, 2018

Due Date

March 26, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SBE3300P

Make

VOLKSWAGEN

$$N_{\text{eff}} = \frac{\pi^2}{90} g(T) T^4 / (\rho_m + \rho_r) = \left(\frac{T}{T_0} \right)^4 \frac{g(T)}{g(T_0)},$$
[illegible][illegible][illegible]

Notes

© 2007 Pearson Education, Inc.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobiles

AXA INSURANCE PTE LTD

Ref : CS/ASM18005107/Ktd3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 19-03-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SBE 3300P
Policy No.	Coverage (\$)	0.00
Claim No. S8M00AMT	Excess (\$)	0.00
Assign From SMARTCLAIM (PETER WANG)	Assign Date	19/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 12/08/2018	Inspection Date
Survey held at BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/03/2018 12:55
Date Of Accident	12/03/2018 16:50
Exact Location Of Accident	DOVER RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBE3300P
Insured/Policyholder	
Name Of Registered Owner	TAN SIEW KIAN LINDA
NRIC No	S7405312B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96530374
Alternative Phone No	OFFICE-96530374
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	PASSAT 1.8 TSI AT 3624H7 HID
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USED
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1516581
Cover Note Number	
Driver	
Name of Driver	TAN SIEW KIAN LINDA
NRIC No	S7405312B
Date Of Birth	09/02/1974
Occupation	INDOOR
Date Of Driving Pass	28/06/2002
Driving Experience	15 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96530374
Fax Number	
Contact Number	OFFICE-96530374
EEmail Address	NOEMAIL

Address	35 MING TECK PARK
Postcode	277402
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKE8868D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

[illegible]

5-01776

42

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

2) Turning into Burger King on green light

3) Collided with another car SRF 88681D

3) was hit on the front left

DECLARATION

(f) We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time _____

Driver's Signature _____
 (It drives almost like an airplane!)

Reporting Centre Personnel's Signature
Name
Title

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5312B

Vehicle Details

Vehicle No.: SBE3300P
Vehicle to be Exported: No
Intended De-registration Date: 13 Mar 2018
Vehicle Make: VOLKSWAGEN
Vehicle Model: PASSAT 1.8 TSI AT 3624H7 HID
Primary Colour: White
Manufacturing Year: 2013
Engine No.: CDA426204
Chassis No.: WVVZZZ3CZEE049675
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$26,752.00
Original Registration Date: 20 Jun 2014
First Registration Date: 20 Jun 2014
Transfer Count: 0
Actual ARF Paid: \$29,453.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 19 Jun 2024
PARF Rebate Amount: \$22,089.00

Intended COE Rebate Details

COE Expiry Date: 19 Jun 2024
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$70,002.00
COE Rebate Amount: \$43,867.00
Total Rebate Amount: \$65,956.00

The information contained herein is correct as at 13 Mar 2018

OK

FairPrice Online www.fairprice.com.sg

Up to 80% off

BABY FAIR

More than 30 brands

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Mercedes £168K



Well Maintained, Regular Servicing,
Direct Owner - 10y 7c

KA-HUP

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997 view our cars

« Back (1 2 3 4) Next »

Sort by Date Posted 20 results/page

75 vehicles

Volkswagen Passat

Begin Search

Price Any price Depre Any depre Reg Date Any date Eng Cap Any Veh Type All types
Fuel Any fuel Mileage Any OMV Any Gear Any Gear Past Owners Any
Category All categories Scheme All schemes Dealer Any Dealer Location Any Status Available

Make & Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
 Volkswagen Passat 1.4A TSI	\$66,800	\$10,700 /yr	30-Apr-2013	1,390 cc	-	Luxury	Available

Elegant White, Serviced By Agent In July 2017, One Owner Only, Accident Free, Spacious Sedan, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-House Loan Packages Available.

Prime Motor & Leasing

Posted: 13-Mar-2018 Tags: 2013 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen

 Volkswagen Passat CC 1.8T	\$33,000	\$8,330 /yr	23-Apr-2010	1,798 cc	153,000 km	Luxury	Available
--	----------	-------------	-------------	----------	------------	--------	-----------

From Only \$506 Per Month! Reliable And Affordable! Good For Short Term Usage! Cheaper Than Renting! Economical And Powerful Engine. No Repairs Needed. Easy Loan Approval And Highest Trade In Value For...

TTS Eurocars

Posted: 12-Mar-2018 Tags: 2010 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen

 Volkswagen Passat CC 1.8T	\$48,988	\$10,880 /yr	29-Mar-2011	1,798 cc	120,000 km	Luxury	Available
--	----------	--------------	-------------	----------	------------	--------	-----------

Promo 1.78% Interest! No Repairs Needed! High Approval Rate. All Vehicles Are Inspected By Our Professional Team For Highest Quality. Extended Warranty Available. Mint Condition! High Trade In Are Wel...

Hamilton Autohub Pte Ltd

Posted: 12-Mar-2018 Tags: 2011 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen

 Volkswagen Passat CC 1.8T	\$55,151	\$12,710 /yr	15-Apr-2011	1,798 cc	-	Luxury	Available
--	----------	--------------	-------------	----------	---	--------	-----------

Beautiful Unit With Original Condition! Peace Of Mind! Serviced Regularly. Well Maintained By Previous Careful Owner. One Of The Most Popular And Reliable Luxury Sedan In The Market! Trade In Welcome....

Dosh Car

Posted: 12-Mar-2018 Tags: 2011 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen

Car Buying

Car Selling

Car Aftermarket

Buying a pre-owned car, but
Unsure of its Condition?
Get STA Car Evaluation

Car Ownership

On The Move

Lifestyle

 Volkswagen Passat CC 1.8A TSI	\$62,800	\$12,340 /yr	17-Jan-2012	1,798 cc	53,000 km	Luxury	Available
--	----------	--------------	-------------	----------	-----------	--------	-----------

Elegant White, Low Mileage Done, Powerful Drive, Serviced By Agent, With Navigation System, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In House Loan Packages Available.

Prime Motor & Leasing

Posted: 11-Mar-2018 Tags: 2012 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen

 Volkswagen Passat 1.4A TSI	\$83,800	\$10,510 /yr	27-Mar-2015	1,390 cc	63,000 km	Luxury	Available
---	----------	--------------	-------------	----------	-----------	--------	-----------

Spacious And Large German Family Sedan For Your Family, Also Comes With A Huge Boot For Your Luggage! 1.4L Turbo Engine Provides You With Sufficient Oomph To Get Around Daily, Yet Returning Good Fuel ...

AL Autocar Pte Ltd

Posted: 11-Mar-2018 Tags: 2015 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat 1.8T **\$31,800** **\$9,760 /yr** **23-Nov-2009** **1,798 cc** **103,382 km** **Luxury** **Available**

1 Owner Come With Low Mileage Unit In Excellent Condition. Very Well Taken Care By Owner. 80% Loan Possible. One Of The Most Popular And Reliable Luxury Sedan In The Market! Trade In Welcome. Loan Up ...

Posted: 10-Mar-2018 Tags: 2009 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat 1.8A TSI **\$55,800** **\$11,060 /yr** **01-Dec-2011** **1,798 cc** **64,320 km** **Luxury** **Available**

1 Owner, Fully Maintained And Serviced With Agent Since Day One With Record To Prove. Low Mileage Done 64320km. Still In Original Condition And Paintwork! Accident Free! Most Wear And Tear Parts Repla...

Posted: 10-Mar-2018 Tags: 2011 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat 1.8A TSI **\$80,300** **\$10,840 /yr** **31-Mar-2014** **1,798 cc** **49,000 km** **Luxury** **Available**

Free 1 Year Warranty! Volkswagen Optical Parking System Upgraded! 100% Serviced And Maintained At Volkswagen SGI High Paper Value To Ensure You Don't Lose Paper Value! 100% Accident Free! STA Evaluati...

ST Carz Pte Ltd

Posted: 10-Mar-2018 Tags: 2014 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat CC 1.8T **\$47,800** **\$11,540 /yr** **04-Jan-2011** **1,798 cc** **85,000 km** **Luxury** **Available**

10% Down Payment Available. Tip Top Condition. Warranty And Free Servicing Package Provided. Call Now For Viewing.

Performance Carz Pte Ltd

Posted: 10-Mar-2018 Tags: 2011 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat 1.8A TSI **\$85,800** **\$10,940 /yr** **05-Aug-2014** **1,798 cc** **59,353 km** **Luxury** **Available**

Graded B by **STA**

Maintance By Agent. One Owner Only, Low Mileage, Well Kept By Previous Owner. Very Neat Interior And Exterior. Powerful Turbo Charged Engine, Sporty And Luxuries Drive. Stable Road Holding And Comfort ...

Autolink Holdings Pte Ltd

Posted: 10-Mar-2018 Tags: 2014 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat 2.0A TSI **\$144,800** **\$13,920 /yr** **22-Feb-2017** **1,984 cc** **-** **Luxury** **Available**

No Chassis/Structural Damage, Warranty By Volkswagen Centre Singapore. Buy With A Peace Of Mind. Contact Us To Arrange For Test Drive Now, Before This Hot Chick Fly Out Of The Showroom!

Posted: 10-Mar-2018 Tags: 2017 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat 2.0A TSI R-Line **\$153,988** **\$14,310 /yr** **28-Jul-2017** **1,984 cc** **8,380 km** **Luxury** **Available**

Singapore's Only Certified Volkswagen Pre-Owned Centre, The Only Place To Find Volkswagen Management Units! 115 Points Check By Volkswagen, Certified Vehicle History And Mileage, No Chassis/Structural...

Das WeltAuto

Posted: 10-Mar-2018 Tags: 2017 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat 1.8A TSI **\$73,800** **\$17,470 /yr** **01-Aug-2011** **1,798 cc** **129,000 km** **Luxury** **Available**

Promo 1.78% Interest! No Repairs Needed! Free Extended Premium Warranty And Servicing! All Vehicles Are Inspected By Our Professional Team For Highest Quality Assurance! Bank And In House Loan Availab...

Hamilton Autohub Pte Ltd

Posted: 10-Mar-2018 Tags: 2011 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat 1.4A TSI **\$83,666** **\$10,960 /yr** **31-Oct-2014** **1,390 cc** **34,250 km** **Luxury** **Available**

Spacious And Large German Family Sedan For Your Family, Also Comes With A Huge Boot For Your Luggage! 1.4L Turbo Engine Provides You With Sufficient To Get Around Daily, Yet Returning Good Fuel Effici...

Creative Auto

Posted: 10-Mar-2018 Tags: 2014 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat CC 2.0A TSI **\$25,800** **\$9,060 /yr** **04-Feb-2009** **1,984 cc** **-** **Luxury** **Available**

Popular And Powerful Luxury Sedan Vehicle. Low Fuel Consumption Of 13.6Km / Litre. Guaranteed Accident Free, Original Stock Condition. All Major Parts Replaced. Selling At Low Depreciation. Free Servi...

Posted: 09-Mar-2018 Tags: 2009 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat CC 1.8A TSI **\$75,800** **\$13,000 /yr** **17-Sep-2012** **1,798 cc** **74,283 km** **Luxury** **Available**

Up To 90% Loan Available. Buy With A Peace Of Mind! Powerful Turbo Charged Engine! Spacious And Luxury. Low Mileage And New Facelift Model, Always In Sheltered Car Park. Well Balanced Drive Ability, P...

Posted: 09-Mar-2018 Tags: 2012 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen

Volkswagen Passat 1.8T **\$54,800** **\$10,820 /yr** **17-Oct-2011** **1,798 cc** **106,000 km** **Luxury** **Available**

5 Seater Passat CC in superb Condition, Very Well Maintained By Previous Owner. High Paper Value Of \$44500. Major Servicing Done By Agent aligned By Volkswagen Agent...

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore (068811)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6338 7288 Fax : 6880 4838

DEAR SIR / MADAM :



Authashw
1-B1
Resony B4paim
Ex ML

OWN DAMAGE CLAIM

Fax: 62564315

ACCIDENT REPAIR ON: SBE3300P

MODEL : VOLKSWAGEN PASSAT 1.8 TSI

POLICY NO : VPA/P156581

CHASSIS NO : WVVZZZ3CZEE049675

YEAR OF MANUFACTURE : 2013

DATE / TIME OF ACCIDENT: 12/03/2018 Time: 1650Hrs at DOVER ROAD.

THIRD PARTY VEHICLE NO: **

Date: 17/03/2018

Page : 1 of 3

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Bonnet	1	595.00	Dented	595.00 X
2 Bonnet damper	1	48.00	Bented	48.00 ?
3 Bonnet hinge LH	1	46.00	Bented	46.00 X
4 Bonnet hinge RH	1	46.00	Bented	46.00 X
5 Bonnet lock assy	1	90.00	Bented	90.00 ✓
6 Bonnet stopper LH	1	3.00	Necessary	3.00 X
7 Bonnet stopper RH	1	3.00	Necessary	3.00 X
8 Front bumper	1	540.00	Broken	540.00 ✓
9 Front bumper side retainer LH	1	14.00	Necessary	14.00 ✓
10 Front bumper side retainer RH	1	14.00	Necessary	14.00 ✓
11 Front bumper centre bracket	1	60.00	Broken	60.00 ?
12 Front bumper clips	10	2.00	Necessary	20.00 ✓
13 Front bumper side bracket LH	1	15.00	Bented	15.00 ?
14 Front bumper side bracket RH	1	15.00	Bented	15.00 ?
15 Front bumper lower grille with lining chrome	1	150.00	Cracked	150.00 ?
16 Front bumper number plate garnish	1	55.00	Kinked	55.00 X
17 Front bumper sensor	8 /	85.00	Broken	510.00 ✓
18 Front bumper sensor ring	6	2.00	Necessary	12.00 ?
19 Front bumper sensor retainer	1	45.00	Necessary	45.00 ?
20 Front bumper sensor wiring harness	1	150.00	Cut	150.00 ?
21 Front bumper lower spoiler	1	90.00	Torn	90.00 ✓
22 Front bumper reinforcement	1	290.00	Dented	290.00 ?
23 Front bumper sponge LH	1	65.00	Broken	65.00 ?
24 Front bumper sponge RH	1	65.00	Broken	65.00 ?
25 Front bumper nozzle LH	1	80.00	Broken	80.00 ✓
26 Front bumper nozzle RH	1	80.00	Broken	80.00 X
27 Front bumper nozzle cover LH	1	20.00	Broken	20.00 ✓
28 Front bumper nozzle cover RH	1	20.00	Broken	20.00 X
29 Front bumper nozzle hose	1	115.00	Cut	115.00 ?
30 Front grille with moulding chrome	1	240.00	Broken	240.00 ✓
31 Front grille emblem	1	38.00	Necessary	38.00 ?
32 Headlamp LH	1	1,050.00	Torn	1,050.00 ✓
33 Headlamp RH	1	1,050.00	Torn	1,050.00 ?

34	Headlamp ecu LH	1	420.00	Necessary	420.00	?
35	Headlamp ecu RH	1	420.00	Necessary	Sm 420.00	X
36	Fog lamp LH	1	145.00	Cracked	145.00	?
37	Fog lamp RH	1	145.00	Cracked	Sm 145.00	X
38	Fog lamp cover with lining chrome LH	1	72.00	Cut	72.00	?
39	Fog lamp cover with lining chrome RH	1	72.00	Cut	Sm 72.00	X
40	Support panel	1	660.00	Cracked	CRA 660.00	✓
41	Front fender LH	1	290.00	Dented	R 290.00	✓
42	Front fender RH	1	290.00	Dented	R 290.00	X
43	Front fender shield LH	1	80.00	Torn	CRA 80.00	✓
44	Front fender shield RH	1	80.00	Torn	Sm 80.00	X
45	Front fender shield clips	20 / 0	2.00	Necessary	Sm 40.00	✓
46	Front fender inner wheelhouse LH	R 1		Dented		
47	Front fender inner reinforcement LH	R 1		Dented		
48	Front fender side plate LH	R 1		Dented		
49	Front fender side bracket LH	R 1		Dented		
50	Front absorber LH	1	150.00	Bented	150.00	?
51	Front absorber mounting LH	1	50.00	Necessary	50.00	?
52	Front absorber stopper LH	1	20.00	Necessary	20.00	?
53	Front lower arm LH	1	225.00	Bented	225.00	?
54	Front knuckle arm LH	1	290.00	Bented	290.00	?
55	Front knuckle arm bearing LH	1	195.00	Necessary	195.00	?
56	Front tie rod LH	1	45.00	Bented	45.00	?
57	Front tie rod end LH	1	55.00	Bented	55.00	?
58	Front stabiliser link LH	1	40.00	Bented	Sm 40.00	X
59	Front wheel rim LH	1	570.00	Bented	Sm 570.00	X
60	Air intake box assy	1	230.00	Cracked	230.00	?
61	Air intake duct	1	12.00	Torn	12.00	?
62	Horn high pitch	1	70.00	Broken	Sm 70.00	X
63	Horn lower pitch	1	70.00	Broken	Sm 70.00	X
64	Aircon condenser	1	520.00	Dented	520.00	?
65	Aircon condenser fan motor assy	1	220.00	Malfunction	220.00	?
66	Aircon condenser air guard LH	1	18.00	Cut	18.00	?
67	Aircon condenser air guard RH	1	18.00	Cut	Sm 18.00	X
68	Radiator	1	240.00	Dented	240.00	?
69	Radiator fan motor assy	1	290.00	Malfunction	290.00	?
70	Radiator fan cowling	1	85.00	Cracked	85.00	?
Sub-Total:					11,761.00	

Total Parts : 11,761.00

Special Nett Items

1	Anti-rust coating	3	80.00	N2 240.00	X
2	Front number plate with casing	1	35.00	Sm 35.00	✓
3	Radiator coolant	1	70.00	Me 70.00	20sm
4	Tyre front LH	1	250.00	Sm 250.00	X
					595.00

Total Parts: 12,356.00

Labour Charges For LH Side Portion

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	1,600.00	6001
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,200.00	8001
3	Provide skill labour to disconnect and check electrical wiring	60.00	201
4	Provide skill labour to remove and replace bumper sensors	50.00	✓
5	Provide skill labour to remove and replace aircon condenser, pipes and radiator, vacuum aircon system and refill gas	150.00	1001

6	Provide skill labour to check and re-adjust all wheel alignment	70.00	601
7	Provide skill labour to remove and replace/refit front LH undercarriage	180.00	?
8	Reset headlamp management system with diagnostic code data and memory	250.00	?
9	Remove and install engine assembly with transmission to facilitate repair	450.00	?
10	Remove and refit engine main harness from engine compartment interior	180.00	?
11	Provide skill labour to remove and replace/balancing front wheel rim LH and tyre	80.00	X
12	Provide skill labour to mount vehicle onto chassis alignment bench	300.00	?

Total Labour:

4,570.00

Total Parts & Labour:

16,926.00

GST 7%

1,184.82

Grand Total:

18,110.82

Estimate Repair Duration

21 days

ACCIDENT VEHICLE OF : SBE3300P

Page : 3 of 3

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kenneth
Company : CLC
Date : 2013/1/8
Time : 11.05am
Contact No : 96916663
Email : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore (068811)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6338 7288 Fax : 6880 4838

DEAR SIR / MADAM :

OWN DAMAGE CLAIM

ACCIDENT REPAIR ON: SBE3300P

MODEL : VOLKSWAGEN PASSAT 1.8 TSI

POLICY NO : VPA/P156581

CHASSIS NO : WVVZZZ3CZEE049675

YEAR OF MANUFACTURE : 2013

DATE / TIME OF ACCIDENT: 12/03/2018 Time: 1650Hrs at DOVER ROAD.

THIRD PARTY VEHICLE NO: **

Date: 17/03/2018

Page : 1 of 3

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
S/N		S\$		S\$
1 Bonnet	1	595.00	Dented	595.00 X
2 Bonnet damper	1	48.00	Bented	48.00 ?
3 Bonnet hinge LH	1	46.00	Bented	46.00 X
4 Bonnet hinge RH	1	46.00	Bented	46.00 X
5 Bonnet lock assy	1	90.00	Bented	90.00 ✓
6 Bonnet stopper LH	1	3.00	Necessary	3.00 X
7 Bonnet stopper RH	1	3.00	Necessary	3.00 X
8 Front bumper	1	540.00	Broken	540.00 ✓
9 Front bumper side retainer LH	1	14.00	Necessary	14.00 ✓
10 Front bumper side retainer RH	1	14.00	Necessary	14.00 ✓
11 Front bumper centre bracket	1	60.00	Broken	60.00 ?
12 Front bumper clips	10	2.00	Necessary	20.00 ✓
13 Front bumper side bracket LH	1	15.00	Bented	15.00 ?
14 Front bumper side bracket RH	1	15.00	Bented	15.00 ?
15 Front bumper lower grille with lining chrome	1	150.00	Cracked	150.00 ?
16 Front bumper number plate garnish	1	55.00	Kinked	55.00 X
17 Front bumper sensor	8 /	85.00	Broken	510.00 ✓
18 Front bumper sensor ring	6	2.00	Necessary	12.00 ?
19 Front bumper sensor retainer	1	45.00	Necessary	45.00 ?
20 Front bumper sensor wiring harness	1	150.00	Cut	150.00 ?
21 Front bumper lower spoiler	1	90.00	Torn	90.00 ✓
22 Front bumper reinforcement	1	290.00	Dented	290.00 ?
23 Front bumper sponge LH	1	65.00	Broken	65.00 ?
24 Front bumper sponge RH	1	65.00	Broken	65.00 ?
25 Front bumper nozzle LH	1	80.00	Broken	80.00 ✓
26 Front bumper nozzle RH	1	80.00	Broken	80.00 X
27 Front bumper nozzle cover LH	1	20.00	Broken	20.00 ✓
28 Front bumper nozzle cover RH	1	20.00	Broken	20.00 X
29 Front bumper nozzle hose	1	115.00	Cut	115.00 ?
30 Front grille with moulding chrome	1	240.00	Broken	240.00 ✓
31 Front grille emblem	1	38.00	Necessary	38.00 ?
32 Headlamp LH	1	1,050.00	Torn	1,050.00 ✓
33 Headlamp RH	1	1,050.00	Torn	1,050.00 ?

34	Headlamp ecu LH	1	420.00	Necessary	420.00	7X
35	Headlamp ecu RH	1	420.00	Necessary	420.00	XX
36	Fog lamp LH	1	145.00	Cracked	145.00	✓
37	Fog lamp RH	1	145.00	Cracked	145.00	X
38	Fog lamp cover with lining chrome LH	1	72.00	Cut	72.00	7X
39	Fog lamp cover with lining chrome RH	1	72.00	Cut	72.00	X
40	Support panel	1	660.00	Cracked	660.00	✓
41	Front fender LH	1	290.00	Dented	290.00	✓
42	Front fender RH	1	290.00	Dented	290.00	X
43	Front fender shield LH	1	80.00	Torn	80.00	✓
44	Front fender shield RH	1	80.00	Torn	80.00	X
45	Front fender shield clips	20/0	2.00	Necessary	40.00	✓
46	Front fender inner wheelhouse LH	1		Dented		
47	Front fender inner reinforcement LH	1		Dented		
48	Front fender side plate LH	1		Dented		
49	Front fender side bracket LH	1		Dented		
50	Front absorber LH	1	150.00	Bented	150.00	7
51	Front absorber mounting LH	1	50.00	Necessary	50.00	7
52	Front absorber stopper LH	1	20.00	Necessary	20.00	7
53	Front lower arm LH	1	225.00	Bented	225.00	7
54	Front knuckle arm LH	1	290.00	Bented	290.00	7
55	Front knuckle arm bearing LH	1	195.00	Necessary	195.00	7
56	Front tie rod LH	1	45.00	Bented	45.00	7
57	Front tie rod end LH	1	55.00	Bented	55.00	7
58	Front stabiliser link LH	1	40.00	Bented	40.00	X
59	Front wheel rim LH	1	570.00	Bented	570.00	X
60	Air intake box assy	1	230.00	Cracked	230.00	7
61	Air intake duct	1	12.00	Torn	12.00	7X
62	Horn high pitch	1	70.00	Broken	70.00	X
63	Horn lower pitch	1	70.00	Broken	70.00	X
64	Aircon condenser	1	520.00	Dented	520.00	7Y
65	Aircon condenser fan motor assy	1	220.00	Malfunction	220.00	7Y
66	Aircon condenser air guard LH	1	18.00	Cut	18.00	7Y
67	Aircon condenser air guard RH	1	18.00	Cut	18.00	X
68	Radiator	1	240.00	Dented	240.00	7
69	Radiator fan motor assy	1	290.00	Malfunction	290.00	7
70	Radiator fan cowl	1	85.00	Cracked	85.00	7
Sub-Total:					11,761.00	

Total Parts : 11,761.00

Special Nett Items

1	Anti-rust coating	3	80.00	2	240.00	X
2	Front number plate with casing	1	35.00	mis	35.00	✓
3	Radiator coolant	1	70.00	ne	70.00	201n
4	Tyre front LH	1	250.00	Sh	250.00	X
					595.00	

Total Parts: 12,356.00

Labour Charges For LH Side Portion

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	1,600.00	6001
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,200.00	8001
3	Provide skill labour to disconnect and check electrical wiring	60.00	201
4	Provide skill labour to remove and replace bumper sensors	50.00	✓
5	Provide skill labour to remove and replace aircon condenser, pipes and radiator, vacuum aircon system and refill gas	150.00	1001

6	Provide skill labour to check and re-adjust all wheel alignment	70.00	60
7	Provide skill labour to remove and replace/refit front LH undercarriage	180.00	?
8	Reset headlamp management system with diagnostic code data and memory	250.00	?
9	Remove and install engine assembly with transmission to facilitate repair	450.00	?
10	Remove and refix engine main harness from engine compartment interior	180.00	?
11	Provide skill labour to remove and replace/balancing front wheel rim LH and tyre	80.00	X
12	Provide skill labour to mount vehicle onto chassis alignment bench	300.00	?

Total Labour:

4,570.00

Total Parts & Labour:

16,926.00

GST 7%

1,184.82

Grand Total:

18,110.82

Estimate Repair Duration

21 days

ACCIDENT VEHICLE OF: SBE3300P

Page : 3 of 3

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kennerly
Company : CKIC
Date : 20/3/18
Time : 11.05am
Contact No : 9691663
Email : _____

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore (068811)
ATTN: MOTOR CLAIM DEPARTMENT
Tel: 6338 7288 Fax: 6880 4838
DEAR SIR / MADAM:



Authan
1-B1
Resony B4 pain
Ex ML

OWN DAMAGE CLAIM

Fax: 62564315

ACCIDENT REPAIR ON: SBE3300P
MODEL: VOLKSWAGEN PASSAT 1.8 TSI
POLICY NO: VPA/P156581
CHASSIS NO: WVWZZZ3CZEE049675
YEAR OF MANUFACTURE: 2013
DATE / TIME OF ACCIDENT: 12/03/2018 Time: 1650Hrs at DOVER ROAD.
THIRD PARTY VEHICLE NO: **

Date: 17/03/2018
Page: 1 of 3

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount	Malfunction
S/N			S\$		S\$	
1	Bonnet	1	595.00	Dented	595.00	X
2	Bonnet damper	1	48.00	Bented	48.00	X
3	Bonnet hinge LH	1	46.00	Bented	46.00	X
4	Bonnet hinge RH	1	46.00	Bented	46.00	X
5	Bonnet lock assy	1	90.00	Bented	90.00	X
6	Bonnet stopper LH	1	3.00	Necessary	3.00	X
7	Bonnet stopper RH	1	3.00	Necessary	3.00	X
8	Front bumper	1	540.00	Broken	540.00	X
9	Front bumper side retainer LH	1	14.00	Necessary	14.00	X
10	Front bumper side retainer RH	1	14.00	Necessary	14.00	X
11	Front bumper centre bracket	1	60.00	Broken	60.00	X
12	Front bumper clips	10	2.00	Necessary	20.00	X
13	Front bumper side bracket LH	1	15.00	Bented	15.00	X
14	Front bumper side bracket RH	1	15.00	Bented	15.00	X
15	Front bumper lower grille with lining chrome	1	150.00	Cracked	150.00	X
16	Front bumper number plate garnish	1	55.00	Kinked	55.00	X
17	Front bumper sensor	8	85.00	Broken	510.00	X
18	Front bumper sensor ring	6	2.00	Necessary	12.00	X
19	Front bumper sensor retainer	1	45.00	Necessary	45.00	X
20	Front bumper sensor wiring harness	1	150.00	Cut	150.00	X
21	Front bumper lower spoiler	1	90.00	Torn	90.00	X
22	Front bumper reinforcement	1	290.00	Dented	290.00	X
23	Front bumper sponge LH	1	65.00	Broken	65.00	X
24	Front bumper sponge RH	1	65.00	Broken	65.00	X
25	Front bumper nozzle LH	1	80.00	Broken	80.00	X
26	Front bumper nozzle RH	1	80.00	Broken	80.00	X
27	Front bumper nozzle cover LH	1	20.00	Broken	20.00	X
28	Front bumper nozzle cover RH	1	20.00	Broken	20.00	X
29	Front bumper nozzle hose	1	115.00	Cut	115.00	X
30	Front grille with moulding chrome	1	240.00	Broken	240.00	X
31	Front grille emblem	1	38.00	Necessary	38.00	X
32	Headlamp LH	1	1,050.00	Torn	1,050.00	X
33	Headlamp RH	1	1,050.00	Torn	1,050.00	X

34	Headlamp ecu LH	1	420.00	Necessary	Sm	420.00	X
35	Headlamp ecu RH	1	420.00	Necessary	Sm	420.00	X
36	Fog lamp LH	1	145.00	Cracked	cm	145.00	2
37	Fog lamp RH	1	145.00	Cracked	Sm	145.00	X
38	Fog lamp cover with lining chrome LH	1	72.00	Cut	Sm	72.00	2
39	Fog lamp cover with lining chrome RH	1	72.00	Cut	Sm	72.00	X
40	Support panel	1	660.00	Cracked	cm	660.00	✓
41	Front fender LH	1	290.00	Dented	R	290.00	✓
42	Front fender RH	1	290.00	Dented	R	290.00	X
43	Front fender shield LH	1	80.00	Torn	\$70 cm	80.00	✓
44	Front fender shield RH	1	80.00	Torn	Sm	80.00	X
45	Front fender shield clips	20/0	2.00	Necessary	na	40.00	✓ 20
46	Front fender inner wheelhouse LH	R	1	Dented		\$20	
47	Front fender inner reinforcement LH	R	1	Dented			
48	Front fender side plate LH	R	1	Dented			
49	Front fender side bracket LH	R	1	Dented			
50	Front absorber LH	1	150.00	Bented		150.00	✓
51	Front absorber mounting LH	1	50.00	Necessary		50.00	✓
52	Front absorber stopper LH	1	20.00	Necessary		20.00	✓
53	Front lower arm LH	1	225.00	Bented		225.00	✓
54	Front knuckle arm LH	1	290.00	Bented		290.00	✓
55	Front knuckle arm bearing LH	1	195.00	Necessary		195.00	✓
56	Front tie rod LH	1	45.00	Bented		45.00	✓
57	Front tie rod end LH	1	55.00	Bented		55.00	✓
58	Front stabiliser link LH	1	40.00	Bented	Sm	40.00	X
59	Front wheel rim LH	1	570.00	Bented	Sm	570.00	X
60	Air intake box assy	1	230.00	Cracked	cm	230.00	2
61	Air intake duct	1	12.00	Torn	Sm	12.00	X
62	Horn high pitch	1	70.00	Broken	Sm	70.00	X
63	Horn lower pitch	1	70.00	Broken	Sm	70.00	X
64	Aircon condenser	1	520.00	Dented	Sm	520.00	X
65	Aircon condenser fan motor assy	1	220.00	Malfunction	Sm	220.00	X
66	Aircon condenser air guard LH	1	18.00	Cut	Sm	18.00	X
67	Aircon condenser air guard RH	1	18.00	Cut	Sm	18.00	X
68	Radiator	1	240.00	Dented	Sm	240.00	X
69	Radiator fan motor assy	1	290.00	Malfunction	Sm	290.00	X
70	Radiator fan cowling	1	85.00	Cracked	Sm	85.00	X
						Sub-Total:	11,761.00

\$5392

Total Parts : 11,761.00

Special Nett Items

1	Anti-rust coating	3	80.00	~2	240.00	X
2	Front number plate with casing	1	35.00	na	35.00	✓
3	Radiator coolant	1	70.00	na	70.00	20sm
4	Tyre front LH	1	250.00	Sm	250.00	X
						595.00

\$55

Total Parts: 12,356.00

Labour Charges For LH Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	1,600.00	6001
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,200.00	8001
3	Provide skill labour to disconnect and check electrical wiring	60.00	201
4	Provide skill labour to remove and replace bumper sensors	50.00	✓
5	Provide skill labour to remove and replace aircon condenser, pipes and radiator, vacuum aircon system and refill gas	150.00	1001

6	Provide skill labour to check and re-adjust all wheel alignment	70.00	601
7	Provide skill labour to remove and replace/refit front LH undercarriage	nn 180.00	X
8	Reset headlamp management system with diagnostic code data and memory	nn 250.00	X
9	Remove and install engine assembly with transmission to facilitate repair	nn 450.00	X
10	Remove and refix engine main harness from engine compartment interior	nn 180.00	X
11	Provide skill labour to remove and replace/balancing front wheel rim LH and tyre	nn 80.00	X
12	Provide skill labour to mount vehicle onto chassis alignment bench	nn 300.00	X

Total Labour:

\$1630

4,570.00

Total Parts & Labour:

16,926.00

GST 7%

1,184.82

Grand Total:

18,110.82

Estimate Repair Duration

21 days

ACCIDENT VEHICLE OF : SBE3300P

Page : 3 of 3

8 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kennerh
Company : CKK
Date : 2013/11/8
Time : 11.05am
Contact No : 96910663
Email : _____

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore (068811)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6338 7288 Fax : 6880 4838

DEAR SIR / MADAM :

SUPPLEMENTARY

ACCIDENT REPAIR ON: SBE3300P

MODEL : VOLKSWAGEN PASSAT 1.8 TSI

POLICY NO : VPA/P156581

CHASSIS NO : WVWZZZ3CZEE049675

YEAR OF MANUFACTURE : 2013

DATE / TIME OF ACCIDENT: 12/03/2018 Time: 1650Hrs at DOVER ROAD.

THIRD PARTY VEHICLE NO: **

Date: 17/03/2018

Page : 1 of 3

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Bonnet Lock Catch	1	38.00	DM	38.00
2 Air Guide LH	1	16.00	CM	16.00
3 Air Guide RH	1	16.00	CM	16.00
4 Head Lamp Side Bracket LH	1	12.00	CM	12.00
5 Head Lamp Module LH	1	260.00	CM	260.00
Sub-Total:				342.00
Total Parts :				342.00

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: Anthony Lau

Survey attended by:

Name : Hennrich

Company : Uick

Date : 29/3/18

Time : _____

Contact No : _____

Email : _____

Part : \$5392.00 + \$342.00 (Supp) + \$23.00 (Supp) ②

S/N : \$55.00

Labour : \$1630.00

Total : \$7442.00 ✓ok



BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore (068811)
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 6338 7288 Fax : 6880 4838
DEAR SIR / MADAM :

SUPPLEMENTARY

ACCIDENT REPAIR ON: SBE3300P
MODEL : VOLKSWAGEN PASSAT 1.8 TSI
POLICY NO : VPA/P156581
CHASSIS NO : WVVZZZ3CZEE049675
YEAR OF MANUFACTURE : 2013
DATE / TIME OF ACCIDENT: 12/03/2018 Time: 1650Hrs at DOVER ROAD.
THIRD PARTY VEHICLE NO: **

Date: 17/03/2018
Page : 1 of 3

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
1		S\$		S\$
2	1	23.00		23.00 ✓
3	1			-
4	1			-
5	1			-
	1			-
Sub-Total:				23.00
Total Parts :				23.00

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: Anthony Lau

Survey attended by:

Name : _____
Company : _____
Date : _____
Time : _____
Contact No : _____
Email : _____



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: BH AUTO SERVICES PTE LTD

Address: BLK 1, SIN MING IND EST SEC C
#01-111/113/115/117, SINGAPORE 575636
A/C: 65598942 KAREN

SBE3300P P/O:2118
ORDER BY ANTHONY

Tax Invoice No: SRI2652723

Date: 03/04/2018

Area Code: 1 DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	AIR DUCT VW TOP S2(1)	1	23.00	23.00
Products received and checked to be in good condition		Sub-Total:		SGD 23.00
		G.S.T(7%):		1.61
		Total :		SGD 24.61

Customer's Signature / Company Stamp
Products sold are not returnable.

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

WEE - 03/04/18 10:21:40 AM

Authorised Signature



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: BH AUTO SERVICES PTE LTD

Address: BLK 1, SIN MING IND EST SEC C
#01-111/113/115/117, SINGAPORE 575636
A/C: 65598942 HUI PING/KAREN

SBE3300P VW PASSAT 13>

P/O: 209

ORDER BY: WEN ZHENG/ANTHONY

Tax Invoice No: SRI2651275

Date: 22/03/2018

Area Code: 1 DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	BONNET HINGE VW PAS 13> LH (3)	1	46.00	46.00
2	BONNET LOCK VW PASSAT 11- +SWITCH (5)	1	90.00	90.00
3	BUMPER VW PASSAT 14- FRT +PARK ASSIST (8)	1	540.00	540.00
4	BUMPER BKT VW PASSAT 11- F/LH SMALL (9)	1	14.00	14.00
5	BUMPER BKT VW PASSAT 11- F/RH SMALL (10)	1	14.00	14.00
6	CLIP BUMPER VW TOUAREG/PASSAT (12)	10	2.00	20.00
7	GRILLE VW PASSAT 11- FRT (30)	1	240.00	240.00
8	BUMPER SPOILER VW PASSAT 11- FRT (21)	1	90.00	90.00

Customer's Signature / Company Stamp

Products sold are not returnable.

Page: 1 of 2

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

WEE - 22/03/18 12:15:39 PM

Authorised Signature



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: BH AUTO SERVICES PTE LTD

Address: BLK 1, SIN MING IND EST SEC C
#01-111/113/115/117, SINGAPORE 575636
A/C: 65598942 HUI PING/KAREN

SBE3300P VW PASSAT 13>

P/O: 209

ORDER BY WEN ZHENG/ANTHONY

Tax Invoice No: SRI2651275

Date: 22/03/2018

Area Code: 1 DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
9	REVERSE SENSOR AUDI/vw frt/rear (17)	1	85.00	85.00
10	H/LAMP VW PAS LH (32)	1	1,050.00	1,050.00
11	PANEL/FULL VW PASSAT 11- C=E (40)	1	660.00	660.00
12	FENDER VW PASSAT 11- F/LH =a (41)	1	290.00	290.00
13	FENDER SHIELD VW PASSAT 11- F/LH R (43)	1	70.00	70.00
14	CLIP VW FENDER SHIELD (45)	10	2.00	20.00

Products received and checked to be in good condition

Sub-Total: SGD 3,229.00

G.S.T(7%): 226.03

Total: SGD 3,455.03

Customer's Signature / Company Stamp
Products sold are not returnable.

Page: 2 of 2

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

WEE - 22/03/18 12:15:40 PM

Authorised Signature



KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

KIAN HUA

Customer's Copy

Customer: BH AUTO SERVICES PTE LTD

Address: BLK 1, SIN MING IND EST SEC C

#01-111/113/115/117, SINGAPORE 575636

A/C: 65598942 HUI PING/KAREN

SBE3300P P/O: 2112

ORDER BY: ANTHONY

Tax Invoice No: SR12652031

Date: 27/03/2018

Area Code: 1 DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
-----	-------------	-----	------------	--------

1	BUMPER REINF VW PASSAT 11-FRT	1	290.00	290.00
---	-------------------------------	---	--------	--------

Products received and checked to be in good condition

Sub-Total: SGD 290.00

G.S.T(7%): 20.30

Total: SGD 310.30

Customer's Signature / Company Stamp

Products sold are not returnable.

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: BH AUTO SERVICES PTE LTD

Address: BLK 1, SIN MING IND EST SEC C
#01-111/113/115/117, SINGAPORE 575636
A/C: 65598942 HUI PING/KAREN

SBE3300P P/O: 2113

ORDER BY: ANTHONY

Tax Invoice No: SRI2652276

Date: 29/03/2018

Area Code: 1 DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	H/LAMP BKT VW PASCC 13> LH small (S4)	1	12.00	12.00
2	AIR GUIDE VW PAS RAD LH (S2)	1	16.00	16.00
3	AIR GUIDE VW PAS RAD RH (S3)	1	16.00	16.00
4	BONNET LOCK VW PASSAT 11- CATCH (S1)	1	38.00	38.00
5	AIR FILTER ASSY A3 1.8T/GF6 CDAA (60)	1	230.00	230.00

Products received and checked to be in good condition

Sub-Total: SGD 312.00
G.S.T(7%): 21.84
Total: SGD 333.84

Customer's Signature / Company Stamp
Products sold are not returnable.

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:
TIME:

WEE - 29/03/18 9:23:52 AM

Authorised Signature

WWW.KIANHUAMOTOR.COM



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: BH AUTO SERVICES PTE LTD

Address: BLK 1, SIN MING IND EST SEC C
#01-111/113/115/117, SINGAPORE 575636
A/C: 65598942 HUI PING/KAREN

SBE3300P P/O;2097

ORDER BY WEN ZHENG/ANTHONY

P/O No: SOR1009748

SOR1009748

WWW.KIANHUAMOTOR.COM

Tax Invoice No: SRI2652104

Date: 28/03/2018

Area Code: 1 DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	WIPER NOZZLE VW PASSAT 14> LH H/L ⁽²⁵⁾	1	80.00	80.00
2	WIPER NOZZLE COVER VW PASSAT 14> LH H/L ⁽²⁷⁾	1	20.00	20.00

Products received and checked to be in good condition

Sub-Total: SGD 100.00
G.S.T(7%): 7.00
Total : SGD 107.00

Customer's Signature / Company Stamp
Products sold are not returnable.

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:
TIME:

WEE - 28/03/2018 9:46:40 AM

Authorised Signature



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: BH AUTO SERVICES PTE LTD

Address: BLK 1, SIN MING IND EST SEC C
#01-111/113/115/117, SINGAPORE 575636
A/C: 65598942 HUI PING/KAREN

SBE3300P P/O: 2114
ORDER BY ANTHONY

Tax Invoice No: SRI2652407

Date: 29/03/2018

Area Code: 1 DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	H/LAMP MODULE VW GF7	1	260.00	260.00
Products received and checked to be in good condition				
Sub-Total:			SGD 260.00	
G.S.T(7%):			18.20	
Total :			SGD 278.20	

Customer's Signature / Company Stamp
Products sold are not returnable.

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:
TIME:

WEE - 29/03/2018 4:18:55 PM

Authorised Signature

WWW.KIANHUAMOTOR.COM



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: BH AUTO SERVICES PTE LTD

Address: BLK 1, SIN MING IND EST SEC C
#01-111/113/115/117, SINGAPORE 575636
A/C: 65598942 HUI PING/KAREN

SBE3300P P/O:2112
ORDER BY ANTHONY

P/O No: SCR1009779

Tax Invoice No: SRI2652437
Date: 31/03/2018
Area Code: 1 DELIVER
Credit Terms: 30Days
Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	FOG LAMP VW PASSAT 2014> LH (36)	1	145.00	145.00

Products received and checked to be in good condition

Sub-Total: SGD 145.00
G.S.T(7%): 10.15
Total : SGD 155.15

Customer's Signature / Company Stamp
Products sold are not returnable.

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

WEE - 31/03/18 9:22:48 AM

Authorised Signature



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: BH AUTO SERVICES PTE LTD

Address: BLK 1, SIN MING IND EST SEC C
#01-111/113/115/117, SINGAPORE 575636
A/C: 65598942 HUI PING/KAREN

SBE3300P P/O:2112
ORDER BY ANTHONY

Tax Invoice No: SRI2652032

Date: 27/03/2018

Area Code: 1 DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	DIESEL FILTER C/BE 1.6 HDI1901-67/78	1	40.00	40.00
2	ABSORBER BONNET VW PASSAT 11>	1	48.00	48.00
3	BUMPER BKT VW PASSAT 11- F/CTR	1	60.00	60.00
4	BUMPER BKT VW PASSAT 11- F/LH LOW	1	15.00	15.00
5	BUMPER GRILLE VW PASSAT 11- F/LH	1	72.00	72.00
6	GRILLE BADGE VW PASSAT 11- F/LH	1	38.00	38.00
7	H/LAMP VW PAS RH	1	1,050.00	1,050.00
8	WIPER HOSE VW H/LAMP (1M PAS RH)	1	115.00	115.00

Return (cancel)

Customer's Signature / Company Stamp
Products sold are not returnable.

Page: 1 of 2

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:
TIME:

WEE - 27/03/18 3:47:00 PM

Authorised Signature

WWW.KIANHUAMOTOR.COM