

ASS. REC. BY:

REF CS/CTI18005112/ Utd3n2 Special Instruction:

Surveyor
MerrinMercury
Adeline Chng

ASSIGNMENT (Office)

From (Person):

of

CTI

Date/Time:

14/3/18 @ 9:09am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 7561R

Insured:

SJF 4599M

at Workshop m/s:

Pegasus Engineering

Tel:

68581846

of

51 Deftune PO

Policy No:

DM HCSN1721451700

Claim No:

SNM18 D01397C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/3/18

CA / REV / REP. / REV 24 HRS

1up?

20/3/18

H.O.D. Endorsement:

Date/Time:

10:42am @ 14/3/18

Person Contacted:

Sharon

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLM 7561R - X
	SJF 4599M - X

REF: CTI

ASSIGNMENT

From:

Date: 20/3/18

Estimated Cost:

OD / P / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLM 7561R

at Workshop m/s

Pegasus Engineering

of

51 Defu Lane 10

Insured:

Policy No.

SLF 4599M

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

DAC Accident Report:

Consistent? : Yes or No

SA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

13.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 wks}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SLM 7561R

Yr Regn:

4 17

Type: M / Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota Vios

C.C. 1496

Colour

(Grey)

A/C: Insured / Std / NI / NA

Sp. Reading

47776

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MHFB29F3702009165

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/50 R16

R:

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

14/3/18

D.O.I.

20/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/3/18 confirmed final by 1860.50 with willan. (Red: 3647.67: 66%)

Date/Time: File Pass to?

23/3 Tyast

Date/Time: File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

220

Report Format :

TP

Lump Sum / (B) (\$

1860.50

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Mar 2018		19 Mar 2018 09:09 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	AUTOMOBILE PREMIER PTE LTD, Co. Reg. No.: -		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLM7561R	Date of Loss:	14/03/2018 16:00 - :59
Claim Type:	TP / SNM18D01397C02	Policy/Cover Note No.:	DMHCSN1721451700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJF4599M	Policy No. (Claimant):	A29069766MKF
		Excess:	S\$0.00
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/03/2018]		
Driver/Custodian (Insured):	LEE BOON CHEONG (43 / Male), NRIC: S7413094A, Tel: +6598587298		
Adj Asg. Remarks:	EST - \$5893.74 , ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18005112/Utd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 19-03-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 4599M	Veh. Inspected	SLM 7561R
Policy No.	DMHCSN1721451700	Coverage (\$)	0.00
Claim No.	SNM18D01397C02	Excess (\$)	0.00
Assign From	MERIMEN (ADELINE CHNG)	Assign Date	19/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/03/2018	Inspection Date
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/03/2018 20:45
Date Of Accident	14/03/2018 16:30
Exact Location Of Accident	868 TAMPINES STREET 83 520868 OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM7561R
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS 1.5E CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29069766MKF
Cover Note Number	

Driver

Name of Driver	MUHAMMAD SYAMIM BIN EMRAN
NRIC No	S9021515I
Date Of Birth	23/06/1990
Occupation	OUTDOOR
Date Of Driving Pass	05/04/2011
Driving Experience	6 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91068941
Fax Number	
Contact Number	
Email Address	MHDSYAERN@GMAIL.COM

Address	BLK 612 ELIAS ROAD #02-146 SINGAPORE 510612
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS PARKED STATIONARY AT BLK 868 TAMPINES VISTA OPN CAR PARK TO WAIT MY PASSENGER COME DOWN FROM HER BLK. AFTER FEW MINUTES, SUDDENLY I FELT A JERK FROM REAR SO I DECIDED TO CAME DOWN AND CHECK. VEHICLE B COLLIDED ONTO MY REAR RIGHT PORTION WHEN HE IS TURNING LEFT. WE TOOK PHOTOI ON THE SPOT AND EXCHANGES PARTICULARS. NO INJURIES INVOLVED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF4599M
Vehicle Make/Model/Colour	TOYOTA/WISH 1.8X/WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE BOON CHEONG
NRIC/Passport Number	S7413094A
Contact Number	98587298
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

ACCIDENT STATEMENT (2000 characters)

I WAS PARKED STATIONARY AT BLK 868 TAMPINES VISTA OPN CAR PARK TO WAIT MY PASSENGER COME DOWN FROM HER BLK. AFTER FEW MINUTES, SUDDENLY I FELT A JERK FROM REAR SO I DECIDED TO CAME DOWN AND CHECK. VEHICLE B COLLIDED ONTO MY REAR RIGHT PORTION WHEN HE IS TURNING LEFT. WE TOOK PHOTOI ON THE SPOT AND EXCHANGES PARTICULARS. NO INJURIES INVOLVED.

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?


No, Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
NG CHIN CHUN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

14 March 2018 at 8:25 PM

Date/Time:

14 March 2018 at 8:25 PM

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	7200G

Vehicle Details

Vehicle No.:	SLM7561R
Vehicle to be Exported:	Yes
Intended De-registration Date:	15 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E CVT
Body Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2NRX128838
Chassis No.:	MHFB29F3702009165
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,946.00
Original Registration Date:	10 Apr 2017
First Registration Date:	10 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$7,946.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Apr 2027
PARF Rebate Amount:	\$5,959.00

Intended COE Rebate Details

COE Expiry Date:	09 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,765.00
COE Rebate Amount:	\$41,412.00
Total Rebate Amount:	\$47,371.00

The information contained herein is correct as at 15 Mar 2018

OK

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

email on 15/03/2018
1615 hours
not Acknowledged
Take photo before repair.

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
539216
Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960
Attn :
Tel :
Fax :
20.03.2018 @ 1500h
LUK Marcus

Quotation No : QO18/03-1141	Quotation Date : 15/03/2018	Terms : 30 DAYS
Vehicle No : SLM7561R	Chassis No : MHFB29F3702009165	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: CHINA TAIPING, INSURED'S VEH NO: SJF4599M, DATE OF ACCIDENT: 14.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER DD	1	504.9000	504.90
2	REAR BUMPER SIDE RETAINER O/S 3rd	1	116.3000	116.30
3	REAR BUMPER SIDE HOLDER O/S 3rd	1	22.3000	22.30
4	REAR BUMPER REINFORCEMENT 11	1	323.3000	323.30
5	REAR BUMPER REFLECTOR O/S 1ve	1	130.5000	130.50
6	REAR BUMPER CLIPS 11	8	5.0000	40.00
7	REAR BUMPER END SPLASHIELD COVER O/S 11	1	89.8000	89.80
8	REAR END PANEL 11	1	694.7000	694.70
9	REAR FENDER O/S 11	1	969.7000	969.70
10	REAR FENDER AIR VENT O/S 11	1	44.7000	44.70
11	REAR LAMP O/S 11	1	375.8000	375.80
12	REAR LAMP PANEL O/S 11	1	238.9000	238.90
13	REAR LAMP CLIP HOLDER 11	4	15.0000	60.00
14	LESS 25% (ITEM 1 - 13)	1	-902.7300	-902.73
15	REAR BUMPER PARKING SENSOR 1 set 11	1	450.0000	450.00
16	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	900.0000	900.00
17	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	850.0000	850.00
18	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00
19	TO RUST-PROOFING OF THE AFFECTED AREAS	1	100.0000	100.00
20	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	180.0000	180.00
21	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	150.0000	150.00

P-814

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/03-1141	Quotation Date : 15/03/2018	Terms : 30 DAYS
Vehicle No : SLM7561R	Chassis No : MHFB29F3702009165	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: CHINA TAIPING, INSURED'S VEH NO: SJF4599M, DATE OF ACCIDENT: 14.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
22	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	50.0000	50.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub Total	5,508.17
GST(7.00%)	385.57
Total (SGD)	5,893.74

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18005112/UTD3N2

Date: 26/03/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1721451700
Claimant Vehicle No :	SLM7561R	Insured Vehicle No :	SJF4599M
Date of Loss:	14/03/2018	Nature of Claim:	TP
		Claim No:	SNM18D01397C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM7561R	Engine No:	2NRX128838
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MHFB29F3702009165
Reg. Date:	10/04/2017 (Man. Year: 2017)	Odometer:	47776 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50R16	Rear Tyre Size:	195/50R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,158.17	610.50	2,547.67	80.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,250.00	1,100.00	46.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,508.17	1,860.50	3,647.67	66.22
+ GST 7.00/7.00% (S\$)	385.57	130.24	255.33	66.22
Nett Amount (S\$)	5,893.74	1,990.74	3,903.00	66.22

INSPECTION

Date of Assignment:	19/03/2018	
Date Inspected:	20/03/2018 Inspected At:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10 Singapore 539216
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2018)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLM7561R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	504.90 FL	*504.90 FL
2	1		*REAR BUMPER SIDE RETAINER O/S	Bent	116.30 FL	*116.30 FL
3	1		*REAR BUMPER SIDE HOLDER O/S	Bent	22.30 FL	*22.30 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	323.30 FL	*- FL
5	1		*REAR BUMPER REFLECTOR O/S	Cracked	130.50 FL	*130.50 FL
6	8		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
7	1		*REAR BUMPER END SPLASHIELD COVER O/S	Not Necessary	89.80 FL	*- FL
8	1		*REAR END PANEL	Repair	694.70 FL	*- FL
9	1		*REAR FENDER O/S	Not Necessary	969.70 FL	*- FL
10	1		*REAR FENDER AIR VENT O/S	Not Necessary	44.70 FL	*- FL
11	1		*REAR LAMP O/S	Not Necessary	375.80 FL	*- FL
12	1		*REAR LAMP PANEL O/S	Not Necessary	238.90 FL	*- FL
13	4		*REAR LAMP CLIP HOLDER	Not Necessary	60.00 FL	*- FL
14	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,060.90	814.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	902.73	203.50
Total Parts (\$\$)	3,158.17	610.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	900.00	520.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	850.00	600.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	100.00	-
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	-
6	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TO ENABLE REPAIR	New	150.00	60.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	20.00
Gross Labour Cost (\$\$)			2,350.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >