

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0332/2018/CCS
Date : 16-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Loh Kwok Whye Melvin
Address : Blk 483 Segar Road
#13-336
Singapore 670483
Telephone : (HP) 98731016
Type of Claim : Own Damage Claims
Policy No. : 1700068233
Vehicle No : **SLT 2075 Z**
Model Code : Audi Q2 1.0 TFSI
Model / Year : Oct-17
Engine No : CHZ 551076
Chassis No : WAUZZZGASJA023024
Mileage :
Date In : 15-Mar-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Mar-18
Place of Accident : Along SLE towards CTE (near speed cam)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 2075 Z.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,750.00	1000 .
3	To respray front bumper and bonnet.	\$ 1,600.00	1100
TOTAL LABOUR CHARGES - FRONT		: \$ <u>3,710.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 2075 Z.

		<u>Damage Parts & Prices</u>	
S/N	Parts Description	S/NETT	REMARKS
1	FRONT BUMPER <i>Delid</i>	\$ 1,620.00	✓
2	FRONT BUMPER FIXING PARTS <i>me</i>	\$ 297.00	✗
3	FRONT BUMPER GRILLE - LOWER ?	\$ 172.00	?
4	FRONT BUMPER GRILLE - LH/RH <i>me</i>	2 \$ 290.00	✗.
5	FRONT BUMPER SPOILER ?	\$ 259.00	?
6	FRONT BUMPER ADAPTER - LH/RH <i>me</i>	2 \$ 72.00	✗
7	RADIATOR GRILLE <i>me</i>	\$ 1,215.00	✓
8	RADIATOR GRILLE STRIKER PLATE ?	\$ 108.00	?
9	FRONT BUMPER FOAM ?	\$ 66.00	?
10	FRONT BUMPER DISTANCE PIECE ?	\$ 11.00	?
11	FRONT REINFORCEMENT BEAM ?	\$ 600.00	?
12	FRONT BUMPER TOP COVER <i>Delid</i>	\$ 86.00	✓
13	SIGN 'CAUTION' STICKER <i>me</i>	\$ 12.00	✓
14	STICKER FOR AIR CONDITIONER <i>me</i>	\$ 7.00	✓
15	FRONT BUMPER GUIDE - LH/RH <i>me</i>	2 \$ 62.00	✗.
16	FRONT WHEEL ARCH TRIM - LH/RH <i>me</i>	2 \$ 558.00	✓
17	BONNET <i>Delid</i>	\$ 2,378.00	✗
18	BONNET IMPACT PROTECTION - LH/RH <i>2 me</i>	2 \$ 54.00	✗
19	BONNET IMPACT PROTECTION - CENTER <i>me</i>	\$ 26.00	✗
20	FRONT NO.PLATE <i>Best</i>	S/N \$ 25.00	✓
TOTAL SPARE PARTS CHARGES - FRONT		:	\$ 7,918.00
TOTAL LABOUR CHARGES - FRONT		:	\$ 3,710.00
GRAND TOTAL - FRONT		:	\$ 11,628.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 2075 Z.

S/N	Nature of Jobs			Estimated Charges	
1	To remove and transfer rear parking aid. Check function.	S/N	\$	280.00	✓
2	To renew rear windscreen.	S/N	\$	480.00	✓
3	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N	\$	480.00	✓
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$	1,400.00	?
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$	1,400.00	?
SUB-TOTAL LABOUR CHARGES - (REAR)			:	\$ 4,040.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 2075 Z.

S/N	Nature of Jobs	Estimated Charges
6	To dismantle rear bumper and rear lid. Cut out and weld rear end panelling, rhs rear fender, tail lamp panel inner reinforcement and connecting plates. Renew rear lid and rear bumper assy. Reinstall all parts removed.	\$ 8,400.00 2000 .
7	To respray rear bumper, rear lid, rhs rear fender, rhs sill panel, door entrance, drain panel, roof channel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 4,900.00 2200
8	To renew rear exhaust silencer. Align to position.	S/N \$ 480.00 X.
9	To carry out diagnostic.	S/N \$ 384.00 192.
SUB-TOTAL LABOUR CHARGES - (REAR)		: \$ <u>18,204.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLT 2075 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
✓ 1	REAR BUMPER <i>rehd</i>	\$ 1,016.00	✓
2	REAR BUMPER FIXING PARTS <i>neu</i>	\$ 66.00	✓
3	REAR BUMPER SPOILER <i>Detention</i>	\$ 247.00	✓
4	REAR PARKING AID SENSOR <i>neu</i>	\$ 422.00	✓
5	REAR PARKING AID SENSOR SEAL <i>neu</i>	\$ 15.00	✓
6	REAR BUMPER WIRING SET <i>neu</i>	\$ 458.00	✓
7	REAR REINFORCEMENT BEAM <i>Best</i>	\$ 480.00	✓
8	REAR BUMPER HOLDING STRAP - LH/RH ?	2 \$ 22.00	?
9	REAR BUMPER GUIDE - LH/RH ?	2 \$ 92.00	?
10	REAR WHEEL ARCH TRIM - LH/RH <i>neu</i>	2 \$ 298.00	✓
11	REAR BUMPER LIGHT REFLECTOR - RH <i>combined</i>	\$ 26.00	✓
12	REAR LID <i>rehd</i>	\$ 2,106.00	✓
13	REAR LID ATTACHMENT PARTS <i>neu</i>	\$ 103.00	✓
14	REAR LID SEAL <i>neu</i>	\$ 101.00	✓
15	REAR LICENCE PLATE TRIM <i>neu</i>	\$ 204.00	✓
16	REAR LID SPOILER FIXING PARTS <i>neu</i>	\$ 117.00	✓
17	REAR WINDSCREEN ?	\$ 679.00	?
18	GLASS PRIMER <i>neu</i>	\$ 19.00	✓
19	REAR LID AUDI LOGO <i>neu</i>	\$ 108.00	✓
20	REAR LID 'Q2' INSCRIPTION <i>neu</i>	\$ 83.00	✓
SUB-TOTAL SPARE PARTS - REAR		\$ 6,662.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLT 2075 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR LID 'TFSI' INSCRIPTION <i>new</i>	\$ 83.00	✓
22	REAR FENDER - RH ?	\$ 1,938.00	?
23	REAR FENDER CONNECTING PLATE - RH OUTER <i>Replaced</i>	\$ 63.00	✓
24	REAR CROSS PANEL - OUTER ?	\$ 216.00	?
25	REAR CROSS PANEL REINFORCEMENT - INNER ?	\$ 645.00	?
26	REAR FENDER CONNECTING PLATE - RH INNER ?	\$ 36.00	?
27	C-PILLAR TRIM - LH INNER <i>at</i>	\$ 529.00	✓
28	ROOF MOLDING CLIP SET ? <i>2 new</i>	\$ 33.00	+
29	1 SET FOAM FOR STRIPS	\$ 122.00	x
30	REAR FENDER VENT TRIM - RH <i>cracked</i>	\$ 29.00	✓
31	TAIL LIGHT - RH <i>cracked</i>	\$ 1,149.00	✓
32	TAIL LIGHT TRIM - RH <i>new</i>	\$ 26.00	x
33	REAR WHEEL HOUSING LINER - RH <i>ton</i>	\$ 181.00	-
34	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 49.00	✓
35	REAR SILENCER	\$ 633.00	+
36	REAR SILENCER DUAL CLIP <i>2 new</i>	\$ 53.00	x
37	REAR SILENCER RETAINER	2 \$ 72.00	+,
38	REAR NO. PLATE <i>new</i>	S/N \$ 25.00	+,
39	REAR WINDSCREEN SEALANT <i>new</i>	S/N \$ 200.00	✓
40	ACRYLIC SEALER ?	S/N \$ 180.00	?
SUB-TOTAL SPARE PARTS - REAR		\$ 6,262.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLT 2075 Z.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
41	CAVITY WAX ?	S/N \$ 140.00	?
42	STONE CHIP 1	S/N \$ 180.00	?
43	METAL FILLER POWDER ?	S/N \$ 280.00	?
44	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS - REAR		: \$ 14,024.00	
TOTAL LABOUR CHARGES - REAR		: \$ 18,204.00	
GRAND TOTAL - REAR		: \$ 32,228.00	
GRAND TOTAL - FRONT/REAR		: \$ 43,856.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian Ling
: 19/03/18.

: All Authorised, 10 days. 4 (Front)
: 6 (Rear).

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant