

INSURANCE OWNER: SAHAG | CC 3 / AIG18005152 | TKS3 | LKK: 17K53 | IDAC: 17K53

ASSIGNMENT
Surveyor: TAUFIKH | DOI: 20/03/18 | Date / Time: 19/03/18
Registered in Merimen: 20/03/18

Pre-assign / CCU / FTE



Insured Vehicle No: SKT 72065 | Claim No: 413526249355
Name of insured: NGOH CHAN HWA | Policy No: 2100418052
Insured Tel No: 9185 8749 | Make / Model: TOYOTA COROLLA ALTES - 1.6A
Excess Sec II :\$ 0 | D.O.A: 09/03/18 | Place of Accident: SLE TOWARDS CTG
Is driver the owner? (YES / NO) | Nature of Accident:
If NO, Driver Name / Age: | OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Driver Tel No: | (V/L: YES / NO) | Insured Liability: % | Final ? Yes / No

CU 24742 → SAC 27232 → SKT 72065 → SLE 7844Y → STY 25354



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP: vollwagen (mercedes)
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
21/03/18 (Sat):	Non-Reporting hr (1st):	
21/03/18 @ 2:08 pm	Non-Reporting hr (2nd):	
	Non-Reporting hr (Final):	
	Notification hr (if non-pickup):	
	Call OI	923032017
	After call hr to OI	
	Documentation Check List	Handler Typist
	Notification hr (if non-pickup)	
	After call hr to OI	
	Authorisation To Act	
	Release Voucher	
	Final Repair Bill	
	Car Rental Invoice	
	Towing Invoice	
	LTA / GIA	
	Medical Bill	
	PIR	
	Mandate/Reject Instruction	
	LOD	
	Payment Breakdown Form	
	Post-Repair Photos	
	Others	

RECEIVED 13 NOV 2018

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: MTV

Repair Cost: PP \$S 10,713.81 (7 days) Reduction: 48 % Email ☒ Call ☐

FINAL SETTLEMENT Date/Time: 10.11.18 Confirm with: MTV Email ☒ Call ☐

Final Liability: \$S 100 (Agreed / Assessed) BOLA S/N No.: 28

Repair Cost: 0/100 \$S 11,521.50

Loss of Rental (LOR): \$S - (days)

Loss of Use (LOU): \$S 60.00 (5 60 x 11 days)

Loss of Income (LOI): \$S - (5 x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search \$S 200

Medical: \$S -

Disbursement: \$S - (e.g. Tow/ Independent)

Legal Cost \$S -

Total: \$S 12,181.50 Global Sum \$S:

FINAL PAYMENT Date/Time: 10-11-18 Confirm with: MTV Email ☒ Call ☐

Payee 1: \$S 12,181.50 Name 1: TRUSMANN GROUP SINGAPORE PTE LTD

Payee 2: (Strike if N.A.) \$S Name 2:

Payee 3: (Strike if N.A.) \$S Name 3:

Tanpin

REP: ALH

18005152/711653

ASSIGNMENT

From: _____ Date: ~~18/03/2016~~

Estimated Cost: _____

OD: ☒ TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: ~~34207244~~

at Workshop No: ~~18005152~~

of: ~~18005152~~

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: ~~18005152~~

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Ball or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / FR Seen: _____ Consistent? : Yes or No

Est. Repairs: 1 days Res: Yes or No

Lump Sum: - % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

P/P: +10,773.31 (RSD: +10,000.34 48%)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transit Fee: _____

Report Format: _____

Lump Sum / 1.2 / 1.3

Add Fee: ☐ 1.4 ☐ 1.5 ☐ 1.6 ☐ 1.7

1.8 ☐ 1.9 ☐ 2.0 ☐ 2.1 ☐ 2.2

2.3 ☐ 2.4 ☐ 2.5 ☐ 2.6 ☐ 2.7

2.8 ☐ 2.9 ☐ 3.0 ☐ 3.1 ☐ 3.2

3.3 ☐ 3.4 ☐ 3.5 ☐ 3.6 ☐ 3.7

3.8 ☐ 3.9 ☐ 4.0 ☐ 4.1 ☐ 4.2

4.3 ☐ 4.4 ☐ 4.5 ☐ 4.6 ☐ 4.7

4.8 ☐ 4.9 ☐ 5.0 ☐ 5.1 ☐ 5.2

5.3 ☐ 5.4 ☐ 5.5 ☐ 5.6 ☐ 5.7

5.8 ☐ 5.9 ☐ 6.0 ☐ 6.1 ☐ 6.2

6.3 ☐ 6.4 ☐ 6.5 ☐ 6.6 ☐ 6.7

6.8 ☐ 6.9 ☐ 7.0 ☐ 7.1 ☐ 7.2

7.3 ☐ 7.4 ☐ 7.5 ☐ 7.6 ☐ 7.7

7.8 ☐ 7.9 ☐ 8.0 ☐ 8.1 ☐ 8.2

8.3 ☐ 8.4 ☐ 8.5 ☐ 8.6 ☐ 8.7

8.8 ☐ 8.9 ☐ 9.0 ☐ 9.1 ☐ 9.2

342078444 Page 2016 June

Type: ☒ M / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Tiguan CC 1390

Colour: white A/C Insured / Std / NI / NA

So Reading: 41220 T/Radio Insured / Std / NI / NA

Eng No: _____

C.No: WVG2225N29W094282

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Mod: Nil / ☒ Shim / STD A/Rim or

Tyre Size: F: 215 / 80 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R.Bal: 6 mm L.Bal: 6 mm

D.O.A: _____ D.OI: 20/3/181520

Survey held at: VW Tinas

Des. of Damages: ☒ Fr / ☒ R / Q / S / N / S / U / C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18005152/T1ks3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 20-03-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKT 7206S	Veh. Inspected	SLD 7844Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/03/2018	Inspection Date	20/03/2018
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 1 KAMPONG AMPAT OFF MACPHERSON ROAD SINGAPORE 368314		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1979I
Vehicle Details	
Vehicle No.:	SLD7844Y
Vehicle to be Exported:	No
Intended De-registration Date:	21 Mar 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TIGUAN 1.4 TSI AT BMT 5N22QY
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	CTH241212
Chassis No.:	WVGZZZ5NZGW094282
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$26,952.00
Original Registration Date:	28 Jun 2016
First Registration Date:	28 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$29,733.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2026
PARF Rebate Amount:	\$22,299.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,000.00
COE Rebate Amount:	\$46,293.00
Total Rebate Amount:	\$68,592.00

The information contained herein is correct as at 21 Mar 2018

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year Coe Renewal Toyota Vios 1.5A



\$2500 Downpayment Monthly
From \$580 Onwards. Lowest
3.68% P.A. @ GV Cars Financing
GV Credit Pte Ltd Shared

Fly Singapore
Phuket
One way direct
Net fare
All-in from: **\$4**

• Free VICOM evaluation
• Free grooming and 8 months maintenance
• In-house workshop ensures quality service
• Member of SVTA and hire purchase association
• 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

5 vehicles

volkswagen tiguan

Sort by Date Posted

20 results/page

Advanced Search

Search Selection

volkswagen tiguan

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
		Any	Any	2016	Any	Any	Any	Available



Volkswagen Tiguan 1.4A TSI BMT

1 Owner. Fully Agent's VGS Maintained. Under Agent's 3 Years / 100k Km Engine Warranty And 5 Years Gearbox Warranty-3 Year Free Servicing At Agent's VGS. Viewing By Appointment Only.

Posted: 16-Mar-2018 Tags: 2016 Volkswagen Tiguan, Volkswagen Tiguan, Volkswagen, Tiguan, Used Volkswagen



Volkswagen Tiguan 1.4A TSI BMT

1 Owner, Accident Free, Low Mileage Done, Maintained And Warranty By VGS/Agent, Elegant White In Colour, Please Call For Viewing And Enquiry.
Hin Lung Auto Pte Ltd

Posted: 11-Mar-2018 Tags: 2016 Volkswagen Tiguan, Volkswagen Tiguan, Volkswagen, Tiguan, Used Volkswagen



Volkswagen Tiguan 1.4A TSI BMT R-Line

R-Line Model, Panoramic Roof, No Gimmicks! Full Equipment With Blue Motion Technologies, Keyless Start/Entry, Built In Bluetooth/GPS/DVD, Side Step, Auto HID Lights With LEDs DRL, Serviced/Maintained ...

Posted: 10-Mar-2018 Tags: 2016 Volkswagen Tiguan, Volkswagen Tiguan, Volkswagen, Tiguan, Used Volkswagen



Volkswagen Tiguan 1.4A TSI BMT

Singapore's Only Certified Volkswagen Pre Owned Centre. The Only Place To Find Volkswagen Management Units! 115 Points Check By Volkswagen, Certified Vehicle History And Mileage, No Chassis/Structural...

Das WeltAuto

Posted: 02-Mar-2018 Tags: 2016 Volkswagen Tiguan, Volkswagen Tiguan, Volkswagen, Tiguan, Used Volkswagen

Car Buying

Car Selling

Car Ownership

**Buying a pre-owned car, but
Unsure of its Condition?**
Get, STA Car Evaluation

Car Aftermarket

On The Move

Lifestyle



Volkswagen Tiguan 1.4A TSI BMT

1 Owner, Accident Free, Low Mileage Done, Maintained And Warranty By VGS/Agent, Elegant White In Colour, Please Call For Viewing And Enquiry.

Posted: 12-Feb-2018 Tags: 2016 Volkswagen Tiguan, Volkswagen Tiguan, Volkswagen, Tiguan, Used Volkswagen

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

20 results/page

For old advertisements, view Expired ads

Compare

...there is the missing one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or V, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used volkswagen

Service Order Confirmation

Tanpin 97495749
20/3/18 @ 1720
Resin before paint
Gdys
sur @ 1h hands-on

SERVICE ORDER NO: 18IP0743
CUSTOMER NO.: CV034264
CUSTOMER NAME: SUMITRO JOYO TASLIM
TELEPHONE NO.:
ADDRESS: 50 LORONG 40 GEYLANG #08-38
Singapore

VEH No.: SLD7844Y

Order Date: 03/19/18
Reg Date: 06/28/16 KM: 41,218
VIN NO.: WVZZZ5NZGW094282 ENGINE NO:
MODEL: Tiguan GP 1.4 TSI 118 DSG6 VNA MODEL NO.: 5N22QY

SA: Tang Shu Shi

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P MECH ELECT WIRING & MECH COMPONENT- CHASSIS NETT	1	TU	1.25		1.25 / 380
2	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	1.25		1.25 / 480
3	B&P MACP LABOUR LABOUR (REAR)	5	UNIT	840		4,200 / 1260 / 1,680
4	B&P MACP PAINT SPRAY PAINT (REAR)	5	UNIT	800		4,000 / 1600
5	B&P MACP LABOUR LABOUR (FRT)	3	UNIT	840		2,520 / 840
6	B&P MACP PAINT SPRAY PAINT (REAR) For	2	UNIT	800		1,600 / 1200
7	B&P NUMBER PLATE B&P NUMBER PLATE - NETT (FRT)	2	ST	80		160 / 44
8	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Item						
9	5N0807421G GRU REAR BUMPER (TOP)	1	PCS	1,138.50		1,138.50 /
10	5N0807521AFGRU REAR BUMPER (CENTRE)	1	PCS	398.19		398.19 /
11	5N0807568 2Z0 REAR BUMPER SPOILER (LOWER)	1	PCS	441.47		441.47 /
12	5N0807305 REINFORCEMENT	1	PCS	480.96		480.96 X N/A
13	5N0807393E LHR BUMPER BRACKET	1	PCS	23.80		23.80 X N/A
14	5N0807394D RHR BUMPER BRACKET	1	PCS	23.80		23.80 /
15	1K0807300 RIVET	4	PCS	2.24		8.96 /
16	N 10821301 NUT	6	PCS	1.85		11.10 /
17	5N0807441A GRU TOW COVER	1	PCS	48.58		48.58 / 48.58
18	5N0945105 REFLECTOR REAR LH	1	PCS	67.37		67.37 /
19	5N0945106 REFLECTOR REAR RH	1	PCS	52.53		52.53 /
20	5N0941071 REVERSING LIGHT LH	1	PCS	75.95		75.95 /
21	5N0941072 REVERSING LIGHT RH	1	PCS	75.95		75.95 /
22	5N0853817C 9B9 LHR BUMPER PROTECTOR	1	PCS	356.42		356.42 X N/A
23	5N0853818C 9B9 RHR BUMPER PROTECTOR	1	PCS	356.42		356.42 X N/A
24	5N0853818E 9B9 RHR FENDER PROTECTOR	1	PCS	613.41		613.41 X N/A
25	5N0853817E 9B9 LHR FENDER PROTECTOR	1	PCS	613.41		613.41 X N/A
26	3C0653566 GROMMET	12	PCS	2.01		24.12 /
27	5N0810672 RHR FENDER LINER	1	PCS	182.00		182.00 /
28	150919275C GRU REAR SENSOR	2	PCS	175.10		350.20 /

Service Order Confirmation

SERVICE ORDER NO: 18IP0743

CUSTOMER NO.: CV034264

CUSTOMER NAME: SUMITRO JOYO TASLIM

TELEPHONE NO.:

ADDRESS: 59 LORONG 40 GEYLANG #08-39

Singapore

VEH No.: SLD7844Y

Order Date: 03/19/18

Reg Date: 06/28/16

KM: 41,218

VIN NO.: VVGZZZ5NZGW094282

ENGINE NO:

SA: Tang Shu Shi

MODEL: TiguanGP 1.4 TSI 118 DSG6 VNA MODEL NO.: 5N22QY

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	1T0919133C 9B9	3	PCS	0.65		1.95 ✓
30	5N0919503D	1	PCS	14.78		14.78 ✓
31	5N0919503E	1	PCS	14.78		14.78 ✓ 14.78
32	5N0919491D	1	PCS	14.78		14.78 ✓
33	5N0919491E	1	PCS	14.78		14.78 ✓
34	5N0919398	1	PCS	13.36		13.36 ✓
35	5N0919504B	1	PCS	25.66		25.66 ✓
36	5N0653687B 739	1	PCS	90.62		90.62 ✓
37	1Q0653675Q GQF	1	PCS	57.84		57.84 ✓
38	5N0653675M CVB	1	PCS	69.58		69.58 ✓
39	5N0653630 FXC	1	PCS	79.95		79.95 ✓
40	5M0819486A	1	PCS	32.47		32.47 ✓
41	5N0807217EHGRU	1	PCS	1,245.38		1,245.38 ✓
42	5N0807287D 9B9	1	PCS	93.15		93.15 ✓
43	N 0385481	6	PCS	0.68		4.08 ✓
44	5N0807248D	1	PCS	45.26		45.26 ✓
45	5N0807183D	1	PCS	21.09		21.09 ✓
46	5N0807184D	1	PCS	21.09		21.09 ✓
47	5N0807109F	1	PCS	445.19		445.19 ✓
48	5N0807651B	1	PCS	153.12		153.12 ✓
49	5N0995494B	1	PCS	53.15		53.15 ✓
50	5N0919493H	1	PCS	13.36		13.36 ✓
51	5N0919494H	1	PCS	13.36		13.36 ✓
52	5N0919493G	1	PCS	13.36		13.36 ✓
53	5N0919494G	1	PCS	13.36		13.36 ✓
54	5N0653671B 82V	1	PCS	160.33		160.33 ✓
55	5N0121341B	1	PCS	47.15		47.15 ✓

Remarks: AIG DIRECT SETTLEMENT

DOA: 09/03/2018

TP VEHICLE: SKT72068

(A) VW SIGN (IMPROVE PART) 1 @ 108.49 ✓ (W)

(B) FRT BUMPER LOWER BRACKET 1 @ 83.07 ✓ (W)



Service Order Confirmation

SERVICE ORDER NO: 15IP0743
CUSTOMER NO.: CV034264
CUSTOMER NAME: SUMITRO JOYO TASLIM
TELEPHONE NO.:
ADDRESS: 80 LORONG 40 GEYLANG #08-39
Singapore

VEH No.: SLD7844Y

Order Date: 03/19/18
Reg Date: 06/25/16 KM: 41,218
VIN NO.: WVGZZZ5NZGW094282 ENGINE NO:
MODEL: TiguanGP 1.4 TSI 118 DSG6 VNA MODEL NO.: 5N22QY

SA: Tang Shu Shi

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

SURVEY BY:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TOTAL	20,773.71
GST AMOUNT	1,454.16
TOTAL AMOUNT	22,227.87



Authorized Signature

Certified Goods/Service received:

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 6 September 2018 12:13 PM
To: 'Syed-Yusoff, Saliha'
Subject: [MANDATE REQUEST] Your ref : 4135262483SG, ACCIDENT ON 09/03/2018 INVOLVING SKT 7206S (OI) & SLD 7844Y (TP)

Your ref : **4135262483SG**
Our ref : CC3/AIG18005152/T1ea3

Dear Sirs,

ACCIDENT ON 09/03/2018 INVOLVING SKT 7206S (OI) & SLD 7844Y (TP)

We refer to the above matter.

The said chain collision involved 5 vehicles whereby our insured was the 3rd vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) maybe affected.

We seek your approval to offer repairer "**VOLKSWAGEN CENTRE SINGAPORE**" at **\$ 12,189.51 (all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 24,069.41	\$ 11,527.51
2. Loss of Use (11days x \$60)	\$ 660.00	\$ 660.00 (11days x \$60)
4. LTA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 24,731.41	\$ 12,189.51

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Poyu Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SLD7844Y (4135262483SG)**
[SKT7206S]

TP

SUMITRO JOYO TASLIM

Mar 9 2018 6:00PM

[NGOH CHIN HWA]

Volkswagen Centre Singapore

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 05/10/2018 15:31 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12129.51) - SLD7844Y - Claim Handler: Syed-Yusoff, Saliha

Approved:12129.51:LOU to be offered up to 10days only.

Print Received Message

This mail is associated with :

***SLD7844Y (4135262483SG)**
[SKT7206S]

TP

SUMITRO JOYO TASLIM

Mar 9 2018 6:00PM

[NGOH CHIN HWA]

Volkswagen Centre Singapore

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 16/10/2018 13:41 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12189.51) - SLD7844Y - Claim Handler: Syed-Yusoff, Saliha

Approved:12189.51;please proceed with settlement as proposal.

PAYMENT ADVICE

Your ref: AIG Insurance Vehicle No. _____

Claimant's Vehicle No. SLO 78444 _____

Accident on 9/3/2016 _____ involving vehicle/s No. SICL 7206S _____

_____ along/at SLE Apt Exit 3 _____

Towards TPE/CTE _____

BREAKDOWN OF PAYMENT/S

1. Repair Cost S\$ 11,527.50 Payable to Volkswagen Group Singapore Pte Ltd _____

2. Loss-of-Use/
Car Rental S\$ 60 x 11 days = 660 Payable to _____

3. Medical and
Search Fees S\$ 2 Payable to Volkswagen Group Singapore Pte Ltd _____

Remarks : _____

Service Adviser Tang Shu Shi _____

Contact No./H/P. 69223502 _____



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG18005152/T1ks3

03 APRIL 2018

NGOH CHIN HWA
65 CEYLON ROAD
SINGAPORE 429750

Dear Sir/Madam,

ACCIDENT INVOLVING SKT 7206S / SLD 7844Y / OTHERS ON 09.03.2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,


Zaini
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: Zaini@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, Sumitro Joyo Taslim (the third party claimant")
of BK 677C Punggol Drive #15-764B) & 23677 (address), owner
of SLD78444 (vehicle no.) hereby authorize Volkswagen Group Singapore Pte Ltd ("the workshop")
to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for
my vehicle no SLD78444 that was damaged pursuant to the accident which occurred
on 9/3/16 (date) along SLE HT Exit 3 Towards TPE/CTE (location)
involving vehicle no/s 8ET 77065 ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 19 (day) of 03 (month) 20 16 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, Volkswagen Group Singapore Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for SS 11,521.50 (Repair Cost), SS 400.00 (Loss of Use/Rental), SS 2.00 (Disbursement) for vehicle no. SLD7844Y that was damaged pursuant to the accident which occurred on 1/3/16 (date) along SLE Apt exit 3 towards TPE/CTE (location) involving vehicle no/s SKT72065. This is pursuant to the inspection conducted on 30.03.16 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Sumitro Jody Taslim ("the third party claimant") of vehicle no. SLD7844Y make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLD 7844Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10 (day) of 11 (month) 2016 (year)



MMH

Signed by appointed surveyor



Signed by "the workshop" (with chop)

Volkswagen Centre Singapore



Service Tax Invoice No. SV18P14250

Biz Reg. No. S3103069E
GST No. M20098505-2

SERVICE ORDER NO: 18IP0743

SERVICE CUSTOMER NO.: F01089R

SERVICE CUSTOMER NAME: AIG ASIA PACIFIC INSURANCE P/L

TELEPHONE NO.:

ADDRESS: 78 Shenton Way
#07-18 AIG Building
Singapore

Post Code: 078120

VEH NO.: SLD7844Y

DATE: 28/03/18

Pickup:

VIN NO.: WVZZZ5NKG1W094282

KM: 41,320

GEARBOX CODE: QZM

Engine No.:

MODEL: TiguanGP 1.4 TSI 118 DSG VNA

SA: Tang Shu Shi

Next Appointment Date :

Next Appointment Mileage : 0

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT
AIG DIRECT SETTLEMENT					
DOA: 09/03/2018					
TP VEHICLE: SKT7206S					
SURVEY BY:TAUFIKH					
	Labor				
1	LABOUR (REAR)	2.00	UNIT	840.00	1,680.00
2	LABOUR (FRT)	1.00	UNIT	840.00	840.00
3	SPRAY PAINT (REAR)	2.00	UNIT	800.00	1,600.00
4	SPRAY PAINT (FRT)	1.00	UNIT	1,200.00	1,200.00
5	B&P NUMBER PLATE -NETT (FRT)	2.00	ST	80.00	160.00
6	Tow SVC- Quality Recovery Services	1.00	UNIT		
7	Tow SVC- Quality Recovery Services	1.00	UNIT		
8	PROGRAMMING & CALIBRATION- NETT	1.00	TU	480.00	480.00
9	ELECT WIRING & MECH COMPONENT CHECK NE	1.00	TU	280.00	280.00
	Item				
10	RIVET	4.00	PCS	2.24	8.96
11	REAR SENSOR	2.00	PCS	175.10	350.20
12	PARKING SENSOR O RING	3.00	PCS	0.65	1.95
13	GROMMET	12.00	PCS	2.01	24.12
14	VW SIGN (IMPROVE PART)	1.00	PCS	108.49	108.49

Volkswagen Centre Singapore

Service Tax Invoice No. SV18P14250



Biz Reg. No. S3103069E
GST No. M20098505-2

SERVICE ORDER NO: 18IP0743

SERVICE CUSTOMER NO.: F01089R

SERVICE CUSTOMER NAME: AIG ASIA PACIFIC INSURANCE P/L

TELEPHONE NO.:

ADDRESS: 78 Shenton Way

#07-16 AIG Building

Singapore

Post Code: 079120

VEH NO.:

SLD7844Y

DATE: 28/03/18

Pickup:

VIN NO.: WVGGZZ5N2GW054282

KM : 41,220

GEARBOX CODE: Q2M

Engine No.:

MODEL: TiguanGP 1.4 TSI 118 DSG VNA

SA: Tang Shu Shi

Next Appointment Date :

Next Appointment Mileage : 0

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT
15	FRT BUMPER LOWER SPOILER	1.00	PCS	855.07	855.07
16	BUMPER FOAM FRT	1.00	PCS	45.26	45.26
17	FRT NUMBER PLATE BRACKET	1.00	PCS	93.15	93.15
18	RHR BUMPER BRACKET	1.00	PCS	23.80	23.80
19	REAR BUMPER (TOP)	1.00	PCS	1,138.50	1,138.50
20	TOW COVER	1.00	PCS	48.59	48.59
21	REAR BUMPER (CENTRE)	1.00	PCS	398.19	398.19
22	REAR BUMPER SPOILER (LOWER)	1.00	PCS	441.47	441.46
23	RHR FENDER LINER	1.00	PCS	182.00	182.00
24	CENTRE LOWER GRILLE (FRT)	1.00	PCS	160.33	160.33
25	RHR BUMPER PROTECTOR	1.00	PCS	356.42	356.42
26	SENSOR BRACKET (OUTER)CENTRE	1.00	PCS	14.78	14.78
27	SENSOR BRACKET (OUTER)CENTRE	1.00	PCS	14.78	14.78
28	SENSOR BRACKET	1.00	PCS	13.36	13.36
29	SENSOR BRACKET	1.00	PCS	13.36	13.36
30	SENSOR BRACKET (INNER)CENTRE	1.00	PCS	14.78	14.78
31	SENSOR BRACKET (INNER)CENTRE	1.00	PCS	14.78	14.78
32	REVERSING LIGHT RH	1.00	PCS	75.95	75.95

Volkswagen Centre Singapore



Service Tax Invoice No. SV18P14250

Bus Reg. No. 53103069E
GST No. M20098505-2

SERVICE ORDER NO: 18IP0743

SERVICE CUSTOMER NO.: F01089R

SERVICE CUSTOMER NAME: AIG ASIA PACIFIC INSURANCE P/L

TELEPHONE NO.:

ADDRESS: 78 Shenton Way
#07-16 AIG Building

Singapore

Post Code: 079120

VEH NO.: SLD7844Y

DATE: 28/03/18

Pickup:

VIN NO.: WVGZZZ5NZGW094282

KM : 41,220

GEARBOX CODE: QZM

Engine No.:

MODEL: TiguanGP 1.4 TSI 118 DSG6 VNA

SA: Tang Shu Shi

Next Appointment Date :

Next Appointment Mileage : 0

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT
33	REFLECTOR REAR LH	1.00	PCS	87.37	87.37
34	REFLECTOR REAR RH	1.00	PCS	52.53	52.53
35	RIVET	6.00	PCS	0.68	4.08
36	NUT	6.00	PCS	1.85	11.10

Sub Total 10,773.37

GST (7%) AMOUNT 754.13

TOTAL AMOUNT 11,527.50

06 APR 2018

for Volkswagen Centre Singapore

Customer

Phone : Fax :



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-040885
Date of Request: 19/03/2018

Your Ref No: Online Purchase

Volkswagen Centre Singapore
247 Alexandra Road
Singapore 159934

Dear Sir/Madam,

Enquiry Date 19/03/2018
Enquiry By Tang Shu Shi
TP Vehicle No. SKT7206S
Accident Date 09/03/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKT7206S	AIG Asia Pacific Insurance Pte. Ltd.	22/06/2017-21/06/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-040885

Date of Request: 19/03/2018

Your Ref No: Online Purchase

Volkswagen Centre Singapore
247 Alexandra Road
Singapore 159934

Dear Sir/Madam,

Enquiry Date 19/03/2018

Enquiry By Tang Shu Shi

TP Vehicle No. SKT7206S

Accident Date 09/03/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Mar 2018 Edit Reg		20 Mar 2018 00:00 Edit Adj Rpt	S\$10,773.37 Edit Estimates	S\$10,773.37 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: NGOH CHIN HWA , ID: S6930134G									
Main Claimant: SUMITRO JOYO TASLIM , ID: S78119791									
Vehicle Reg. No.: SLD7844Y		Date of Loss: 09/03/2018 18:00 - :59 [20 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4135262483SG		Policy/Cover Note No.: 2100418032 (Comprehensive)							
Vehicle Reg. No. (Insured): SKT7206S		Policy No. (Claimant): A28788813AVW							
		Excess:							
Repairer: Volkswagen Group Singapore Pte Ltd (HQ) No: 17 Tuas Ave 9, 639197 Tuas - Tel: 65156560									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com									
Claimant's Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 29/03/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (16/10/2018): Alert - Adj Mandate Approved (S\$12189.51) - SLD7844Y - Claim Handler: Syed-Yusof... - AIG_SG_EXPRESS (05/10/2018): Alert - Adj Mandate Approved (S\$12129.51) - SLD7844Y - Claim Handler: Syed-Yusof...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLD7844Y (4135262483SG)
[SKT7206S]**

**TP
SUMITRO JOYO TASLIM
Mar 9 2018 6:00PM
[NGOH CHIN HWA]
Volkswagen Group Singapore Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		v	☒		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	22/03/18 09:03	Video - Accident From:OD - Reg. No: SKT7206S, Claimant: NGOH CHIN HWA													Load AVI					
2	22/03/18 09:03	Video - Accident From:OD - Reg. No: SKT7206S, Claimant: NGOH CHIN HWA													Load AVI					
Letters/Correspondences															1 per page		v	☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown													Edit					
Assessment Reports															1 per page		v	☒		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	21/03/18 12:14	Accident Statement From:OD - Reg. No: SKT7206S, Claimant: NGOH CHIN HWA													Load HTM					
Photos/Images															3 per page		v	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	06/09/18 12:11	Odometer Reading													Load JPG	☒				
2	06/09/18 12:11	Chassis Number													Load JPG	☒				
3	06/09/18 12:11	General View													Load JPG	☒				
4	06/09/18 12:11	General View													Load JPG	☒				
5	06/09/18 12:11	General View													Load JPG	☒				
6	06/09/18 12:11	General View													Load JPG	☒				
7	06/09/18 12:11	General View													Load JPG	☒				
8	06/09/18 12:11	General View													Load JPG	☒				
9	06/09/18 12:11	General View													Load JPG	☒				
10	06/09/18 12:11	General View													Load JPG	☒				
11	06/09/18 12:11	General View													Load JPG	☒				
12	06/09/18 12:11	General View													Load JPG	☒				
13	06/09/18 12:11	General View													Load JPG	☒				
14	06/09/18 12:11	General View													Load JPG	☒				
15	06/09/18 12:11	General View													Load JPG	☒				
16	06/09/18 12:11	General View													Load JPG	☒				
17	06/09/18 12:11	General View													Load JPG	☒				
18	06/09/18 12:11	General View													Load JPG	☒				
19	06/09/18 12:11	General View													Load JPG	☒				
20	06/09/18 12:11	General View													Load JPG	☒				
21	06/09/18 12:11	General View													Load JPG	☒				
22	06/09/18 12:11	General View													Load JPG	☒				
23	06/09/18 12:11	General View													Load JPG	☒				
24	06/09/18 12:11	General View													Load JPG	☒				
25	06/09/18 12:11	General View													Load JPG	☒				

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
				☒
26	06/09/18 12:11	General View	 Load JPG	☒
27	06/09/18 12:11	General View	 Load JPG	☒
28	06/09/18 12:11	General View	 Load JPG	☒
29	06/09/18 12:11	General View	 Load JPG	☒
30	06/09/18 12:11	General View	 Load JPG	☒
31	06/09/18 12:11	General View	 Load JPG	☒
32	06/09/18 12:11	General View	 Load JPG	☒
33	06/09/18 12:11	General View	 Load JPG	☒
34	06/09/18 12:11	General View	 Load JPG	☒
35	06/09/18 12:11	General View	 Load JPG	☒
36	06/09/18 12:11	General View	 Load JPG	☒
37	06/09/18 12:11	General View	 Load JPG	☒
38	06/09/18 12:11	General View	 Load JPG	☒
39	06/09/18 12:11	General View	 Load JPG	☒
40	06/09/18 12:11	General View	 Load JPG	☒
41	06/09/18 12:11	General View	 Load JPG	☒
42	06/09/18 12:11	General View	 Load JPG	☒
43	06/09/18 12:11	General View	 Load JPG	☒
44	06/09/18 12:11	General View	 Load JPG	☒
45	06/09/18 12:11	General View	 Load JPG	☒
46	06/09/18 12:11	General View	 Load JPG	☒
47	06/09/18 12:11	General View	 Load JPG	☒
48	06/09/18 12:11	General View	 Load JPG	☒
49	06/09/18 12:11	General View	 Load JPG	☒
50	06/09/18 12:11	General View	 Load JPG	☒
51	06/09/18 12:11	General View	 Load JPG	☒
52	06/09/18 12:11	General View	 Load JPG	☒
53	06/09/18 12:11	General View	 Load JPG	☒
54	06/09/18 12:11	General View	 Load JPG	☒
55	06/09/18 12:11	General View	 Load JPG	☒
56	06/09/18 12:11	General View	 Load JPG	☒
57	06/09/18 12:11	General View	 Load JPG	☒
58	06/09/18 12:11	General View	 Load JPG	☒
59	06/09/18 12:11	General View	 Load JPG	☒
60	06/09/18 12:11	General View	 Load JPG	☒
61	06/09/18 12:11	General View	 Load JPG	☒
62	06/09/18 12:11	General View	 Load JPG	☒
63	06/09/18 12:11	General View	 Load JPG	☒
64	06/09/18 12:11	General View	 Load JPG	☒
65	06/09/18 12:12	Reinspection Photo	 Load JPG	☒
66	06/09/18 12:12	Reinspection Photo	 Load JPG	☒
67	06/09/18 12:12	Reinspection Photo	 Load JPG	☒
68	06/09/18 12:12	Reinspection Photo	 Load JPG	☒
69	06/09/18 12:12	Reinspection Photo	 Load JPG	☒
70	06/09/18 12:12	Reinspection Photo	 Load JPG	☒
71	06/09/18 12:12	Reinspection Photo	 Load JPG	☒
72	06/09/18 12:12	Reinspection Photo	 Load JPG	☒
73	06/09/18 12:12	Reinspection Photo	 Load JPG	☒
74	06/09/18 12:12	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
75	06/09/18 12:12	Reinspection Photo		☒
76	06/09/18 12:12	Reinspection Photo		☒
77	06/09/18 12:12	Reinspection Photo		☒
78	06/09/18 12:12	Reinspection Photo		☒
79	06/09/18 12:12	Reinspection Photo		☒
80	06/09/18 12:12	Reinspection Photo		☒
81	06/09/18 12:12	Reinspection Photo		☒
82	06/09/18 12:12	Reinspection Photo		☒
83	06/09/18 12:12	Reinspection Photo		☒
84	06/09/18 12:12	Reinspection Photo		☒
85	06/09/18 12:12	Reinspection Photo		☒
86	06/09/18 12:12	Reinspection Photo		☒
87	06/09/18 12:12	Reinspection Photo		☒
88	06/09/18 12:12	Reinspection Photo		☒
89	06/09/18 12:12	Reinspection Photo		☒
90	06/09/18 12:12	Reinspection Photo		☒
91	06/09/18 12:12	Reinspection Photo		☒
92	06/09/18 12:12	Reinspection Photo		☒
93	06/09/18 12:12	Reinspection Photo		☒
94	06/09/18 12:12	Reinspection Photo		☒
95	06/09/18 12:12	Reinspection Photo		☒
96	06/09/18 12:12	Reinspection Photo		☒
97	06/09/18 12:12	Reinspection Photo		☒
98	06/09/18 12:12	Reinspection Photo		☒
99	06/09/18 12:12	Reinspection Photo		☒
100	06/09/18 12:12	Reinspection Photo		☒
101	06/09/18 12:12	Reinspection Photo		☒
102	06/09/18 12:12	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/03/18 09:13	NOTIFICATION FROM WORKSHOP + TP ESTIMATE + TP GIA REPORT		
2	22/03/18 10:20	TP ESTIMATE- MARKED		
3	05/09/18 14:55	LETTER TO OI		
4	05/09/18 14:55	GIA SEARCH		
5	15/11/18 10:17	WORKSHOP INVOICE		
6	15/11/18 10:17	AUTHORISATION TO ACT FORM		
7	15/11/18 10:17	Release Voucher		

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKT7206S (Insd veh)	Model:	VOLKSWAGEN TIGUAN 1.4
	SLD7844Y (TP veh)		TSI (A)
Date of Accident:	09/03/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	24,069.41
Final Repair Cost	:	\$	11,527.50
Loss of Use	:	\$	660.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	12,189.50

11.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Volkswagen Group Singapore Pte Ltd	:	\$ 12,189.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

15 Nov

2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18005152/T1EA3Q2

Date: 15/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100418032

Claimant Vehicle No: SLD7844Y

Insured Vehicle No: SKT7206S

Date of Loss: 09/03/2018

Nature of Claim: TP

Claim No: 4135262483SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD7844Y

Make & Model: VOLKSWAGEN TIGUAN, 1.4 TSI (A)

Engine No: CTH241212

Reg. Date: 28/06/2016 (Man. Year: 2016)

Chassis No: WVGZZZ5NZGW094282

Colour: White

Odometer: 41220 km

Engine Capacity: 1390 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/80 R16

Rear Tyre Size:

215/80 R16

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,414.78	4,693.37	4,721.41	50.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,080.00	6,080.00	7,000.00	53.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,494.78	10,773.37	11,721.41	52.11
+ GST 7.00/7.00% (S\$)	1,574.63	754.14	820.49	52.11
Nett Amount (S\$)	24,069.41	11,527.51	12,541.90	52.11
+ Loss of Use (11.0 x S\$60.00/day) (S\$)		660.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,189.51		

INSPECTION

Date of Assignment: 20/03/2018

Date Inspected: 20/03/2018 Inspected At:

Volkswagen Group Singapore Pte Ltd (HQ)

17 Tuas Ave 9

Singapore 639197

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*B&P NUMBER PLATE	Dented	160.00 FS	*160.00 FS
2	1		*REAR BUMPER (TOP)	Deformed	1,138.50 FS	*1,138.50 FS
3	1		*REAR BUMPER (CENTRE)	Deformed	398.19 FS	*398.19 FS
4	1		*REAR BUMPER SPOILER (LOWER)	Distorted	441.46 FS	*441.46 FS
5	1		*REINFORCEMENT	Not Necessary	480.96 FS	*- FS
6	1		*LHR BUMPER BRACKET	Not Necessary	23.80 FS	*- FS
7	1		*RHR BUMPER BRACKET	Necessary	23.80 FS	*23.80 FS
8	4		*RIVET	Necessary	8.96 FS	*8.96 FS
9	6		*NUT	Necessary	11.10 FS	*11.10 FS
10	1		*TOW COVER	Missing	48.59 FS	*48.59 FS
11	1		*REFLECTOR REAR LH	Cut	67.37 FS	*67.37 FS
12	1		*REFLECTOR REAR RH	Cut	52.53 FS	*52.53 FS
13	1		*REVERSING LIGHT LH	Not Necessary	75.95 FS	*- FS
14	1		*REVERSING LIGHT RH	Cut	75.95 FS	*75.95 FS
15	1		*LHR BUMPER PROTECTOR	Not Necessary	356.42 FS	*- FS
16	1		*RHR BUMPER PROTECTOR	Bent	356.42 FS	*356.42 FS
17	1		*RHR FENDER PROTECTOR	Not Necessary	613.41 FS	*- FS
18	1		*LHR FENDER PROTECTOR	Not Necessary	613.41 FS	*- FS
19	12		*GROMMET	Necessary	24.12 FS	*24.12 FS
20	1		*RHR FENDER LINER	Torn	182.00 FS	*182.00 FS
21	1		*REAR SENSOR (3 PCS)	Distorted (2 PCS ONLY)	525.29 FS	*350.20 FS
22	3		*PARKING SENSOR O RING	Necessary	1.95 FS	*1.95 FS
23	1		*SENSOR BRACKET (INNER) CENTRE	Necessary	14.78 FS	*14.78 FS
24	1		*SENSOR BRACKET (INNER) CENTRE	Necessary	14.79 FS	*14.79 FS
25	1		*SENSOR BRACKET (OUTER) CENTRE	Necessary	14.78 FS	*14.78 FS
26	1		*SENSOR BRACKET (OUTER) CENTRE	Necessary	14.78 FS	*14.78 FS
27	1		*SENSOR BRACKET (SIDE) OUTER RH	Not Necessary	13.36 FS	*- FS
28	1		*SENSOR BRACKET (SIDE) INNER RH	Not Necessary	25.66 FS	*- FS
29	1		*TIGUAN EMBLEM	Not Necessary	90.62 FS	*- FS
30	1		*TSI EMBLEM	Not Necessary	57.84 FS	*- FS
31	1		*BLUEMOTION EMBLEM	Not Necessary	69.58 FS	*- FS
32	1		*VW SIGN	Not Necessary	79.95 FS	*- FS
33	1		*RHS REAR FENDER AIR DUCT	Not Necessary	32.47 FS	*- FS
34	1		*FRT BUMPER	Repair	1,245.38 FS	*- FS
35	1		*FRT NUMBER PLATE BRACKET	Necessary	93.15 FS	*93.15 FS
36	6		*RIVET	Necessary	4.08 FS	*4.08 FS
37	1		*BUMPER FOAM FRT	Cracked	45.26 FS	*45.26 FS
38	1		*BUMPER SIDE BRACKET LH	Not Necessary	21.09 FS	*- FS
39	1		*BUMPER SIDE BRACKET RH	Not Necessary	21.09 FS	*- FS
40	1		*FRT REINFORCEMENT	Not Necessary	445.19 FS	*- FS
41	1		*MEMBER	Not Necessary	153.12 FS	*- FS
42	1		*SENSOR BRACKET FRT	Not Necessary	53.15 FS	*- FS
43	1		*SENSOR BRACKET FRT	Necessary	13.36 FS	*13.36 FS
44	1		*SENSOR BRACKET FRT	Necessary	13.36 FS	*13.36 FS
45	1		*SENSOR BRACKET FRT	Not Necessary	13.36 FS	*- FS
46	1		*SENSOR BRACKET FRT	Not Necessary	13.36 FS	*- FS
47	1		*CENTRE LOWER GRILLE (FRT)	Cut	160.33 FS	*160.33 FS
48	1		*AIR GUIDE LOWER	Not Necessary	47.15 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*VW SIGN (IMPROVE PART)	Cut	108.49 FS	*108.49 FS
50	1		*FRT BUMPER LOWER SPOILER	Cracked	855.07 FS	*855.07 FS
Total Parts (S\$)					9,414.78	4,693.37

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ELECT WIRING & MECH COMPONENT	New	280.00	280.00
2	PROGRAMMING & CALIBRATION	New	480.00	480.00
3	LABOUR (REAR)	New	4,200.00	1,680.00
4	SPRAY PAINT (REAR)	New	4,000.00	1,600.00
5	LABOUR (FRT)	New	2,520.00	840.00
6	SPRAY PAINT (FRT)	New	1,600.00	1,200.00
Gross Labour Cost (\$\$)			13,080.00	6,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >