

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18005168/T1DS3Q2

Date: 05/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100491930

Claimant
Vehicle No : SJS2258S **Insured Vehicle No :** SLJ1341P

Date of Loss: 17/03/2018 Nature of Claim: TP Claim No: 5692808685SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS2258S	Engine No:	CDA037243
Make & Model:	SKODA SUPERB, 1.8 Elegance (A)	Chassis No:	TMBBB93T399038358
Reg. Date:	03/08/2009 (Man. Year: 2009)	Odometer:	137291 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,748.81	6,572.81	6,176.00	48.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,430.00	1,470.00	960.00	39.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,178.81	8,042.81	7,136.00	47.01
Approved Total (Overridden) (\$\$)		6,400.00		
Nett Amount (\$\$)	15,178.81	6,400.00	8,778.81	57.84
+ Car Rental (9.0 x S\$130.00/day) (\$\$)		1,170.00		
Nett Liability (\$\$)		7,570.00		
Global Sum Settlement (\$\$)		7,500.00		

INSPECTION

Date of Assignment: 20/03/2018

Date Inspected: 21/03/2018 Inspected At:

Car Life Auto Engineering Services
(TOWN)
BLK 1002 #01-75 BUKIT MERAH
LANE 3
Singapore 159719

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,380.71 FL	*1,450.00 FL
2	2		*REAR BUMPER RETAINER	Necessary	279.40 FL	*279.40 FL
3	1		*REAR BUMPER ENFORCEMENT	Not Necessary	997.30 FL	*- FL
4	1		*REAR BUMPER BEAM	Not Necessary	20.00 FL	*- FL
5	1		*REAR BUMPER LOWER CHROME	Deformed	699.79 FL	*699.79 FL
6	1		*TAIL LAMP OUTER LH	Cracked	682.70 FL	*682.70 FL
7	1		*BOOT COVER TAIL LAMP LH	Cut	599.75 FL	*599.75 FL
8	1		*BOOT COVER LOWER	Damaged	3,007.60 FL	*1,860.00 FL
9	1		*BOOT COVER INNER	Bent	2,900.31 FL	*620.00 FL
10	1		*BOOT COVER CHROME	Necessary	488.70 FL	*388.00 FL
11	1		*END PANEL	Repair	1,370.61 FL	*- FL
12	1		*END PANEL GARNISH	Deformed	288.90 FL	*288.90 FL
13	1		*SKODA LOGO	Necessary	169.79 FL	*169.79 FL
14	1		*TSI EMBLEM	Necessary	169.79 FL	*169.79 FL
15	1		*NOS PLATE WITH CASE	Cracked	58.50 FS	*45.00 FS
16	10		*BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,158.85	7,298.12
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,410.04	725.31
Total Parts (\$\$)	12,748.81	6,572.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACE REAR BUMPER ,BOOT COVER ,AND TO PANEL BEAT CUT & WELD END PANEL	New	1,200.00	800.00
2	TO PUTTY & SPRAY PAINT REAR BUMPR,BOOT COVER AND OTHER AFFECTED AREA	New	800.00	600.00
3	TO CHECK & RECTIFY WIRING	New	80.00	30.00
4	TUFF KOTE	New	350.00	40.00
Gross Labour Cost (\$)			2,430.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >