

CAR LIFE AUTO ENGINEERING SERVICES

W/shop address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719
E-mail : autolife_sin@yahoo.com.sg
Tel: 6273 3810 Fax: 6278 7522

Date : 21-Mar-18

Address : NG KOK PENG
BLK 225 BUKIT BATOK CENTRAL
02-83
SINGAPORE 650225

Reference : TP 1150/03/18
Vehicle No : SJS 2258S
Make/Model : SKODA
Insurance Co. : AXA

RE : QUOTATION REPAIRS TO SJS 2258S FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>AMT \$</u>	
1) REAR BUMPER	1	\$ 2,380.71	dl
2) REAR BUMPER RETAINER	2	\$ 279.40	ca
3) REAR BUMPER ENFORCEMENT	1	\$ 997.30	?
4) REAR BUMPER BEAM	1	\$ 20.00	?
5) REAR BUMPER LOWER CHROME	1	\$ 699.79	dl
6) TAIL LAMP OUTER LH	1	\$ 682.70	ana
7) BOOT COVER TAIL LAMP LH	1	\$ 599.75	cut
8) BOOT COVER LOWER } for check. 1860	1	\$ 3,007.60	?
9) BOOT COVER UPPER	1	\$ 2,900.31	bt
10) BOOT COVER CHROME	1	\$ 488.70	✓
11) END PANEL	1	\$ 1,370.61	ky
12) END PANEL GARNISH	1	\$ 288.90	dl
13) "SKODA" LOGO	1	\$ 169.79	ner
14) "TSI" EMBLEM	1	\$ 169.79	ner
15) NOS PLATE WITH CASE	1	\$ 65.00	45 ar
16) BUMPER CLIPS	10	\$ 45.00	ner
LIST PRICE TOTAL		\$ 14,165.35	
LESS DISCOUNT 10%		\$ 1,416.54	
LIST PRICE TOTAL AFTER LESS		\$ 12,748.82	

NETT PRICE TOTAL \$0.00

TOTAL PARTS COST **\$12,748.82**

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE REAR BUMPER, BOOT COVER, AND TO PANEL BEAT CUT & WELD END PANEL	\$ 1,200.00	800
		(6 DAYS)	
2)	TO PUTTY & SPRAY PAINT REAR BUMPER, BOOT COVER AND OTHER AFFECTED AREA.	\$ 800.00	600
		(4 PANEL)	

3) TO CHECK & RECTIFY WIRING.

\$ 80.00 30

5) TUFF KOTE

\$ 350.00 40

LABOUR TOTAL

\$ 2,430.00

TOTAL ESTIMATED REPAIR COST

\$ 15,178.82

Tanjin 97495749

-wp-

21/2/18 e 1630

Lumpsum

Resurvey before After repair

6 days

See @ hhaub.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: