

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1367E
 Ref. No : TAX/03/18/2079
 Reg. Date : 07/05/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : REVEENDRAN VIJAYAN
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 14/03/2018 10:52:00 AM
 Accident Reported Date / Time : 16/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095080
 Special Instruction to ARC, if any :



Prepared Date : 16/03/2018 02:22:33 PM

Sebastian
19/3/18

- Lump Sum Repair.
- Question Mark Item Photo.
- Photo After Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chassis No : JTDKN36U205741498

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 2,808.00	0.00
Total Material Charges	: 4,263.66	4,350.68
Other Charges	: 580.00	0.00
TOTAL	: 8,665.66	0.00
Lum Sum Total	: 8,650.00	0.00
No. of Repair Days	: 7.00	0.00
Prepared / Adjusted By	:	4 days
Arc / Surveyor Sign Off Date	: 16/03/2018 03:35:10 PM	01/01/1900 12:00:00 AM

M

Prepared / Adjusted Date :

Remarks :

Prepared Date : 16/03/2018 03:35:10 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,014.00	0.00 500
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY VIEW MIRROR	180.00	0.00 50
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 100
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY DOOR HANDLE	180.00	0.00 50
Total Spray Painting & Panel Beating	2,808.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO TRANSFER DOOR MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX WING MIRROR	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	580.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace R	No
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace ?	No
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace R	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace ✓ N/C	No
67002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace R	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace ✓ N/C	No
87940-47310		6505599	MIRROR ASSY, LH	1	1,224.90	25.00	918.67	Replace	Replace X	No
81740-52040		6505465	MIRROR LAMP LH	1	65.30	10.00	58.77	Replace	Replace ✓ C/K	No
87945-74010		6505597	COVER, OUTER MIRROR, LH	1	107.40	25.00	80.55	Replace	Replace ✓ C/K	No
69210-74030			DOOR OUTER HANDLE FRT/LH	1	370.80	25.00	278.10	Replace	Replace R	No
69217-74010			COVER, FRONT DOOR OUTSIDE HANDLE	1	14.10	25.00	10.57	Replace	Replace R	No
75852-47900			MOULDING BODY, LH	1	673.60	25.00	505.20	Replace	Replace R	No
67004-47080		6505487	DOOR RR/LH	1	954.50	25.00	715.87	Replace	Replace R	No
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace R	No
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace ✓ N/C	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ N/C	No
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace R	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace ?	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓ N/C	No
TOTAL MATERIALS								5,438.37	5,438.35	
TOTAL MATERIALS(Discounted)								4,263.66	4,350.68	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									