

# EVER SEN AUTO SERVICE

BLK 3022A UBI ROAD 1 #01-49  
SINGAPORE 408716

Tel No. : 67437111 Fax No. : 67489611  
E-Mail : eversenauto@singnet.com.sg  
Buss. Reg. No. : B24044500/K

## EQ INSURANCE COMPANY LIMITED

5 Maxwell Road  
#17-00 Tower Block MND Complex  
Singapore 069110

Attention : Motor Claim Department

Contact : 62239433 Fax No. : 62234190/62243903

## Estimate : TI18/002

Date : 13/03/2018  
Vehicle Num. : SLB 5947 H  
Make/Model : TOYOTA ALTIS  
Chassis/Eng# : MR053REH104547448  
Accident Date : 11/03/2018  
Claim No. :  
Reference :  
Policy No. :

TPEQ  
Vic.

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1PC	BUMPER -REAR <i>Reformed</i>	627.1	597.10 ✓
2.	1PC	BUMPER BEAM -REAR <i>new</i>	470.32	329.40 *
3.	4PCS	CLIPS <i>new</i>	12.90	<del>51.60</del> 30
4.	1SET	BUMPER REVERSE SENSOR-RR <i>new</i>	S/N: 200	<del>350.40</del> 200.00
5.	2/LH&RH	BUMPER REFLECTOR REAR <i>new</i>	66.90	133.80 *

List Total S\$ :

1,470.30

### LABOUR :

ACCIDENT REPAIR PANEL BEATING  
RUSTPROOFING TREATMENT  
RESPRAY PAINT WORK ON REPAIR AREA  
WIRING SERVICE

430

~~680.00~~ 200  
150.00 \*  
~~680.00~~ 200  
~~80.00~~ 30

Labour Total S\$ :

1,590.00

SingDollars : Three Thousand Sixty & Cents Thirty Only

Total S\$ : 3,060.30

EVER SEN AUTO SERVICE

*[Signature]*

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey, before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

1/5 Adrian King,  
02 days.

total: 1100.32  
1/5: 880