

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 19 March 2018

Third Party Insurer:

INDIA

Vehicle No: SFJ8111L

Third Party Veh No:

SHB4085Z

Model: MERCEDES BENZ A45

Date of Accident:

16/03/18

Chassis: WDD1760522J272590

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	<i>By</i>	\$1,767.00
1	REAR TAILGATE LOGO EMBLEM	<i>me</i>	\$47.00
3	REAR TAILGATE LOGO EMBLEM CLIP	<i>me</i> \$9.00	\$27.00
1	REAR TAILGATE AMG EMBLEM	<i>me</i>	\$152.00
1	REAR TAILGATE WINDSCREEN MOULDING	<i>me</i>	\$582.00
2	REAR TAILLAMP LOWER BRACKET LH + RH	\$49.00	\$98.00
1	REAR BUMPER	<i>Bumper</i>	\$1,513.00
4	REAR BUMPER REVERSE SENSOR	\$280.00	\$1,120.00
4	REAR BUMPER REVERSE SENSOR RUBBER SEAL	<i>me</i> \$12.00	\$48.00
4	REAR BUMPER REVERSE SENSOR HOLDER	\$28.90	\$115.60
1	REAR BUMPER REVERSE SENSOR WIRE HARNESS SET		\$121.00
1	REAR BUMPER TOW HOOK COVER	<i>CM</i>	\$53.00
2	REAR BUMPER SIDE SPOILER LH + RH	\$142.00	\$284.00
1	REAR BUMPER LOWER DIFFUSER	<i>me</i>	\$228.00
1	REAR BUMPER LOWER LIP CARBON FIBER 'ORIGINAL'	<i>Not in</i>	\$2,995.86
2	REAR BUMPER SIDE RETAINER LH + RH	\$26.00	\$52.00
10	REAR BUMPER CLIP	\$9.00	\$90.00
8	REAR BUMPER RIVET	\$9.00	\$72.00
1	REAR BUMPER TOP RETAINER		\$106.00
1	REAR BUMPER REINFORCEMENT		\$456.00
2	REAR BUMPER SIDE AIR GUIDE LH + RH	\$33.00	\$66.00
2	REAR EXHAUST END CHROME PIPE LH + RH	<i>olsmit</i>	\$418.00
2	REAR EXHAUST END PIPE LH + RH		\$430.00
2	REAR EXHAUST END PIPE GASKET LH + RH		\$48.00
1	REAR EXHAUST ALUMINIUM HEATSHIELD		\$193.00
SUB TOTAL			\$11,978.46
Less 10%			-\$1,197.85
PARTS TOTAL			\$10,780.61

*Not within
1. B1
Resurvey B4 paint
5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 19 March 2019

Third Party Insurer:

INDIA

Vehicle No: SFJ8111L

Third Party Veh No:

SHB4085Z

Model: MERCEDES BENZ A45

Date of Accident:

16/03/18

Chassis: WDD1760522J272590

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	100	\$100.00
1	REAR BUMPER TOP CARBON STICKER	200	\$200.00
1	REAR BUMPER LOWER LIP CARBON FIBER RED STICKER	100	\$100.00
1	REAR BUMPER LOWER LIP CARBON FIBER CARBON STICKER	180	\$180.00
S/N TOTAL			\$580.00

400a
?
?
?

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,000.00	500
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$800.00	600
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	\$180.00	?
TO CHECK WIRING WITH TEST	\$80.00	200
TO DISMANTLE & REALIGNED REAR EXHAUST SILENSER BOX	\$200.00	800
TO DISMANTLE & REFIX REAR TAILGATE REVERSE CAMERA	\$80.00	600
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$80.00	600
TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST	\$150.00	1200
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$230.00	800

LABOUR TOTAL \$2,800.00

WINSON TOTAL \$14,160.61