

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

Estimate No: ES1890270/YISHUN

Date: 19 Mar 2018

Policy No: 5096302434

Veh Reg No: SJS1357X

Make/Model: HONDA FREED 1.5 GL
 AUTO

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 17/03/2018

TP Veh Reg No: SKN3703G

Not Authorized

6/1 Sep 8?

Recovery After Pairs

Chassis No: GB31040609

Engine No: L15A2341095

Reg. Date: 29/07/2009

Estimate Repair Cost to Vehicle No :SJS1357X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	562.10	1 PC	<i>CM</i> 562.10	✓
2 FRONT BUMPER REINFORCEMENT	233.70	1 PC	233.70	?
3 FRONT BUMPER LH SIDE RETAINER	17.90	1 PC	<i>Dii</i> 17.90	✓
4 FRONT BUMPER TOW COVER	15.00	1 PC	<i>mii</i> 15.00	✓
5 FRONT BUMPER CLIPS	3.70	6 PCS	<i>m</i> 22.20	✓
6 LH HEADLAMP	650.80	1 PC	<i>m, dii</i> 650.80	✓
7 LH HEADLAMP LOWER RETAINER	24.15	1 PC	<i>dii</i> 24.15	✓
8 FRT SUPPORT PANEL	540.10	1 PC	540.10	?
9 FRONT GRILLE	220.30	1 PC	<i>Red</i> 220.30	✓
10 FRONT GRILLE LOGO	24.70	1 PC	<i>m</i> 24.70	✓
11 FRONT GRILLE MOULDING	206.00	1 SET	206.00	?
12 FRONT GRILLE CLIPS	3.70	4 PCS	<i>m</i> 14.80	✓
13 AIR-CON CONDENSER	747.80	1 PC	747.80	?
14 RADIATOR	1,302.90	1 PC	1,302.90	?
15 REAR TAILGATE	1,282.80	1 PC	<i>B</i> 1,282.80	✓
16 TAILGATE LOGO	25.70	1 PC	<i>m</i> 25.70	✓
17 TAILGATE EMBLEM (FREED)	42.10	1 PC	<i>m</i> 42.10	✓
18 REAR WINDSCREEN GLASS MOULDING	151.80	1 PC	<i>m</i> 151.80	✓
19 REAR BUMPER	490.30	1 PC	<i>B</i> 490.30	✓
20 REAR BUMPER RH SIDE RETAINER	28.00	1 PC	<i>dii</i> 28.00	✓
21 REAR BUMPER CLIPS	3.70	6 PCS	<i>m</i> 22.20	✓
22 RH TAILLAMP	458.10	1 PC	<i>6/1/m3/cm</i> 458.10	✓
23 REAR RH TAILLAMP PANEL	210.30	1 PC	210.30	?
24 REAR PANEL	342.90	1 PC	<i>B</i> 342.90	✓
25 REAR PANEL INNER TOP GARNISH	80.60	1 PC	80.60	?
26 REAR RH FENDER	1,294.50	1 PC	<i>Bu</i> 1,294.50	✓
27 REAR RH FENDER GLASS MOULDING	30.50	1 PC	<i>m</i> 30.50	✓
28 REAR EXHAUST PIPE	820.90	1 PC	820.90	?
29 REAR EXHAUST PIPE TOP SHIELD	48.60	1 PC	48.60	?
			9,911.75	
		Less 20%	1,982.35	7,929.40
Special Net				
30 REAR WINDSCREEN GLASS GUM	40.00	1 PC	<i>m</i> 40.00	✓
31 COOLANT (2 LTRS)	40.00	1 UNIT	40.00	?
			80.00	80.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288 FAX: 68804739
 ATTN: Motor Claim Department

WS Ref: TP/AXA/YS
 Claim Type: Third Party
 Accident Date: 17/03/2018
 TP Veh Reg No: SKN3703G

Estimate No: ES1890270/YISHUN
 Date: 19 Mar 2018
 Policy No: 5096302434
 Veh Reg No: SJS1357X
 Make/Model: HONDA FREED 1.5 GL
 AUTO
 Chassis No: GB31040609
 Engine No: L15A2341095
 Reg. Date: 29/07/2009

Estimate Repair Cost to Vehicle No :SJS1357X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
32 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
33 REMOVE & REFIX REAR RH FENDER GLASS	80.00	1 LA	80.00	601
34 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE & ATTACHMENT, TO STRAIGHTEN, CUT, WELD & RENEW REAR PANEL, RH TAILLAMP PANEL, REAR RH FENDER, STRAIGHTEN, KNOCK & REPAIR REAR RH CHASSISS, REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME	1,500.00	1 LA	1,500.00	13001
35 REMOVE & REFIX SEAT, CARPET, TOP ROOF LINING, ETC	120.00	1 LA	120.00	✓
36 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	60.00	1 LA	60.00	✓
37 REMOVE & REFIX FRT BUMPER ASSY HEADLAMPS, GRILLE, RADIATOR & MOTOR, FRT FENDERS, CUT, WELD & RENEW FRT SUPPORT PANEL, KNOCK & REPAIR FRT LH FENDER & REALIGN THE SAME	700.00	1 LA	700.00	7
38 PUTTY & RESPRAY ON FRT PORTION	600.00	1 LA	600.00	5401
39 PUTTY & RESPRAY ON FRT & REAR RH DOORS, TAILGATE, REAR BUMPER, REAR RH FENDER, COMPARTMENT & ALL AFFECTED AREA	1,400.00	1 LA	1,400.00	13001
40 RUSTPROOFING	150.00	1 LA	150.00	1201
41 REMOVE & REFIX REAR EXHAUST & CHECK LEAKING	60.00	1 LA	60.00	✓
			4,790.00	4,790.00

Total S\$ 12,799.40

Add GST @ 7% 895.96

Total Amount Payable S\$ 13,695.36

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE