

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

AKA
LKK
21/31
after 11am

14/03/2018

Owner: ALLIANCE LEASING PTE LTD

Not wither
61 Sep @ 3100
Penny After Pain
4 days

ESTIMATE TO REPAIR HONDA STREAM 1.8L - SJL4537K

1pc front bumper
2pcs front bumper side retainer @ \$13.00
1pc front LH headlamp
1pc front LH headlamp lower bracket
1pc front LH fender
1pc front LH fender inner shield
1pc front LH door
1pc front LH door frame sticker 1
1pc front LH door frame sticker 2

R	\$	635.40	X
SL	\$	26.00	X
SL	\$	958.00	✓
SL	\$	36.50	X
R	\$	486.30	✓
SL	\$	80.40	X
R	\$	987.50	✓
M	\$	181.50	✓
M	\$	195.50	✓


\$	3,587.10
\$	717.42
\$	2,869.68

1pc front LH side skirt

CM s.nett \$ 480.00 ✓

wiring
tuffkote
spray painting
labour charges
Total

\$	80.00	201
\$	80.00	601
\$	1,000.00	6001
\$	950.00	5001
\$	5,459.68	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____