

ASS. REC. BY:

REF: CS/FCI 18005187 / D/d3

Special Instructions:

Surveyor: Lynn

ASSIGNMENT (Office)

From (Person): May Chua

of: FCI

Date/Time: 19/3/18 @ 2:34pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 8811M

Insured: SH7570H

at Workshop m/s: Churni Motor

Tel: 65425119

of: AMK Autoport #01-05/06

Policy No:

Claim No: D18002204MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 16/3/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time: 2:29pm @ 20/3/18 Person Contacted: Lynn

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 8811M - x
	SH7570H - CS3/FCI 15015038/F/bdl D.O.A: 1/9/15
26/3	Report preli advise
09/04/18	Finance 1/5 14500/- with 7 dgs. (Red: 885994, 370%)

MOTOR SURVEY ASSIGNMENT

Date 16-03-2018 **Our Ref No.** D18002204MFSH

Accident Date 16-03-2018 **Claim Type.** Third Party

Insured Vehicle SH7570H **Third Party Vehicle.** SHC8811M

Survey Location AMK AUTOPOINT, SOON HOCK MOTOR,#01-05/06

Contact Person. LYNN OR IRENE

Contact No. 64836016/ 65425119 **Fax No.** 65426039

Survey Type WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Fax No.** 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop CHUNNI MOTOR WORK PTE LTD **Attention.** NIL

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge MAY CHUA

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236055)

PRI Documents

Close X

PRI Header Details

Claim No	D18002204MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CHUNNI M
Workshop Name	CHUNNI MOTOR WORK PTE LTD (Contact Person : LYNN OR IRENE)	Survey Location & Contact Details	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06 Mobile: 65425119 , Phone: 64836016 , Fax: 6542603! EmailId: CHUNNIMOTOR@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7570H	TP Vehicle No	SHC8811M
PRI Recieved Date	16-03-2018 09:23:33 PM	Surveyor Appointed Date	19-03-2018 02:33:26 PM	Surveyor Accept Date	20-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	20-03-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--------------------------------------------

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005187/Dtd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 7570H	Veh. Inspected	SHC 8811M
Policy No.		Coverage (\$)	0.00
Claim No.	D18002204MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	20/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/03/2018	Inspection Date	20/03/2018
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MCO81803821R / ComfortDelGro Engineering Pte Ltd - Leyang
 ENTRY DATE & TIME: 18/03/2018 16:02
 SUBMITTED BY: Janet Lim Slang Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/03/2018 16:02
Date Of Accident	16/03/2018 12:10
Exact Location Of Accident	TAMPINES AVE 5 BEFORE TAMPINES CENTRAL 2 JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8811M
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	MOHD AMIN B SULAIMAN
NRIC No	S1249671J
Date Of Birth	14/06/1957
Occupation	OUTDOOR
Date Of Driving Pass	03/05/1977
Driving Experience	40 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 230B TAMPINES STREET 24 #10-33
Postcode	525230
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH7570H
Vehicle Make/Model/Colour	HYUNDAI I40
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKH6417U
Vehicle Make/Model/Colour	HYUNDAI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOHAMED NASEER BIN TAM ABDUL AZIZ
NRIC/Passport Number	S8040631B
Contact Number	97818503
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time: 16.03.2018 @ 16:00 Hrs

Reporting Centre Personnel's Signature
Name: *Rubbini*
NRIC/FIN No.:

SKETCH PLAN



A - SHC 8811M.
 B - SH 7570H. (CTPL)
 C - SKH 6417U.

Along Tampines Ave 5 B4 Tampines Central 2 Junction.

Describe Circumstances of the Accident

On 16/03/2018 @ about 12:10 hrs,my taxi (A) (SHC 8811M) was travelling along Tampines Ave 5 before Tampines Central 2 junction with no passenger on board.
I saw infront of my vehicles slowing down and stopped ,So I follow too.
Out of sudden,there was a loud impact coming from the rear portion and caused my taxi (A),to lose control and surge forward,and colliding onto veh (C) (SKH 6417U) rear portion.My taxi (A) front and rear portion were damaged.
I assessed the damages to my taxi (A) and come to know that there were 3 vehicles involved in the chain accident.
No one was conveyed by the ambulance.
The parties involved in the accident are:
A - SHC 8811M.
B - SH 7570H (CTPL). Female driver.
C - SKH 6417U. Mr. Mohamed Naseer Bin Tam Abdul Aziz. NRIC : S 8040631B. Hp : 9781 8503.
No injury in this accident.

I/We declare the foregoing particulars are true in every respect.

CHUNNI MOTOR TRANSPORTATION PTE LTD
 CO. RES. NO. 199303821R

Rubbini

policyholder's Signature

Date & Time

Driver's Signature (If driver is not the policyholder)

Date & Time 16.03.2018 @ 16:00 Hrs

Reporting Centre Personnel's Signature

Name : Rubbini

NRIC/FIN No :-

SHC 8811M

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>is+</i>			\$ 1,681.40	L
	Boot Lid Rubber <i>distorted</i>			\$ 115.80	L
	Boot Lid Hinge (LH/RH) <i>SVC</i>		\$ 178.10	\$ 356.20	X
	Boot Lid Lock Upper <i>is+</i>			\$ 137.90	L
	Boot Lid Lock Lower <i>is+</i>			\$ 31.70	L
	Boot Lid 'H' Emblem <i>h/c</i>			\$ 27.20	L
	Boot Lid CRDI Plate <i>h/c</i>			\$ 41.00	L
	Boot Lid Lamp (LH/RH) <i>h/s crack o/s svc</i>		\$ <u>556.80</u>	\$ 1,113.60	L
	Boot Lid Trimboard <i>torn</i>			\$ 172.70	L
	Boot Lid Trimboard Clips (10pcs) <i>h/c</i>			\$ 11.00	L
	Bootlid Moulding <i>SVC</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>h/c</i>			\$ 41.00	L
	Bootlid Lower Garnish <i>SVC</i>			\$ 398.00	X
	Rear Bumper <i>distorted</i>			\$ 603.60	L
	Rear Bumper Reinforcement <i>crack</i>			\$ 504.35	X L
	Rear Bumper Reinforcement Bracket (LH/RH) <i>is+</i>		\$ 180.00	\$ 360.00	X L
	Rear Bumper Clip 10 pcs <i>h/c</i>			\$ 22.00	L
	Rear Bumper Bracket <i>SVC</i>		\$ 49.00	\$ 98.00	X
	Rear Bumper Sponge <i>is torn</i>			\$ 143.40	X L
	Rear Bumper Under Cover <i>distorted</i>			\$ 225.00	L
	Tail Lamp (LH/RH) <i>crack</i>		\$ 565.60	\$ 1,131.20	L
	Rear Panel <i>dent</i>			\$ 592.30	L
	Rear Panel Garnish <i>almost missing</i>			\$ 57.70	L
	Rear Panel Lower Panel <i>is dent</i>			\$ 495.50	X L
	Exhaust Pipe Insulator <i>HN</i>		\$ 58.55	\$ 117.10	X
	Exhaust Silencer <i>is wt</i>		\$ 954.00	\$ 1,908.00	X L
	Exhaust Pipe Hanger <i>SVC</i>		\$ 58.55	\$ 117.10	X
	Exhaust Pipe Centre <i>is HN</i>			\$ 1,150.30	X
			8859.55	\$ 11,738.05	
				\$ 2,347.61	
				\$ 9,390.44	
				\$ 30.00	Nett L
				\$ 135.70	Nett L
				\$ 50.00	Nett L
				\$ 215.70	
				\$ 1,000.00	800/-
				\$ 800.00	600/-
				\$ 50.00	30/-
				\$ 50.00	20/-
				\$ 120.00	40/-
				\$ 360.00	60/-
				\$ 2,380.00	
				\$ 23,359.94	

SUB TOTAL
LESS 20%
DISCOUNTED TOTAL

8859.55
7087.64

215.70

1550/-

TOTAL LABOUR
ESTIMATE TOTAL

18302.14
1514500-

KK Auto Cons...
the Repairer of...
To resurvey before...
To display damaged...
Parts prices are s...
Third party survey...
No illegal modifica...
Supplementary ite...
is subject to final...
Acknowledged by R...
Signature:
Date:

20/03/2018
HVA Antan
Liam F
Rajan
KK Auto

Boot Lid Comfort Logo & Tel No. Sticker *h/c*
Rear Bumper Reverse Sensor *is wt*
Rear Bumper Rubber Mat *h/c*
Labour Charge
Panel Beating
Spray Painting Charge
Wiring Charge

Tuff Kote
Remove/Refix Reverse Sensor
Remove/Refix Exhaust Pipe
Check BV
Photo given



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005187/Dtd3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 7570H	Veh. Inspected	SHC 8811M
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18002204MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	19/03/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU085452	Colour	BLUE
Odometer	336678	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	6 mm
L/H Front Tyre	205/60 R16	HANKOOK	6 mm
R/H Rear Tyre	205/60 R16	HANKOOK	6 mm
L/H Rear Tyre	205/60 R16	HANKOOK	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/03/2018	Inspection Date	20/03/2018
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8811M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RADIATOR GRILLE	CUT	1,480.00	1,480.00
1	RADIATOR GRILLE H EMBLEM	NECESSARY	290.80	290.80
1	RADIATOR GRILLE CHROME MOULDING	SERVICEABLE	395.50	-
1	FRONT BUMPER COVER	DISTORTED / MTG CRACKED	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	TORN	142.20	142.20
1	FRONT BUMPER REINFORCEMENT	BENT	526.10	526.10
1	FRONT BUMPER LIP	SERVICEABLE	62.50	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	SERVICEABLE	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	SERVICEABLE	49.20	-
2	FRONT BUMPER RETAINER MOUNTING @\$9.20	SERVICEABLE	18.40	-
1	HEADLAMP SUPPORT TOP COVER	TORN	398.00	398.00
1	HEADLAMP SUPPORT PANEL ASSY	CRACKED / BENT	1,067.50	1,067.50
2	HEADLAMP (LH/RH)@\$1388.00	MTG CRACKED	2,776.00	2,776.00
1	RADIATOR	BENT	850.20	850.20
1	RADIATOR FAN BLADE ,COWLING ,MOTOR ASSY	NOT NECESSARY	792.95	-
2	RADIATOR BRACKET (RH/LH) @\$6.50	NOT NECESSARY	13.00	-
1	RADIATOR EXTENSIO TANK	NOT NECESSARY	48.00	-
2	RADIATOR GUARD @\$35.00	NOT NECESSARY	70.00	-
2	HORN UNIT (LH/RH)@\$86.75	NOT NECESSARY	173.50	-
1	AIRCON CONDENSER	BENT	1,137.35	1,137.35
1	INTER COOLER	PUNCTURE	921.90	921.90
2	INTER COOLER MOUNTING	NOT NECESSARY	25.90	-
1	BOOT LID	BENT	1,681.40	1,681.40
1	BOOT LID RUBBER	DEFORMED	115.80	115.80
2	BOOT LID HINGE (LH/RH) @\$178.10	SERVICEABLE	356.20	-
1	BOOT LID LOCK UPPER	BENT	137.90	137.90
1	BOOT LID LOCK LOWER	BENT	31.70	31.70
1	BOOT LID 'H' EMBLEM	NECESSARY	27.20	27.20
1	BOOT LID CRDI PLATE	NECESSARY	41.00	41.00
2	BOOT LID LAMP (LH/RH) @\$556.80	N/S CRACKED / O/S	1,113.60	556.80

Report Ref No. CS/FC118005187/Dtd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LID TRIMBOARD	TORN	172.70	172.70
10	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00
1	BOOTLID MOULDING	SERVICEABLE	85.00	-
1	BOOTLID I40 EMBLEM	NECESSARY	41.00	41.00
1	BOOTLID LOWER GARNISH	SERVICEABLE	398.00	-
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	CRACKED	504.35	504.35
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	BENT	360.00	360.00
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$49.00	SERVICEABLE	98.00	-
1	REAR BUMPER SPONGE	TORN	143.40	143.40
1	REAR BUMPER UNDER COVER	DISTORTED	225.00	225.00
2	TAIL LAMP (LH/RH) @\$565.60	CRACKED	1,131.20	1,131.20
1	REAR PANEL	DENTED	592.30	592.30
1	REAR PANEL GARNISH	MTG DEFORMED	57.70	57.70
1	REAR PANEL LOWER PANEL	DENTED	495.50	495.50
2	EXHAUST PIPE INSULATOR @\$58.55	NOT NECESSARY	117.10	-
2	EXHAUST SILENCER @\$954.00	BENT	1,908.00	1,908.00
2	EXHAUST PIPE HANGER @\$58.55	SERVICEABLE	117.10	-
1	EXHAUST PIPE CENTRE LESS 20% DISCOUNT	NOT NECESSARY	1,150.30	-
			-4,814.81	-3,900.36
			19,259.24	15,601.44
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	CRACKED	25.00	25.00
1	FRONT NO PLATE TRIM COVER (SN)	SERVICEABLE	30.00	-
1	BOOT LID COMFORT LOGO TEL NO.STICKER (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			270.70	240.70
	<u>LABOUR</u>			
	PANEL BEATING .		2,000.00	1,400.00
	SPRAY PAINTING CHARGE.		1,000.00	800.00

Report Ref No. CS/FC118005187/Dtd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHARGE.	NOT NECESSARY	100.00	60.00
	TOWING CHARGE.		50.00	-
	REMOVE/ REFIX AIRCON & REFILL GAS.		150.00	80.00
	TUFF KOTE .		50.00	20.00
	REMOVE/REFIX REVERSE SENSOR .		120.00	40.00
	REMOVE/REFIX EXHAUST PIPE.		360.00	60.00
			3,830.00	2,460.00
	GRAND TOTAL		23,359.94	18,302.14
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			14,500.00

Report Ref No. CS/FCI18005187/Dtd3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.