



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

VEHICLE NO. : SLA727P
ACCIDENT DATE : 17-03-2018 13:55
THIRD PARTY REF. : SJS1362E

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SLA727P HONDA VEZEL

DATE : 19-03-2018

*Not Arthur
diana mercus
take photo before party
Tel: 62583581
2 day*

QTY PARTS DESCRIPTION

1	1	FRONT BUMPER
2	1	FRONT BUMPER SIDE RETAINER LH
3	10	FRONT BUMPER CLIP@\$4.90
4	1	FRONT FENDER GARNISH LH

AMOUNT (SG\$)

Repair	801.70	✓
11	20.60	✓
10	49.00	✓
Grand	195.00	✓

1,066.30

LESS 20 %

213.26

TOTAL (A)

853.04

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS
3	1	SPRAYPAINTING CHARGES

30.00 20

400.00 200

400.00 380

TOTAL (D)

830.00

ESTIMATE TOTAL

1,683.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: