

ASS. REC. BY:

REF: CS/EG18005189/Avd3n2 Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 19/3/18 @ 5:06pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 4679H Insured: SLS 7333B

at Workshop m/s JEC AUTO Service Tel: 92327457

of 1 Kaki Bkt Ave 6 # 02-11

Policy No: Claim No: SLS 7333B / SE / p /

Sum Insured: Excess:

Make of Veh: D.O.A. 16/03/18  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time: 11:49am @ 20/3/18 Person Contacted: Ah xian Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

SLC 4679H - x

SLS 7333B - x

21/3/18

Informed Pei Li pending for workshop est by email

11/4/18

Adrian confirmed LS \$ 5500 (Red 12, 152.88, 687)

11/4/18

Email preli revised to ERGO

ASS. REC. BY: Adrian Ling

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLC 4679H Yr Regn: 2016 MayType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier Premium cc 1986Colour: White A/C: Insured / Std / NI / NASp. Reading: 27917 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ZSU600077371Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/55R18R: 235/55R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 20/03/18Survey held at JECDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Ego.

RECEIVED 11 APR 2018

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 5

1)

☐ : Final ReportResurvey No. of Trip: 2

Date/Time, File Return to?

2) 11/4 - typistAdd Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

350

Report Format: TPLump Sum / I.B.I. (\$) 5500/p



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18005189/Avd3

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 20-03-2018



Code : EGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 7333B	Veh. Inspected	SLC 4679H
Policy No.		Coverage (\$)	0.00
Claim No.	SLS 7333B/SE/pl	Excess (\$)	0.00
Assign From	YEE PE LI	Assign Date	20/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	16/03/2018	Inspection Date	20/03/2018
Survey held at	JEC AUTOMOTIVE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SLS 7333B/SE/pl

Our ref: CS/EGI18005189/Avd3

Date : 11/4/2018

The Motor Claims Department  
M/s: ERGO Insurance Pte Ltd

***Without Prejudice***

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SLC 4679H**


We thank you for your instruction on 19/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/3/2018 at the premises of M/s JEC AUTOMOTIVE

Workshop Estimate Amount	: S\$17,652.88
Revised Estimate Amount	: S\$5,500.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the rear portion.



**Comments/Present Status:**  
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING  
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI  
Licensed Appraiser

**Nivitha (LKK Auto)**

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Monday, 19 March 2018 5:06 PM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : SLS7333B / TP : SLC4679H/LKK / DOA : 16/03/2018  
**Attachments:** SLC4679H - SAS.pdf; SLC4679H - PRS FORM.pdf; ACCIDENT INVOLVING SLC4679H & SLS7333B ON 16-3-2018. Y REF: SLS7333B/SE/... (9.11 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **JUSEQUITY LAW CORPORATION**.

ADDRESS : **JEC AUTO SERVICE**  
1 KAKI BUKIT AVENUE 6  
#2-11 AUTOBAY @ KAKI BUKIT  
SINGAPORE 417883

PERSON TO CONTACT : AH XIAN @ 9232 7457

ERGO OFFICER-IN-CHARGE : STEVE

***Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please update the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached is TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

**Kindly acknowledge receipt of this email.**

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

# ERGO

Date: 19.03.2018  
Our Reference: SLS 7333B/SE/pl  
Your Reference: JEQ/1802180318/JEC(ZL)

Sent via Fax

6253 0120

or

Email

To: JUSEQUITY LAW CORPORATION

## Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLC 4679H  
Insured's Vehicle: SLS 7333B  
Date Of Accident: 16.03.2018

We acknowledge receipt of your request for PRS on: 19.03.2018


In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.  
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.  
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.  
☒ Our Insured's driver has not reported the accident to us todate.  
☒ Others:

**WORKSHOP DETAILS NOT PROVIDED. OFFICER-IN-CHARGE - SITI**  
**KINDLY UPDATE YOUR RECORDS, ERGO CLAIMS DEPT. FAX NO. IS 6829 9247**

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

### Assessor use only:

Assignment Date: \_\_\_\_\_  
Assignment Time: \_\_\_\_\_

Remarks:

### Workshop use only:

#### Assessor attended workshop on:

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 11 April 2018 10:15 AM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** SUR  
**Subject:** RE: OI : SLS7333B / TP : SLC4679H/LKK / DOA : 16/03/2018  
**Attachments:** SLC 4679H PRELI REVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLC 4679H  
Date of survey: 20/3/2018  
Number of days:5 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 21 March 2018 1:52 PM  
**To:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: OI : SLS7333B / TP : SLC4679H/LKK / DOA : 16/03/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SLC 4679H on 20/3/2018 .

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Monday, 19 March 2018 5:29 PM  
**To:** Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** RE: OI : SLS7333B / TP : SLC4679H/LKK / DOA : 16/03/2018

Dear Catherine,

Enclosed OI's SAS for your action.

Rgds  
Pei Li

**From:** Survey Report (ERGO Insurance Pte. Ltd.)  
**Sent:** Monday, 19 March, 2018 5:06 PM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : SLS7333B / TP : SLC4679H/LKK / DOA : 16/03/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **JUSEQUITY LAW CORPORATION**.

ADDRESS : **JEC AUTO SERVICE**  
1 KAKI BUKIT AVENUE 6  
#2-11 AUTOBAY @ KAKI BUKIT  
SINGAPORE 417883

PERSON TO CONTACT : AH XIAN @ 9232 7457

ERGO OFFICER-IN-CHARGE : STEVE

**Note:** To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please update the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached is TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

**Kindly acknowledge receipt of this email.**

Thank you.

**Yee Pei Li**  
Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 21 March 2018 1:52 PM  
**To:** Survey Report (ERGO Insurance Pte. Ltd.)  
**Cc:** SUR  
**Subject:** RE: OI : SLS7333B / TP : SLC4679H/LKK / DOA : 16/03/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SLC 4679H on 20/3/2018 .

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]  
**Sent:** Monday, 19 March 2018 5:29 PM  
**To:** Admin-D (LKKAUTO) <admin-d@lkkauto.com>  
**Subject:** RE: OI : SLS7333B / TP : SLC4679H/LKK / DOA : 16/03/2018

Dear Catherine,

Enclosed OI's SAS for your action.

Rgds  
Pei Li

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.)  
**Sent:** Monday, 19 March, 2018 5:06 PM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : SLS7333B / TP : SLC4679H/LKK / DOA : 16/03/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **JUSEQUITY LAW CORPORATION,**

ADDRESS : **JEC AUTO SERVICE**  
1 KAKI BUKIT AVENUE 6  
#2-11 AUTOBAY @ KAKI BUKIT  
SINGAPORE 417883

PERSON TO CONTACT : AH XIAN @ 9232 7457

ERGO OFFICER-IN-CHARGE : STEVE

***Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please update the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached is TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

**Kindly acknowledge receipt of this email.**

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

# JEC AUTO SERVICE

1 Kaki Bukit Avenue 6 #02-11 Autobay, Singapore 417883

H/P : 9232 7457

Fax : 6509 6584

Email : jecautoservice@yahoo.com.sg

Vehicle No. : SLC4679H

TP Ergo  
Voron

Qty	List Price	Price
1	Rear Bumper <i>Dehorn d</i>	\$ 1,481.50 -
1	Rear Bumper Sponge <i>amul d</i>	\$ 160.20 ✓
1	Rear Bumper Reinforcement <i>new</i>	\$ 485.60 ✗
2	Rear Bumper Support Bracket @ \$68.50 <i>new</i>	\$ 137.00 ✗
2	Rear Bumper Side Retainers-R/L @ \$101.20 <i>new</i>	\$ 202.40 -
1	Rear Smart Keyless Sensor <i>new</i>	\$ 230.50 ✗
2	Rear Bumper Reflector @ R/L \$96.80 <i>new</i>	\$ 193.60 ✓
1	Rear Bumper Difusser <i>Rehd</i>	\$ 419.65 ✓
2	Rear Lamps @ R/L @ \$481.60 <i>new</i>	\$ 963.20 ✗
1	Rear End Panel <i>Rehd Dented.</i>	\$ 881.65 ✓
1	Rear End Panel Garnish <i>Not new</i>	\$ 381.60 ✗
1	Rear Exhaust <i>new</i>	\$ 516.50 ✗
1	Tailgate Glass Moulding <i>new</i>	\$ 199.62 -
1	Tailgate <i>Dented</i>	\$ 1,975.60 ✓
1	Tailgate Logo <i>new</i>	\$ 68.50 -
2	Tailgate Lamps @ R/L @ \$414.20 <i>new</i>	\$ 828.40 ✗
1	Tailgate Spoiler <i>new</i>	\$ 596.60 ✗
1	Tailgate Outer Opening Switch <i>new</i>	\$ 233.65 ✗
2	Tailgate Licence Lamps @ R/L \$48.50 <i>new</i>	\$ 97.00 ✗
1	Tailgate Inner Lock <i>Dented</i>	\$ 597.35 -
1	Tailgate Lock Sticker <i>new</i>	\$ 41.50 ✗
1	Tailgate W/Strip <i>new</i>	\$ 341.66 -
2	Tailgate Damper @ R/L @ \$260.50 <i>new</i>	\$ 521.00 ✗
2	Tailgate Hinges @ R/L \$68.50 <i>new</i>	\$ 137.00 ✗
1	Tailgate Inner Board	\$ 581.60 ✗
Subtotal: \$ 11,982.88		12, 270.88

6378.13  
4746.09.

Vehicle No. : SLC4679H

**Special Nett Items:**

1 Set	Rear Reverse Sensor	250	\$	280.00	250
1 Set	Rear Reverse Camera	300	\$	450.00	+
1	Rear Number Plate		\$	60.00	+
1 Set	Tailgate Glass Sealant	m	\$	120.00	60
Subtotal:			\$	910.00	

**Labour Charges:**

To Checking Rear Electrical Wiring	\$	120.00	30
To Remove ,Refix Rear Windscreen	\$	220.00	120
To Remove,Refix Reverse Sensor	\$	80.00	50
To Remove,Refix R/interior Trims To Assit Repair	\$	180.00	60
To Remove and Replace Exhaust	\$	150.00	+
To Respray Undercoating	\$	120.00	40
To Respray Painting and etc	\$	1,800.00	750
Panel Beating, Cut, Weld, Remove and Replacing Above Parts	\$	1,800.00	800
Subtotal:		\$	4,470.00

**ESTIMATE PARTS AND LABOUR GRAND TOTAL**

**\$ 17,362.88 17,650.88**

Adrian Lj  
L/S 20/03/18.

05 days.

total: 6006.09  
L/S: 55K.

S.S/LC

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18005189/Avd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 12-04-2018	
		Code : EGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLS 7333B	Veh. Inspected	SLC 4679H
Policy No.		Coverage (\$)	0.00
Claim No.	SLS 7333B/SE/pl	Excess (\$)	0.00
Assign From	YEE PE LI	Assign Date	19/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA HARRIER PREMIUM	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZSU600077371	Colour	WHITE
Odometer	27917	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm
L/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	16/03/2018	Inspection Date	20/03/2018
Survey held at	JEC AUTOMOTIVE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 4679H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DEFORMED	1,481.50	1,481.50
1	REAR BUMPER SPONGE	CRACKED	160.20	160.20
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	485.60	-
2	REAR BUMPER SUPPORT BRACKET @\$68.50	NOT NECESSARY	137.00	-
2	REAR BUMPER SIDE RETAINERS-R/L @\$101.20	NECESSARY	202.40	202.40
1	REAR SMART KEYLESS SENSOR	NOT NECESSARY	230.50	-
2	REAR BUMPER REFLECTOR-R/L @\$96.80	NOT NECESSARY	193.60	-
1	REAR BUMPER DIFUSSER	DEFORMED	419.65	419.65
2	REAR LAMPS-R/L @\$481.60	NOT NECESSARY	963.20	-
1	REAR END PANEL	DENTED	881.65	881.65
1	REAR END PANEL GARNISH	NOT NECESSARY	381.60	-
1	REAR EXHAUST	NOT NECESSARY	516.50	-
1	TAILGATE GLASS MOULDING	NECESSARY	199.62	199.62
1	TAILGATE	DENTED	1,975.60	1,975.60
1	TAILGATE LOGO	NECESSARY	68.50	68.50
2	TAILGATE LAMPS R/L @\$414.20	NOT NECESSARY	828.40	-
1	TAILGATE SPOILER	NOT NECESSARY	596.60	-
1	TAILGATE OUTER OPENING SWITCH	NOT NECESSARY	233.65	-
2	TAILGATE LICENCE LAMPS-R/L @\$48.50	NOT NECESSARY	97.00	-
1	TAILGATE INNER LOCK	DAMAGED	597.35	597.35
1	TAILGATE LOCK STICKER	NOT NECESSARY	41.50	-
1	TAILGATE W/STRIP	NECESSARY	341.66	341.66
2	TAILGATE DAMPER-R/L @\$260.50	NOT NECESSARY	521.00	-
2	TAILGATE HINGES-R/L @\$68.50	NOT NECESSARY	137.00	-
1	TAILGATE INNER BOARD	NOT NECESSARY	581.60	-
	LESS 25% DISCOUNT		-	-1,582.03
			12,272.88	4,746.10
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	280.00	250.00
1	SET REAR REVERSE CAMERA (SN)	NOT NECESSARY	450.00	-

Report Ref No. CS/EGI18005189/Avd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	60.00	-
1	SET TAILGATE GLASS SEALANT (SN)	NECESSARY	120.00	60.00
			910.00	310.00
	<b>LABOUR</b>			
	TO CHECKING REAR ELECTRICAL WIRING.		120.00	30.00
	TO REMOVE,REFIX REAR WINDSCREEN.		220.00	120.00
	TO REMOVE,REFIX REVERSE SENSOR.		80.00	50.00
	TO REMOVE,REFIX R/INTERIOR TRIMS TO ASSIST REPAIR.		180.00	60.00
	TO REMOVE AND REPLACE EXHAUST.	NOT NECESSARY	150.00	-
	TO RESPRAY UNDERCOATING.		120.00	40.00
	TO RESPRAY PAINTING AND ETC.		1,800.00	750.00
	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS.		1,800.00	800.00
			4,470.00	1,850.00
	<b>GRAND TOTAL</b>		<b>17,652.88</b>	<b>6,906.10</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,500.00</b>

Report Ref No. CS/EG18005189/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.