

22/03/2003

ASS. REC. BY:

REF: CS/ICS 18005195/Atd3

Special Instruction:

Surveyor

Adrian

ASSIGNMENT (Office)

From (Person):

Janicee Goh

of

ECICS

Date/Time:

19/3/18 @ 5:01pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL 5581 B

Insured:

SLQ 2959P

at Workshop m/s

1st Autoworks

Tel:

6844 1985

of

23 Keki Bkt Ave 4 #04-01

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/03/18

CA / REV / REP. / REV 24 HRS

lwp

21/03/18 @ 12pm-2pm

H.O.D. Endorsement:

Date/Time: 11:16am @ 20/3/18

Person Contacted:

Suhaimi

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SL 5581 B - x
	SLQ 2959P - x.
	Part by Part \$5094.95 (Red: 8478.28; 620%)

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : **Yes** or **No**GIA / PR Seen: _____ Consistent? : **Yes** or **No**Est. Repairs: _____ days Res.: **Yes** or **No**Lum Sum: _____ % 3 Val.: **Yes** or **No****CA / REV / REP. / 24 HRS**Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: SL55818 Yr Regn: 2017 / Feb.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Chevrolet Orlando c.c. 1362Colour: Brown A/C: **Insured / Std / NI / NA**Sp. Reading: 17602 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: KL1YA7S89HK608156Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: **Nil** / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO** or Kumho

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 21/03/18Survey held at 1st AntworkDes. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** orRear O/SThe **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time _____ Action / Instruction _____

TP ECLCS

RECEIVED 30 APR 2018

Date/Time, File Pass to?

1) 30/4 Typist

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____) \$ + RS. SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)Report Format: TPLump Sum / I.B. (\$) 5094.95

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

350

10

360

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Monday, 19 March 2018 5:01 PM
To: suhaimi@firstautoworks.com.sg; assignments
Cc: ECICS Claims
Subject: RE: Accident involving SLL5581B against your insured SLQ2959P on 17/03/2018
Attachments: SAS2376034.PDF[1].pdf

Without Prejudice

Dear Suhaimi

Thank you for your email.
We will appoint LKK for the survey.

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Suhaimi [mailto:suhaimi@firstautoworks.com.sg]
Sent: Monday, 19 March, 2018 4:28 PM
To: ECICS Claims
Subject: Accident involving SLL5581B against your insured SLQ2959P on 17/03/2018

Dear Sir

We are instructed by Tang Sheng Fung Kelly to notify you of a road traffic accident on 17/03/2018 at about 2150 at Bishan St 11 To Braddell Rd involving our client's/customer's vehicle registration number SLL5581B and vehicle registration number SLQ2959P driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's/customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Thanks & Regards

Suhaimi Ong
Service Executive
1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4,
#04-01 (South Wing)
S'pore 415933
Tel : 6844 1985
Fax : 6844 5185

follow us on  facebook
follow us on  twitter
visit our website ecics.com.sg 

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CS/ICS18005195/Atd3		
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987		Date : 20-03-2018		
		Code : ICS		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 2959P	Veh. Inspected	SLL 5581B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	JANICE GOH	Assign Date	20/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/03/2018	Inspection Date		
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/03/2018 11:58
Date Of Accident	17/03/2018 21:50
Exact Location Of Accident	BISHAN ST 11 TO BRADDELL RD (SLIP RD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL5581B
Insured/Policyholder	
Name Of Registered Owner	TANG SHENG FUNG KELLY
NRIC No	S7931588E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96954254
Alternative Phone No	OFFICE-96954254

Vehicle Particulars

Manufacturer	CHEVROLET
Model	ORLANDO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800019529
Cover Note Number	

Driver

Name of Driver	LOUIE CHUN YU
NRIC No	S7770756E
Date Of Birth	03/01/1977
Occupation	INDOOR
Date Of Driving Pass	30/01/2007
Driving Experience	11 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-82887926
Fax Number	
Contact Number	
EMail Address	CYLOUIE1@GMAIL.COM

Address	BLK 130 PUNGGOL WALK #02-14
Postcode	828776
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : KELLY TANG GENDER: : FEMALE
Passenger 2	NAME: : LINUS LOUIE GENDER: : MALE
Passenger 3	NAME: : LEONARD LOUIE GENDER: : MALE
Passenger 4	NAME: : GENA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE WAS STATIONARY TO CHECK FOR INCOMING VEHICLE. SUDDENLY, VEHICLE B HIT ONTO MY VEHICLE REAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ2959P
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

my vehicle was stationary to check for incoming vehicle, suddenly vehicle B hit onto my vehicle rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

License Number: **S7770756E**

Name:
LOUIE CHUN YU
(LEI ZHENYU)

Date of Birth: **03 Jan 1977**
Valid Until: **30 Jan 2007**



 001475877H

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7770756E



Name

LOUIE CHUN YU
(LEI ZHENYU)

雷振宇

Race

CHINESE

Date of birth
03-01-1977

Sex

M

Country of birth
HONG KONG




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver, and other motor vehicles < 2500kg 30 Jan 2007

NP 428A



4024410

NRIC No. S7770756E



Date of issue
02-04-2007

APT BLK 130 PUNGGOL WALK #02-14
SINGAPORE 828776

NRIC No. S7770756E

Date 26/12/2016

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 21/3/2018

TPEICS
Denise

Reference: SLL5581B
CHEVROLET
ORLANDO
Make: 1.4AT TURBO

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLL5581B
CHASSIS NO.:KL1YA7589HK608156
ENGINE NO.:A14NET162660009

Name of insured :TANG SHENG FUNG KELLY
Date of accident.: 17/03/2018

Vehicle in. All parts 19.
Before Paint

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)	
1	1	REAR TAILGATE	\$ 1,404.00	✓
2	1	REAR TAILGATE EMBLEM	\$ 65.00	✓
3	1	CHEVROLET LETTERING	\$ 50.00	✓
4	1	ORLANDO LETTERING	\$ 40.00	✓
5	1	TURBO LETTERING	\$ 45.00	✓
6	1	RHR TAILGATE LAMP	\$ 263.00	x
7	1	REAR WINDSCREEN WITH MOLDING	\$ 780.00	x
8	1	REAR TAILGATE INNER TRIM	\$ 340.00	+
9	1	REAR TAILGATE WEATHERSTRIP	\$ 240.00	+
10	1	REAR TAIL LID LATCH	\$ 220.00	x
11	1	REAR TAIL LID STRIKER	\$ 80.00	x
12	1	REAR BUMPER STEP PLATE	\$ 160.25	✓
13	1	REAR BUMPER UPPER	\$ 1,467.00	✓
14	1	REAR BUMPER LOWER	\$ 540.00	✓
15	1	REAR BUMPER SILL PLATE(SILVER)	\$ 300.00	✓
16	1	REAR BUMPER TOWING COVER	\$ 75.00	✓
17	1	RHR BUMPER REFLECTOR	\$ 95.00	✓
18	1	REAR REVERSE LIGHT AND BRAKE LIGHT	\$ 401.00	x
19	1	RHR TAILLAMP	\$ 527.00	?

<u>20</u>	1	RHR FENDER PROTECTOR	<i>New</i>	\$ 150.00	✓
<u>21</u>	1	REAR BUMPER CENTRE GUIDE	<i>New</i>	\$ 120.00	✓
<u>22</u>	1	RHR BUMPER GUIDE, OTR	<i>New</i>	\$ 60.00	✓
<u>23</u>	1	LHR BUMPER GUIDE, OTR	<i>New</i>	\$ 60.00	✓
<u>24</u>	1	REAR BUMPER LEFT CENTRE GUIDE, INR	<i>New</i>	\$ 50.00	✓
<u>25</u>	1	REAR BUMPER RIGHT CENTRE GUIDE, INR	<i>New</i>	\$ 50.00	✓
<u>26</u>	1	REAR BUMPER ABSORBER	<i>Ref New</i>	\$ 190.00	✓
<u>27</u>	1	REAR BUMPER BEAM	<i>Ref New</i>	\$ 743.00	✓
<u>28</u>	1	REAR END PANEL TRIM	<i>Ref New</i>	\$ 125.00	✓
<u>29</u>	1	RHR FENDER INNER PLASTIC TRIM	<i>Ref New</i>	\$ 320.00	✓
<u>30</u>	1	REAR END PANEL OUTER	<i>Ref New</i>	\$ 680.00	✓
<u>31</u>	1	REAR END PANEL INNER	<i>Ref New</i>	\$ 470.00	✓

5258.25
3154.95

Parts Total: \$ 10,110.25
40% Less 10%: \$ 1,011.03
Total: \$ 9,099.23

Labour

Labour Description

No.

Price (SGD)

<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$220 PER DAY)	\$ 1,320.00	<i>740/860</i>
<u>2</u>	Carry out spray painting on accident affected area (\$200 Per panel)	\$ 1,200.00	<i>600</i>
<u>3</u>	To conduct anti rust of under carriage tuff coat	\$ 120.00	<i>✓</i>
<u>4</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 80.00	<i>30</i>
<u>5</u>	To remove and refix reverse sensor and conduct test	\$ 80.00	<i>60</i>
<u>6</u>	To remove and refix rear tail gate windscreen	\$ 180.00	<i>120</i>
<u>7</u>	To conduct transfer of parts from old tailgate to new tailgate	\$ 350.00	<i>100</i>
<u>8</u>	To conduct water leakage test after repairs of vehicle	\$ 50.00	<i>✓</i>

1350

Labour Total : \$ 3,380.00

Others

Other Description

No. Qty

Price (SGD)

1	1	Number plate with casement	<i>New</i>	\$ 45.00	<i>t</i>
2	10	Rear bumper upper clip	<i>New</i>	\$ 65.00	<i>30</i>

3	10	Rear bumper lower clip	<i>Nil</i>	\$ 65.00	30
4	8	Fender Protector clip	<i>Nil</i>	\$ 52.00	10
5	8	Fender Liner Clip	<i>Nil</i>	\$ 52.00	1
6	8	Rear end panel trim clip	<i>Nil</i>	\$ 52.00	X
7	12	Rear Tailage inner trim clip	<i>Nil</i>	\$ 78.00	X
8	10	Fender inner trim clips	<i>Nil</i>	\$ 65.00	X
9	1	Rear Windscreen Sealant	<i>Nil</i>	\$ 80.00	60
10	1	Reverse sensor(1 set)	<i>Damaged</i>	\$ 460.00	✓
11	1	Rear end panel insulation seal	<i>Not New</i>	\$ 80.00	7

590

Other Total: \$ 1,094.00

GRAND TOTAL: \$ 13,573.23

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Suhaimi

Service Executive
Suhaimi Ong
HP : 8298 8933 Fax:6844 5185

Adrian Li
P/P 21/03/18.

total: 5084.95

04 days

A-6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Autoworks

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

ECICS Limited
7 Temasek Boulevard
#10-03 Suntec Tower One
SINGAPORE 038987

GST Ref. No: 20-0000274-Z

Vehicle No: SLL5581B
Chassis No: KL1YA7589HK608156
Engine No: A14NET162660009

Invoice No:

Invoice Date:

DESCRIPTION			AMOUNT	SGD
Parts				
<u>1</u>	1	REAR TAILGATE	\$	1,404.00
<u>2</u>	1	REAR TAILGATE EMBLEM	\$	65.00
<u>3</u>	1	CHEVROLET LETTERING	\$	50.00
<u>4</u>	1	ORLANDO LETTERING	\$	40.00
<u>5</u>	1	TURBO LETTERING	\$	45.00
<u>6</u>	1	REAR BUMPER STEP PLATE	\$	160.25
<u>7</u>	1	REAR BUMPER UPPER	\$	1,467.00
<u>8</u>	1	REAR BUMPER LOWER	\$	540.00
<u>9</u>	1	REAR BUMPER SILL PLATE(SILVER)	\$	300.00
<u>10</u>	1	REAR BUMPER TOWING COVER	\$	75.00
<u>11</u>	1	RHR BUMPER REFLECTOR	\$	95.00
<u>12</u>	1	RHR TAILLAMP	\$	527.00
<u>13</u>	1	RHR FENDER PROTECTOR	\$	150.00
<u>14</u>	1	REAR BUMPER CENTRE GUIDE	\$	120.00
<u>15</u>	1	RHR BUMPER GUIDE, OTR	\$	60.00
<u>16</u>	1	LHR BUMPER GUIDE, OTR	\$	60.00
<u>17</u>	1	REAR BUMPER LEFT CENTRE GUIDE, INR	\$	50.00
<u>18</u>	1	REAR BUMPER RIGHT CENTRE GUIDE, INR	\$	50.00

Total: \$ 5,258.25
Less 40%: \$ 2,103.30
Parts Total : \$ 3,154.95

Labour

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$220 PER DAY)	\$ 440.00
2	Carry out spray painting on accident affected area (\$200 Per panel)	\$ 600.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
4	To remove and refix reverse sensor and conduct test	\$ 60.00
5	To remove and refix rear tail gate windscreen	\$ 120.00
6	To conduct transfer of parts from old tailgate to new tailgate	\$ 100.00

Labour Total : \$ 1,350.00

Other

No.	Other Description	Price (SGD)
1	10 Rear bumper upper clip	\$ 30.00
2	10 Rear bumper lower clip	\$ 30.00
3	8 Fender Protector clip	\$ 10.00
4	1 Rear Windscreen Sealant	\$ 60.00
5	1 Reverse sensor(1 set)	\$ 460.00

Other Total : \$ 590.00

Total : \$ 5,094.95
GST (7%) \$ 356.65
Grand Total: \$ 5,451.60

Yours Faithfully,



Suhaimi Ong

Suhaimi Ong

Service Advisor

Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1ST Autoworks Pte Ltd",
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18005195/ATD3N2

Date: 07/05/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLL5581B	Insured Vehicle No :	SLQ2959P
Date of Loss:	17/03/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL5581B	Engine No:	A14NET162660009
Make & Model:	CHEVROLET ORLANDO, 1.4 (A)	Chassis No:	KL1YA7589HK608156
Reg. Date:	28/02/2017 (Man. Year: 2016)	Odometer:	17602 km
Colour:	Brown		
Engine Capacity:	1362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,193.22	3,744.95	6,448.27	63.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,350.00	2,030.00	60.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,573.22	5,094.95	8,478.27	62.46
+ GST 7.00/7.00% (S\$)	950.13	356.65	593.48	62.46
Nett Amount (S\$)	14,523.35	5,451.60	9,071.75	62.46

INSPECTION

Date of Assignment:	19/03/2018	Inspected At:	1st Autoworks Pte Ltd (HQ)
Date Inspected:	21/03/2018		23 Kaki Bukit Ave 4, #04-01
			Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2018)
Parts: M1-MPV	CHEVROLET ORLANDO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLL5581B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,404.00 FL	*1,404.00 FL
2	1		*REAR TAILGATE EMBLEM	Necessary	65.00 FL	*65.00 FL
3	1		*CHEVROLET LETTERING	Necessary	50.00 FL	*50.00 FL
4	1		*ORLANDO LETTERING	Necessary	40.00 FL	*40.00 FL
5	1		*TURBO LETTERING	Necessary	45.00 FL	*45.00 FL
6	1		*RHR TAILGATE LAMP	Not Necessary	263.00 FL	*- FL
7	1		*REAR WINDSCREEN WITH MOLDING	Not Necessary	780.00 FL	*- FL
8	1		*REAR TAILGATE INNER TRIM	Not Necessary	340.00 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	240.00 FL	*- FL
10	1		*REAR TAIL LID LATCH	Not Necessary	220.00 FL	*- FL
11	1		*REAR TAIL LID STRIKER	Not Necessary	80.00 FL	*- FL
12	1		*REAR BUMPER STEP PLATE	Deformed	160.25 FL	*160.25 FL
13	1		*REAR BUMPER UPPER	Deformed	1,467.00 FL	*1,467.00 FL
14	1		*REAR BUMPER LOWER	Deformed	540.00 FL	*540.00 FL
15	1		*REAR BUMPER SILL PLATE (SILVER)	Deformed	300.00 FL	*300.00 FL
16	1		*REAR BUMPER TOWING COVER	Cut	75.00 FL	*75.00 FL
17	1		*RHR BUMPER REFLECTOR	Cracked	95.00 FL	*95.00 FL
18	1		*REAR REVERSE LIGHT AND BRAKE LIGHT	Not Necessary	401.00 FL	*- FL
19	1		*RHR TAILLAMP	Cracked	527.00 FL	*527.00 FL
20	1		*RHR FENDER PROTECTOR	Necessary	150.00 FL	*150.00 FL
21	1		*REAR BUMPER CENTRE GUIDE	Necessary	120.00 FL	*120.00 FL
22	1		*RHR BUMPER GUIDE,OTR	Necessary	60.00 FL	*60.00 FL
23	1		*LHR BUMPER GUIDE,OTR	Necessary	60.00 FL	*60.00 FL
24	1		*REAR BUMPER LEFT CENTRE GUIDE,INR	Necessary	50.00 FL	*50.00 FL
25	1		*REAR BUMPER RIGHT CENTRE GUIDE,INR	Necessary	50.00 FL	*50.00 FL
26	1		*REAR BUMPER ABSORBER	Not Necessary	190.00 FL	*- FL
27	1		*REAR BUMPER BEAM	Not Necessary	743.00 FL	*- FL
28	1		*REAR END PANEL TRIM	Not Necessary	125.00 FL	*- FL
29	1		*RHR FENDER INNER PLASTIC TRIM	Not Necessary	320.00 FL	*- FL
30	1		*REAR END PANEL OUTER	Repair	680.00 FL	*- FL
31	1		*REAR END PANEL INNER	Not Necessary	470.00 FL	*- FL
32	1		*NUMBER PLATE WITH CASEMENT	Not Necessary	45.00 FS	*- FS
33	10		*REAR BUMPER UPPER CLIP	Necessary	65.00 FS	*30.00 FS
34	10		*REAR BUMPER LOWER CLIP	Necessary	65.00 FS	*30.00 FS
35	8		*FENDER PROTECTOR CLIP	Necessary	52.00 FS	*10.00 FS
36	8		*FENDER LINER CLIP	Not Necessary	52.00 FS	*- FS
37	8		*REAR END PANEL TRIM CLIP	Not Necessary	52.00 FS	*- FS
38	12		*REAR TAILGATE INNER TRIM CLIP	Not Necessary	78.00 FS	*- FS
39	10		*FENDER INNER TRIM CLIPS	Not Necessary	65.00 FS	*- FS
40	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
41	1		*SET REVERSE SENSOR	Damaged	460.00 FS	*460.00 FS
42	1		*REAR END PANEL INSULATION SEAL	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,204.25 5,848.25

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/40.00% (S\$)					1,011.03	2,103.30
Total Parts (S\$)					10,193.22	3,744.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,320.00	440.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	1,200.00	600.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	120.00	-
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	80.00	30.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	80.00	60.00
6	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	180.00	120.00
7	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	350.00	100.00
8	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	50.00	-
Gross Labour Cost (\$\$)			3,380.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >