

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 059/IC/TCAC/CCR/2018
DATE : 16-MAR-2018

AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MR PHUA WEI ZHENG, JUSTIN
ADDRESS : BLK 807C CHOA CHU KANG AVENUE 1
#17-540
S(683807)
TELEPHONE NO : 94754274/96802438

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : AVIVA AGAINST AXA INSURANCE
VEHICLE NO : SLD5624D
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2273871A
CHASSIS NO : SJNFEAJ11U1652400
MILEAGE : 1 KM
DATE IN : 16/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 17/03/2018

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLD5624D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	60.00	
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	
3	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	
5	WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	
6	ZZ/001	RENEW REAR BUMPER,BRACKETS,REAR UPPER PANEL ETC PANELS & REPAIR	1000.00	
7	ZZ/002	RESRAY REAR BUMPER IN 2 TONE COLORS,REAR UPPER PANEL,BOTH REAR FENDERS ETC	1000.00	
8	ZZ/003	QC, RETUNE & CONSULT CHECK		
9	ZZ/004	COMPLIMENTARY WASH & VACUUM		
		TOTAL LABOUR CHARGES	2575.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLD5624D

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			360.00
2	WEATHER STRIP-BACK DOOR	90830-4EA0A	158.70		
3	ORNAMENT-BACK D	90892-4EA0A	87.00		
4	EMBLEM-REAR	90890-4EA0A	59.70		
5	PLATE-LUGGAGE	84992-4EA0A	63.50		
6	BRACKET-BUMPER RR RH	85220-4EA0A	35.90		
7	BRACKET-RR BUMPER LH	85221-4EA0A	35.90		
8	REINF-BUMPER RR	H5030-4EAMA	619.20		
9	ENERGY ABSORBER	85090-4EA0B	126.40		
10	FINISHER-REAR BUMPER	85071-4EA0A	16.80		
11	FASCIA-RR BUMPER	85022-4EA0H	717.00		
12	PANEL-REAR UPPER	69110-4EAMA	482.60		
13	LAMP COMB RR,LHR	26555-4EA5D	215.90		
14	COMB LAMP RHR	26550-4EA5C	288.60		
15	ORNAMENT ASSY RHR	26560-JJ90A	55.00		
16	ORNAMENT ASSY LHR	26565-JJ90A	55.00		
17	LAMP COMB RR,RH	26550-4EA0A	323.70		
18	LAMP COMB RR,LH	26555-4EA0A	323.70		
19	LAMP ASSY-LICENCE @ \$27.30 X 2	26510-3BB0A	54.60		
SUB TOTAL			3719.20	0.00	360.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			743.84	0.00	0.00
GRAND TOTAL			2975.36	0.00	360.00
OVERALL TOTAL			3335.36		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLD5624D

TOTAL LABOUR CHARGES	2575.00
TOTAL SPARE PARTS CHARGES	3335.36
GRAND TOTAL	5910.36 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.