

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0328/2018/GW
Date	:	15-Mar-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Lam Pek Ying
Address	:	3 Pasir Ris View Singapore 518586
Telephone	:	HP +65 91899940
Type of Claim	:	Own Damage Claim
Policy No.	:	2100468761-01000
Vehicle No	:	SLC 8775 L
Model Code	:	Audi A3 Sedan 1.4 TFSI
Model / Year	:	May-16
Engine No	:	CZC 540605
Chassis No	:	WAUZZZ8V5G1089776
Mileage	:	-
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	13-Mar-18
Place of Accident	:	3 Pasir Ris View

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 8775 L.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs rear door's multi-lock system and power window devices.	S/N \$ 280.00	✓
2	To dismantle and renew lhs rear door, transfer old fittings and align to position. Inspect B-pillar for damage. Reinstall all parts removed.	\$ 900.00 500 .	
3	To remove lhs front door panel trims , renew damaged trims and dismantle lhs wing mirror asy.	S/N \$ 600.00	✓
4	To respray lhs front and rear doors, and door hines.	\$ 1,700.00 1100	
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 3,672.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 8775 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT WINDOW SLOT SEAL-LH <i>Not in</i>	\$ 268.00	X
2	TRIM FOR PILLAR B-LH <i>Not in</i>	\$ 85.00	X
3	REAR DOOR-LH <i>Dented</i>	\$ 2,190.00	✓
4	REAR OUTER DOOR SEAL- LH <i>in</i>	\$ 139.00	✓
5	BONDING AGENT ?	\$ 43.00	?
6	REAR DOOR CATCH-LH ?	\$ 82.00	?
7	REAR DOOR HINGE-LH ?	\$ 73.00	?
8	REAR DOOR UPPER HINGE-LH ?	\$ 108.00	?
9	REAR DOOR LOWER HINGE-LH ?	\$ 72.00	?
10	REAR WINDOW SLOT SEAL-LH <i>Not in</i>	\$ 256.00	X
11	TRIM FOR PILLAR C-LH <i>Not in</i>	\$ 101.00	X
12	SUNDIRES ?	\$ 400.00	?
TOTAL SPARE PARTS		\$ 3,817.00	
TOTAL LABOUR CHARGES		\$ 3,672.00	
GRAND TOTAL		\$ 7,489.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 20/03/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant