



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/S-quo

19th March 2018

AIG

SJM 3015 B HYUNDAI AVANTE

SS

Spare Parts	1	Frt bonnet. <i>bt</i>
	1	Frt bonnet insulator <i>de</i>
	1	Set frt bonnet insulator clips. <i>ne</i>
	1	Frt bonnet lock. <i>ty</i>
	2	Frt headlights. <i>LH-wa, RHx</i>
	2	Frt headlight holders. <i>LH-ne, RH-p</i>
	1	Frt grille. <i>ant</i>
	1	Set frt grille clips. <i>ne</i>
	1	Left frt fender. <i>bt</i>
	1	Left frt fender inner cowling. <i>m</i>
	1	Set left frt fender inner cowling clips. <i>ne</i>
	1	Frt support panel. <i>de</i>
	1	Frt bumper. <i>de</i>
	1	Frt bumper reinforcement. <i>? photo</i>
	1	Set frt bumper clips. <i>ne</i>
	2	Frt bumper side retainers. <i>ne</i>
	1	Frt bumper foam. <i>?</i>
	1	Frt bumper low grille. <i>de</i>
	1	Rt frt fog light. <i>?</i>
	1	Frt lower engine cover. <i>?</i>
	1	Set frt lower engine cover clips. <i>?</i>
	1	Frt number plate. <i>bt</i>
	1	Coolant. <i>ne</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour

To knock, straighten frt inner panel, frt lower panel, frt side panel, rt frt wheel house, rt frt fender, left frt wheel house, frt chassis, renew frt bonnet, frt support panel, left frt fender, frt lights, frt grille, frt bumper and assembly.
To respray damaged parts.
To remove, replace air con system.

1200.00

700

1200.00

150.00 / 100

Bridgestone 185/65R15
KMHDU41BR9U660264
138106

Tanfer 97495749
21/3/18 @ 1750
6 days
surv @ lkkauto.com