

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2018)
Parts:	143	MERCEDES-BENZ E220 2.1 D CDI BlueEFFICIENCY (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHB6350U/19/03/2018 18:48	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>Refund</i>	20.00	0.00	*1,510.00 FL <i>✓</i>
2	1		*REAR BUMPER REINFORCEMENT <i>Refund</i>	20.00	0.00	*1,150.00 FL <i>✓</i>
3	1		*REAR BUMPER BRACKET LOWER LH <i>see</i>	20.00	0.00	*135.00 FL <i>X</i>
4	1		*REAR BUMPER BRACKET LOWER RH <i>see</i>	20.00	0.00	*135.00 FL <i>X</i>
5	1		*REAR BUMPER BRACKET TOP LH <i>see</i>	20.00	0.00	*125.00 FL <i>X</i>
6	1		*REAR BUMPER BRACKET TOP RH <i>see</i>	20.00	0.00	*125.00 FL <i>X</i>
7	1		*REAR BUMPER RETAINER MOUNTING LH <i>see</i>	20.00	0.00	*115.00 FL <i>X</i>
8	1		*REAR BUMPER RETAINER MOUNTING RH <i>see</i>	20.00	0.00	*115.00 FL <i>X</i>
9	1		*TAILLAMP ASSY LH <i>see</i>	20.00	0.00	*1,280.00 FL <i>✓</i>
10	1		*BOOTLID LAMP LH <i>see</i>	20.00	0.00	*655.00 FL <i>✓</i>
11	1		*REAR BUMPER REVERSE SENSOR <i>still</i>	0.00	0.00	*388.00 F <i>✓</i>

F=Franchise part. L=List/ItemDisc.

Sub Total (S\$)	5,733.00
- List Item Discount on L Items (S\$)	1,069.00
Total Parts (S\$)	4,664.00

ComfortDelGro Engineering Pte Ltd/SHB6350U/19/03/2018 18:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

3 day

photo

* 2 items? - parts taken

3,445
+? 1,150
4,595
- 202
3,676
+? 388 nett
4,064

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	350.00 300
2	SPRAY PAINTING CHARGE	New	200 250.00 180
3	WIRING CHARGE	New	50.00 30
4	TOWING CHARGE (KING DOLLY)	New	150.00
5	REMOVE/REFIX REVERSE SENSOR	New	120.00 60
Gross Labour Cost (S\$)			920.00

ComfortDelGro Engineering Pte Ltd/SHB6350U/19/03/2018 18:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Repair
Hp 900 600 68

3 days

W/S # 3,850

20/03/18 @ 1205

Resurvey after repair

COMFORTDELGRO ENGINEERING

Our Job Ref No 305126323

Date 28/03/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr RASUL

Vehicle Reg No. SHB6350U CTPL

17.03.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- GBC5864B

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

20%

\$3,850.00

\$3,850.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature: 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature: 

Name :

Date : 10/4/2018

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

LKR/MA L/Sun

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Tokio Marine

Singapore

L.Kee

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY
Policy No:
Vehicle Reg. No.: SHB6350U
Party At Fault: UNKNOWN

Ref. No:
Date of Loss: 17/03/2018
Driveable? YES

Make/Model: MERCEDES-BENZ E220, 2.1 D CDI
BLUEEFFICIENCY (A)
Vehicle Colour: WHITE
Engine No: 65192431502460
Odometer: 0 KM

Vehicle Reg. 25/10/2013
Date:
Gen Condition: GOOD
Chassis No: WDD2120022A758869

Paint Type:
List Item 20.00 %
Discount:
Total Loss? NO
Est. Duration of 4
Repair (day)

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	4,664.00
Miscellaneous Items	10.00
Labour	920.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	5,594.00
+ GST 7.00% (\$)	391.58
Nett Amount (\$)	5,985.58

This claim is handled by: LIM KWOK ENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Mar 2018)

Parts: 143 MERCEDES-BENZ E220 2.1 D CDI BlueEFFICIENCY (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHB6350U/19/03/2018 18:48

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*1,510.00 FL
2	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*1,150.00 FL
3	1		*REAR BUMPER BRACKET LOWER LH	20.00	0.00	*135.00 FL
4	1		*REAR BUMPER BRACKET LOWER RH	20.00	0.00	*135.00 FL
5	1		*REAR BUMPER BRACKET TOP LH	20.00	0.00	*125.00 FL
6	1		*REAR BUMPER BRACKET TOP RH	20.00	0.00	*125.00 FL
7	1		*REAR BUMPER RETAINER MOUNTING LH	20.00	0.00	*115.00 FL
8	1		*REAR BUMPER RETAINER MOUNTING RH	20.00	0.00	*115.00 FL
9	1		*TAILLAMP ASSY LH	20.00	0.00	*1,280.00 FL
10	1		*BOOTLID LAMP LH	20.00	0.00	*655.00 FL
11	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	*388.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,733.00
- List Item Discount on L Items (S\$)	1,069.00
Total Parts (S\$)	4,664.00

ComfortDelGro Engineering Pte Ltd/SHB6350U/19/03/2018 18:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (\$\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	350.00 ³⁰⁰
2	SPRAY PAINTING CHARGE	New	200 ²⁰⁰ 250.00 ¹⁸⁰
3	WIRING CHARGE	New	50.00 ³⁰
4	TOWING CHARGE (KING DOLLY)	New	150.00
5	REMOVE/REFIX REVERSE SENSOR	New	120.00 ⁶⁰
Gross Labour Cost (\$\$)			920.00

ComfortDelGro Engineering Pte Ltd/SHB6350U/19/03/2018 18:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair
Hp 90060068

3 days

4/5

20/03/18 @ 1205

Resurvey after repair

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Mar 2018 18:33 Sendback Est	19 Mar 2018 18:48 S\$5,594.00	20 Mar 2018 10:38 Edit Adj Rpt	S\$3,850.00 Edit Estimates	S\$3,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CTPL , Co. Reg. No.: 199303821R		
Main Claimant:	199303821R		
Vehicle Reg. No.:	SHB6350U	Date of Loss:	17/03/2018 16:00 - :59 [52 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1801452	Policy/Cover Note No.:	MW001724 (Comprehensive) Coverage: 09/03/2018 - 08/03/2019
Vehicle Reg. No. (Insured):	GBC5864B	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 29/03/2018]		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHB6350U (M1801452)
[GBC5864B]

TP

199303821R

Mar 17 2018 4:00PM

[CTPL]

ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	19/03/18 18:48	Repairer Estimates		Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	20/03/18 10:40	Accident Statement From: SC - Reg. No: GBC5864B, Claimant: C & C RENOVATION PTE. LTD.		Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/04/18 11:01	General View		Load JPG	☒
2	11/04/18 11:01	General View		Load JPG	☒
3	11/04/18 11:01	General View		Load JPG	☒
4	11/04/18 11:01	General View		Load JPG	☒
5	11/04/18 11:01	General View		Load JPG	☒
6	11/04/18 11:01	General View		Load JPG	☒
7	11/04/18 11:01	General View		Load JPG	☒
8	11/04/18 11:01	General View		Load JPG	☒
9	11/04/18 11:01	General View		Load JPG	☒
10	11/04/18 11:01	General View		Load JPG	☒
11	11/04/18 11:01	General View		Load JPG	☒
12	11/04/18 11:01	General View		Load JPG	☒
13	11/04/18 11:01	General View		Load JPG	☒
14	11/04/18 11:01	General View		Load JPG	☒
15	11/04/18 11:01	General View		Load JPG	☒
16	11/04/18 11:01	General View		Load JPG	☒
17	11/04/18 11:01	General View		Load JPG	☒
18	11/04/18 11:01	General View		Load JPG	☒
19	11/04/18 11:01	General View		Load JPG	☒
20	11/04/18 11:01	General View		Load JPG	☒
21	11/04/18 11:01	General View		Load JPG	☒
22	11/04/18 11:05	Reinspection Photo		Load JPG	☒
23	11/04/18 11:05	Reinspection Photo		Load JPG	☒
24	11/04/18 11:05	Reinspection Photo		Load JPG	☒
25	11/04/18 11:05	Reinspection Photo		Load JPG	☒
26	11/04/18 11:05	Reinspection Photo		Load JPG	☒
27	11/04/18 11:05	Reinspection Photo		Load JPG	☒
28	11/04/18 11:05	Reinspection Photo		Load JPG	☒
29	11/04/18 11:05	Reinspection Photo		Load JPG	☒
30	11/04/18 11:05	Reinspection Photo		Load JPG	☒
31	11/04/18 11:05	Reinspection Photo		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	19/03/18 18:56	E-filed GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TM18005233/R1TBE2

Date: 16/04/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MW001724
Claimant Vehicle No :	SHB6350U	Insured Vehicle No :	GBC5864B
Date of Loss:	17/03/2018	Nature of Claim:	TP
		Claim No:	M1801452

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB6350U		
Make & Model:	MERCEDES-BENZ E220, 2.1 D CDI BlueEFFICIENCY (A)	Engine No:	65192431502797
Reg. Date:	25/10/2013 (Man. Year: 2013)	Chassis No:	WDD2120022A758869
Colour:	White	Odometer:	753290 km
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,664.00	4,064.00	600.00	12.86
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	920.00	740.00	180.00	19.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,594.00	4,814.00	780.00	13.94
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	5,594.00	3,850.00	1,744.00	31.18
+ GST 7.00/7.00% (S\$)	391.58	269.50	122.08	31.18
Nett Amount (S\$)	5,985.58	4,119.50	1,866.08	31.18

INSPECTION

Date of Assignment:	20/03/2018 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	20/03/2018 Inspected At:	59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2018)
Parts:	143	MERCEDES-BENZ E220 2.1 D CDI BlueEFFICIENCY (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB6350U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,510.00 FL	*1,510.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	1,150.00 FL	*1,150.00 FL
3	1		*REAR BUMPER BRACKET LOWER LH	Serviceable	135.00 FL	*- FL
4	1		*REAR BUMPER BRACKET LOWER RH	Serviceable	135.00 FL	*- FL
5	1		*REAR BUMPER BRACKET TOP LH	Serviceable	125.00 FL	*- FL
6	1		*REAR BUMPER BRACKET TOP RH	Serviceable	125.00 FL	*- FL
7	1		*REAR BUMPER RETAINER MOUNTING LH	Serviceable	115.00 FL	*- FL
8	1		*REAR BUMPER RETAINER MOUNTING RH	Serviceable	115.00 FL	*- FL
9	1		*TAILLAMP ASSY LH	Cracked	1,280.00 FL	*1,280.00 FL
10	1		*BOOTLID LAMP LH	Scratched	655.00 FL	*655.00 FL
11	1		*REAR BUMPER REVERSE SENSOR	Shorted	388.00 F	*388.00 F
					Sub Total (\$\$)	5,733.00 4,983.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,069.00 919.00
					Total Parts (\$\$)	4,664.00 4,064.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	300.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
3	WIRING CHARGE	New	50.00	30.00
4	TOWING CHARGE (KING DOLLY)	New	150.00	150.00
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	60.00
Gross Labour Cost (S\$)			920.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >