

ASS. REC. BY:

REF: CS/MSA18005240/R19d3^{N2}

Special Instruction:

Surveyor: Raisul ASSIGNMENT (Office)

From (Person): Menimen Elaine Ngu of MSIG Date/Time: 20/3/18 @ 2.43pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFA 2882G Insured: SKS 9830G

at Workshop m/s Performance Motors Tel: 6319 0174

of 303 Alexandra Road

Policy No: MSD/VPCP/17-001130-00 Claim No: MSC/V/18-000410

Sum Insured: Excess:

Make of Veh: D.O.A. 19/3/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 4:08pm @ 20/3/18 Person Contacted: Caroline Vehicle IN/OUT OUT

Date/Time	Action/Instruction (✓) Estimate
	SFA 2882G-X
	SKS 9830G-X
04/4/18 @ 11:53am	revised to Elaine Ngu via Menimen.
29/5/18 @ 11:16am	Plan confirmed with Caroline final fig \$3660, 4 days by email. (Red \$ 6441.65, 64%)

Surveys *Person*

REF:

2969c

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SFA 2882G Yr Regn: 2017 OCT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 520D C.C. 1995

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 06504 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAJC320409868713

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45R18
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI / TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19/03/18 D.O.I. 02/04/18

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time	Action / Instruction

Monty
25/5/2018

RECEIVED 28 MAY 2018

Date/Time, File Pass to? : Preli. Report

11/28/18 *Amara* : Final Report

Date/Time, File Return to? _____

Days Of Repair: 4

Resurvey No. of Trip: _____

Report Format: WEB-TR

Lump Sum / I.B.I. (\$) 3660

- Add Fee:
- : Site Insp (\$)
 - : Interview (\$)
 - : Tech. Invs (\$)
 - : Weekend (\$)

Survey Fee:	<u>300</u>
Transportation:	<u>10</u>
S + RS, SI	
Photos	
Others	
TOTAL	<u>310</u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18005240/R1qd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 21-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 9830G	Veh. Inspected	SFA 2882G
Policy No.	MSD/VPCP/17-001130-00	Coverage (\$)	0.00
Claim No.	MSCV/18-000410	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	21/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/03/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2018		20 Mar 2018 14:43 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD , Co. Reg. No.: 199400399N		
Main Claimant:	TOO KAH JOO , ID: S7322969C		
Vehicle Reg. No.:	SFA2882G	Date of Loss:	19/03/2018 07:00 - :59
Claim Type:	TP / MSC/V/18-000410	Policy/Cover Note No.:	MSD/VPCP/17-001130-00 (Comprehensive) Coverage: 19/05/2017 - 18/05/2018
Vehicle Reg. No. (Insured):	SKS9830G	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/03/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 25 May 2018 11:51 AM
To: PBSP; Rasul (LKKAuto); SUR
Subject: RE: FINAL REPORT / SFA2882G

Dear Caroline,

Confirm final fig \$3,660.00 before GST and 4 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Thursday, 24 May 2018 5:33 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SFA2882G

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 3,660.00

Total Parts :

Total Labour & Parts : 3,660.00

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 04 Apr 2018

Preliminary Advice

Insured Vehicle No	: SKS9830G	Accident Date	: 19/03/2018
TP Vehicle No	: SFA2882G	Assignment Date	: 20/03/2018
Make	: BMW 520D	Est. Duration of Repair	: 5.00
Date of Inspection	: 02/04/2018		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,101.65
Revised Amount	:S\$	3,660.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,660.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/03/2018 12:41
Date Of Accident	19/03/2018 07:10
Exact Location Of Accident	JOO CHIAT RD JUNCTION NEAR MARINE PARADE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFA2882G
Insured/Policyholder	
Name Of Registered Owner	TOO KAH JOO
NRIC No	S7322969C
Email Address	JOETOO@LIVE.COM
Mobile Phone No	(LOCAL) +65-91867577
Alternative Phone No	OFFICE-86113085

Vehicle Particulars

Manufacturer	BMW
Model	520D G30
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	NOTAVAIL
Cover Note Number	

Driver

Name of Driver	TOO KAH JOO
NRIC No	S7322969C
Date Of Birth	11/06/1973
Occupation	INDOOR
Date Of Driving Pass	07/02/1991
Driving Experience	27 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91867577
Fax Number	
Contact Number	OFFICE-86113085
EMail Address	JOETOO@LIVE.COM

Address	11 JOO CHIAT LANE #04-03
Postcode	428127
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKS9830G
Vehicle Make/Model/Colour	AUDI WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHRISTINA
NRIC/Passport Number	
Contact Number	93386776
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 17/3/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Name: Inthiran A/L Thurasamy
303 Alexandra Road
Singapore 159941
NRIC/Photo: [Redacted]

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Joo Chiat Rd, towards East Coast Road, when a vehicle, SKS9830G, ahead of me that came to a stop, decided to make an illegal U-turn.


While passing the vehicle (SKS9830G) on its right-side, the vehicle, without any indication, decided to execute the U-turn. Failing to notice my vehicle, the right-front end of the vehicle hit onto the left-rear end of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Signature: 
 Date & Time: 19/3/18

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Inthira A/L. Thurasamy
 Reporting Performance Motors (S) Pte. Ltd.
 303 Alexandra Road
 Name: Darby Performance Centre
 H2IC/EN NO. Singapore 159941

29-03 @ 9.00am
Survey & repair

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64749770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796801 (AfterSales)
64796824 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

20 MAR 2018

Estimate No. : b1 46288	Page No. : 1 of 2
Date Estimated : 20/03/2018	
Prepared By : Inthiran A/L Thurasamy	

<p>- ESTIMATE REPAIR FOR - Too Kah Joo (Tu Jiayu) 11 Joo Chiat Lane #04-03 Singapore 428127</p>	<p>- ACCOUNT - 66 MSIG Insurance (S) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807</p>
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA2882G	G868713	30/10/2017	520D	0

DESCRIPTION	VALUE
To replace rear bumper, repair rear left fender and repair rear left door. <i>X</i>	1700 3400.00
Painting rear bumper, rear left fender, rear left door and roof frame. <i>X</i>	1730 3256.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To replace tyre and wheel rim including balancing. (1x).	11 X 94.00
To check steering geometry and conduct wheel alignment according to BMW specification (1X)	11 X 531.00
Sundries.	rec 80.00
Total Labour 1:	7,538.00

DESCRIPTION	QTY	PRIC	VALUE
LIGHT ALLOY RIM 8JX18 W SPK 632	1	961.75	svl X 961.75
REAR BUMPER LH SIDE GUIDE	1	57.05	svl X 57.05
REAR BUMPER PANEL PRIMED (PDC/PMA)	1	1,481.90	R 1,481.90
SET MOUNTING PMA SENSOR	1	62.95	svl X 3 62.95
Total Parts :			2,563.65

Claims / Direct Settlement

Regn No. _____ Claim No. _____

Date Time 02/04/18 @ 1410 Excess \$5

Surveyor's Name Rafael Sign _____

Surveyor's Tel 90060618 Authorised Yes / No _____

Arrived Date _____ Time _____

REPAIR PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 4-5 days

[Handwritten Signature]
4/4/18

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46288	Page No. : 2 of 2
Date Estimated : 20/03/2018	
Prepared By : Inthiran A/L Thurasamy	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA2882G	G868713	30/10/2017	520D	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour 1	:		7,538.00
Parts	:		2,563.65
Labour 2	:		0.00
Excess	:		0.00
Total GST @ 7%	:		707.12
Grand Total	:		10,808.77

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

101 21.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401509W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46288
Date Estimated : 20/03/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Too Kah Joo (Tu Jiayu)
11 Joo Chiat Lane
#04-03

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 428127

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE		
SFA2882G	G868713	30/10/2017	520D	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To make good the rear bumper, rear LH fender include removing attachments to facilitate repairs and knocking out dents caused by the accident	1700.00		1,700.00			
To spray paint rear bumper and rear LH fender	1730.00		1,730.00			
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00			
Sundries.	80.00		80.00			
DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT		

SUPPLEMENTARY ITEMS

Total Labour :	3,660.00
Total Parts :	
Total Labour & Parts :	3,660.00
Deduction for Excess :	
Total Repair Costs less Excess:	3,660.00
GST @7%:	256.20
Grand Total :	3,916.20

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005240/R1QD3N2

Date: 30/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCP/17-001130-00	Claim No:	MSCN/18-000410
Claimant Vehicle No :	SFA2882G	Insured Vehicle No :	SKS9830G		
Date of Loss:	19/03/2018	Nature of Claim:	TP		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFA2882G	Engine No:	66919999B47D20A
Make & Model:	BMW 520D, 2.0 M SPORT (A)	Chassis No:	WBAJC32040G868713
Reg. Date:	30/10/2017 (Man. Year: 2017)	Odometer:	6504 km
Colour:	Blue		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,643.65	80.00	2,563.65	96.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,458.00	3,580.00	3,878.00	52.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,101.65	3,660.00	6,441.65	63.77
+ GST 7.00/7.00% (S\$)	707.12	256.20	450.92	63.77
Nett Amount (S\$)	10,808.77	3,916.20	6,892.57	63.77

INSPECTION

Date of Assignment:	20/03/2018		
Date Inspected:	02/04/2018	Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2018)
Parts: 143	BMW 520D 2.0 M SPORT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFA2882G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*LIGHT ALLOY RIM 8JX18 W SPK 632	Serviceable	961.75 FS	*- FS
3	1		*REAR BUMPER LH SIDE GUIDE	Serviceable	57.05 FS	*- FS
4	1		*REAR BUMPER PANEL PRIMED (PDC/PMA)	Repair	1,481.90 FS	*- FS
5	1		*SET MOUNTING PMA SENSOR	Serviceable	62.95 FS	*- FS
Total Parts (S\$)					2,643.65	80.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER,REPAIR REAR LEFT FENDER AND REPAIR REAR LEFT DOOR	New	3,400.00	1,700.00
2	PAINTING REAR BUMPER,REAR LEFT FENDER,REAR LEFT DOOR AND ROOF FRAME	New	3,256.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1X)	New	94.00	-
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION (1X)	New	531.00	-
Gross Labour Cost (\$\$)			7,458.00	3,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >