

# FIRST AUTOWORKS

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

## Repair Estimate

Date : 16/3/2018

Reference: SKX 6908K

Make: CHEVROLET  
ORLANDO

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SKX 6908K

CHASSIS NO.: KL1YA7589GK318006

ENGINE NO.: A14NET152770387

Name of insured : Yuhari bin Musa

Date of accident.: 12/03/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

### Parts

No.	Qty	Part Description	Price (SGD)
1	1	REAR BUMPER STEP PLATE	DD 160.00
2	1	REAR BUMPER UPPER	DD/DC 1730.00
3	1	REAR BUMPER LOWER	Dis 760.00
4	1	REAR BUMPER SILL PLATE(SILVER)	Bul 390.00
5	1	REAR BUMPER TOWING COVER	DC 25.00
6	1	LHR BUMPER REFLECTOR	AN 65.00
7	1	RHR BUMPER REFLECTOR	AN 65.00
8	1	REAR REVERSE LIGHT AND BRAKE LIGHT	320.00 ?
9	1	REVERSE SENSOR WIRING HARNESS	325.00 ?
10	1	REAR TAILGATE	Bul/ DD 1850.00
11	1	REAR TAILGATE CHROME HANDLE	11 290.00
12	1	CHEVROLET LETTERING	26 50.00
13	1	ORLANDO LETTERING	26 40.00
14	1	LS LETTERING	26 30.00
15	1	CHEVROLET EMBLEM	26 120.00
16	1	LHR TAILLAMP	11 729.00
17	1	RHR TAILLAMP	11 729.00
18	1	LHR TAILGATE LAMP	11 330.00
19	1	LHR TAILLAMP PANEL	11 180.00
20	1	RHR TAILGATE LAMP	11 330.00
21	1	RHR TAILLAMP PANEL	11 180.00
22	1	REAR WINDSCREEN	11 498.00
23	1	REAR WINDSCREEN MOLDING	26 80.00
24	1	REAR TAILGATE WEATHERSTRIP	11 240.00
25	1	REAR WIPER ARM	11 65.00
26	1	REAR WIPER BLADE SET	11 57.00
27	1	REAR WIPER MOTOR	11 430.00
28	1	REAR TAILGATE INNER TRIM	11 290.00
29	1	REAR TAILGATE INNER LH TRIM	11 150.00
30	1	REAR TAILGATE INNER RH TRIM	11 150.00
31	1	REAR TAIL LID LATCH	11 220.00

not actual  
date  
take photo before  
repairing.  
21/3/18  
4 day.

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

<u>32</u>	1	REAR TAIL LID STRIKER	11	80.00	X
<u>33</u>	1	REAR END PANEL	1	770.00	X
<u>34</u>	1	REAR END PANEL TRIM	11	125.00	X
<u>35</u>	1	REAR FLOOR BOARD	11	490.00	X
<u>36</u>	1	REAR BUMPER CENTRE GUIDE		50.00	?
<u>37</u>	1	RHR BUMPER GUIDE, OTR		40.00	?
<u>38</u>	1	LHR BUMPER GUIDE, OTR		40.00	?
<u>39</u>	1	REAR BUMPER LEFT CENTRE GUIDE, INR		45.00	?
<u>40</u>	1	REAR BUMPER RIGHT CENTRE GUIDE, INR		45.00	?
<u>41</u>	1	REAR BUMPER ABSORBER		120.00	?
<u>42</u>	1	REAR BUMPER BEAM		860.00	?

Parts Total: 13543.00

Less 10%: 1354.30

Total : 12188.70

#### Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
<u>1</u>	To dismantle / renew the accident damaged portion, to panel 510 beating, reshape, straighten, orientate and align repair / replacement parts.	2800.00 1100
<u>2</u>	Carry out spray painting on accident affected area 450	2280.00 1350
<u>3</u>	To conduct anti rust of under carriage tuff coat	120.00 50
<u>4</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	80.00 30
<u>5</u>	To remove and refix reverse sensor and conduct test	180.00 50
<u>6</u>	To remove and refix reverse camera and conduct test	180.00 50
<u>7</u>	To conduct transfer of parts from old tailgate to new tailgate	11 350.00 X
<u>8</u>	To conduct water leakage test after repairs of vehicle	11 30.00 X
<u>9</u>	To remove and refix rear tail gate windscreen	180.00 120

Labour Total : 6200.00

#### Others

<u>No.</u>	<u>Qty</u>	<u>Other Description</u>	<u>Price (SGD)</u>
		<u>Rear portion</u>	
1	1	Rear number plate	11 45.00 X
2	10	Rear bumper clip	11 65.00 /
3	1	Rear Windscreen Sealant	11 80.00 40
4	12	Rear Tailgate inner trim clip	11 78.00 X
5	8	Rear end panel trim clip	11 52.00 X
6	1	Rear reverse camera	11 350.00 X

- |   |   |                                |
|---|---|--------------------------------|
| 7 | 1 | Reverse sensor(1 set)          |
| 8 | 1 | Rear end panel insulation seal |
| 9 | 1 | Turbo Logo                     |

<i>stuck</i>	460.00	<i>200</i>
<i>17</i>	80.00	<i>X</i>
<i>all</i>	30.00	<i>✓</i>

Other Total: 1240.00

---

Total :	\$19,628.70
Gst (7%) :	\$1,374.01
<b>GRAND TOTAL:</b>	<b>\$21,002.71</b>

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully




---

Service Adviser  
 Ronnie Tan  
 HP : 8298 8933 Fax:6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: