

## SMRT Accident Vehicle Repair Estimates

IV

G117

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5189B  
 Ref. No : TAX/03/18/2090  
 Reg. Date : 10/10/2017  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS4  
 Name of Driver : PANG CHEEN TECK  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 17/03/2018 12:25:00 PM  
 Accident Reported Date / Time : 19/03/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024095099  
 Special Instruction to ARC,if any :  
 DROVE IN / SHB6363H (COMFORT) - III  
 Prepared Date : 19/03/2018 09:06:11 AM



Sebastian.  
21/3/18.

- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU403572816

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,476.00	0.00
Total Material Charges	: 3,756.21	3,756.21
Other Charges	: 480.00	0.00
<b>TOTAL</b>	<b>: 6,726.21</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 6.00	<del>0.00</del>
Prepared / Adjusted By	:	3 days
Arc / Surveyor Sign Off Date	: 19/03/2018 02:22:34 PM	01/01/1900 12:00:00 AM

F

Prepared / Adjusted Date :

Remarks :

Prepared Date : 19/03/2018 02:20:21 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :  
Quotation Date : Invoice Date :  
Invoice Amount : Prepared Date :

Section 2 - Details of Repair Estimates

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00	<del>0.00</del> 400
<b>Total Labour</b>	<b>1,014.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	<del>0.00</del> 200
TO RESPRAY BUMPER BEAM	180.00	<del>0.00</del> ?
TO RESPRAY TAIL GATE	378.00	0.00 X
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	<del>0.00</del> 100
TO RESPRAY REAR PANEL	180.00	0.00 ?
TO RESPRAY FILLER RR BUMPER LH	180.00	<del>0.00</del> 50
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,476.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	<del>0.00</del> 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	<del>0.00</del> 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>480.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace ✓ CNK	No
52161160 10			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace ✓ NEC	No
52566479 00			FILLER, RR BUMPER, LH	1	119.90	25.00	89.92	Replace	Replace ✓ TN	No
52023470 30			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace ?	No
52462470 30			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Replace ?	No
52462470 20			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Replace ?	No
52462470 10			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Replace ?	No
52191470 30			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace ?	No
52592470 40			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Replace ?	No
52576470 40			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace ?	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ?	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓ NEC	No
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace ✓ Defoam	No
52461470 10			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace ?	No
58399470 30			COVER, REAR FLOOR UNDER, LH	1	234.30	25.00	175.72	Replace	Replace ?	No
67005474 40			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace X	No
76801471 10A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace R	No
75441470 90			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓ NEC	No
75442471 30			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓ NEC	No
75403480 10			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace ✓ NEC	No
	COMMO		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
	N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No
58307470 30			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace ?	No
	COMMO	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ?	No
	N									
<b>TOTAL MATERIALS</b>								<b>3,756.25</b>	<b>3,756.21</b>	
<b>TOTAL MATERIALS(Discounted)</b>							<b>3,756.21</b>	<b>3,756.21</b>		

Added Spare Parts / Material Usage After Surveyor Signed off

Number	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LI Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>								