From: Pegasus Engineering [mailto:claims2@pegasusengrg.com.sg] Sent: Thursday, 22 March 2018 4:06 PM To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com >
Subject: Fwd: Accident Inlv SLS4761T & SLQ4449G on 20/03/2018
Hi Hsiao Tong,
We refer to below email.
Kindly advise liability.
Thanks
Sebastian
Forwarded message
From: Pegasus Engineering < <u>claims2@pegasusengrg.com.sg</u> >
Date: Thu, Mar 22, 2018 at 2:32 PM
Subject: Fwd: Accident Inlv SLS4761T & SLQ4449G on 20/03/2018 To: jaskhine@lkkauto.com
Hi Jas,
We refer to below email.
Kindly advise liability.
Thanks
Sebastian
Forwarded message
From: Pegasus Engineering < <u>claims2@pegasusengrg.com.sg</u> > Date: Wed, Mar 21, 2018 at 10:03 AM
Subject: Accident Inly SLS4761T & SLQ4449G on 20/03/2018 To: vicalpeh@lkkauto.com

AUTHORIZATION TO ACT

TO: PEGASUS	S ENGINEERING & TRADING PTE LTD
FROM: HIRER	OF VEHICLE NUMBER _SS 47617
ACCIDENT IN	IVOLVING SLOH449G
ALONG/AT	Geylang lor 22 @ 2010312018
	norize you to act on my behalf in pursuance of my claim for loss of rental /
5 0	rve as the 'AUTHORITY TO ACT'.
	by authorize all agreed settlement payment be made in favour to PEGASUS
Name	: HANG KAI KIRT
NRIC	: S1701009C
Address	: BIR 255 ON MO 1010 QUE 4 \$10-119 (2056)
Contact	: 810039726
Date	: _ 36103ha8
Signature	
6	illi
Hirer	

Without Prejudice to any claim for personal injury

RELEASE VOUCHER (AIG Asia Pacific - Express Third Party Claim)

"We/l, PEGASUS ENGINEERING & TRADING PTE LTD ("the workshop") hereby confirm that we/l have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$6,576.84 (Repair Cost), S\$1,279.60 (Loss of Use/Rental), S\$7.45 (Disbursement) for vehicle no. SLS 4761T that was damaged pursuant to the accident which occurred on 20/03/2018 (date) along GEYLANG LOR 22 (location) involving vehicle no/s SLO 4449G. This is pursuant to the inspection conducted on 21/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GRAB RENTALS PTE LTD (the third party claimant") of vehicle no. SLS 4761T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLS 4761T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this ______ (day) of ______ (month) 20 _____ (year)

| Company | Compa



GST / ROC Company No:

201101753C

Third Party Insurer: Insured's Veh No:

NTUC SLQ4449G

Date of accident :

20/03/2018

Tax Invoice No.:

AR/IV18/04-1011

Invoice Date:

09/04/2018

Estimate To Repair

Singapore 573960

Grab Rentals Pte Ltd

#01-08 Midview City

18 Sin Ming Lane

TOYOTA PRIUS

Vehicle No:

SLS4761T

Chassis No:

S/NO	QUANTITY	DESCRIPTION	Pages: 1 of 1
3/110	QUANTITY	SPARE PARTS	AWIOONI
1	1PC	REAR GATE	\$922.50
2	1PC	REAR GATE CENTRE LOGO	\$43.80
3	1PC	REAR GATE "PRIUS" PLATE	\$49.0
4	1PC	REAR GATE "HYBRID" PLATE	\$51.0
5	1PC	REAR GATE LOCK	\$47.70
6	1PC	REAR GATE INNER RUBBER	\$340.80
7	1PC	REAR WINDSCREEN MOULDING (TOP)	\$62.80
8	1PC	REAR GATE OUTER GARNISH	\$866.50
9	1PC	REAR GATE GLASS MOULDING (LOWER)	\$69.10
10	8PC	REAR GATE INNER TRIM BOARD CLIPS @\$8.40	\$67.20
11	1PC	REAR BUMPER TOP	\$464.00
12	2 PC	REAR BUMPER RETAINER @\$112.7	\$112.70
13	10PC	REAR BUMPER CLIPS @\$5.50	\$55.00
14	1PC	REAR BUMPER REINFORCEMENT	\$349.00
15	1PC	REAR BUMPER (LOWER)	\$552.80
16	1PC	REAR CORNER BUMPER RH	\$125.30
17	1 PC	REAR END PANEL TOP GARNISH	\$190.00
18	1PC	REAR UNDER TOWING COVER	\$65.50
19	1PC	REAR FLOOR PANEL UNDER COVER	\$197.10
20	1 PC	REAR UDER COVER RH	\$190.20
			\$4,822.10
		LESS 25%	\$1,205.53
			\$3,616.58
		MISC ITEMS	
19	1 PC	REAR WINDSCREEN GUM	\$40.00
20	1PC	REAR GATE GLASS GUM	\$40.00
21	1PC	REVERSE SENSOR	\$200.00
		Total	\$280.00
		LABOUR & MISC. CHARGES	
1	1	WIRE CHECKING	\$30.00
2		REMOVE & REFIX REAR WINDSCREEN	\$120.00

If you have enquiries concerning this invoice, please contact Mr. Gary / Mr. Frankie at Tel: (65) 8338 8418 Mailing Address: 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

E-mail: claims2@pegasusengrg.com.sg



Grab Rentals Pte Ltd 18 Sin Ming Lane #01-08 Midview City Singapore 573960

GST / ROC Company No:

Third Party Insurer: NTUC Insured's Veh No: SLQ4449G

Date of accident : 20/03/2018

Tax Invoice No.: AR/IV18/04-1011

Invoice Date: 09/04/2018

201101753C

Estimate To Repair

TOYOTA PRIUS

Vehicle No: Chassis No .

SLS4761T

		Pages :	1 of 1
S/NO	QUANTITY	DESCRIPTION	AMOUNT
3		REMOVE & REFIX REAR GATE GLASS (LOWER)	\$100.00
4		R&R REAR BOOT UPHOLSTERY TO FACILITATE TO REPAIR	\$80.00
5		CAVITY PROTECTION ON ALL AFFECTED AREAS	\$60.00
6		REMOVE & REFIX EXHAUST BOX	\$60.00
7		LABOUR CHARGE	\$800.00
8		SPRAY PAINTING	\$1,000.00
		Total	\$2,250.00
		Sub Total	\$6,146.58
		GST (7.00%)	\$430.26
		Total	\$6,576.84

Cheques should be made payable to PEGASUS ENGINEERING & TRADING PTE LTD

PEGASUS ENGINEERING & TRADING PTE LTD

Authorised Signature (Company Stamp)

If you have enquiries concerning this invoice, please contact Mr. Gary / Mr. Frankie at Tel: (65) 8338 8418

Mailing Address: 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

E-mail: claims2@pegasusengrg.com.sg



Our Ref: GR-ACC-2017-02

01 June 2017

Pagasus Engineering & Trading Pte Ltd No. 51 Defu Lane 10 Singapore 539216 Mailing Address 18 Sin Ming Lane, #01-08 Midview City, Singapore 573960 Co. No. 201617200G

To whom it may concern,

Re: Vehicle Rental Rates for Loss of Rental Claims.

With regards to the above subject matter, we are pleased to inform you our Grab Rental rate for our various vehicles which are as follows:

S/No.	Make & Model	Daily Rental Rates (S\$)
01	Toyota Prius 1,798cc, 90kw, 120bhp, Automatic	\$ 79.95
02	Mazda 3 1.5 (A) Sedan	\$ 66.95
03	Nissan Qashqai 1.2L	\$78.95
04	Honda Vezel 1.5L	\$77.95
05	Honda Vezel 1.5L Hybrid	\$84.95
06	Toyota Vios 1.5L	\$66.95

Please note that the above stated rate is our daily rental rate to our drivers. For your necessary actions on third party accident claims on loss of rental.

Yours faithfully,

Tay Chee Wee Grab Rental Pte Ltd



Land Transport Authority 10 Sin Ming Drive Singapore 575701

profession (

GST Registration No.: M4-0006529-2

Print Date/Time:

20 Mar 2018 / 17:09:12

Receipt Date/Time 20 Mar 2018 / 17:09:12

Tax Invoice/Receipt

Receipt No.: ITNET-00000-180320-001781

Previous Receipt No. :

Lianc	ds (1606ip) 140.		8 8		
S/N	Item Description/		Amount	GST	Amount
	Business Transaction Reference		Before	Amount	After GST
	No.		GST (S\$)	(S\$)	(S\$)
Resu	It of Insurance Enquiry - SLQ4449G				
As at	20 Mar 2018/11:50:00				
Insur	ance Co: AIG ASIA PACIFIC INSURA	NCE PTE. LTD.			
1	Insurance Enquiry - SLQ4449G		1000	12.00	T 10
	Enquiry Fee		7.00	0.49	7.49
	20180320170816545442			0.10	7.45
		Sub-Total	7.00	0.49	7.49
		Total Before Rounding	7,00	0.49	7.49
		Rounding Difference			0.04
		Total Amount Payable			7.45
		Paid By			
		******************************	Credit Card: Visa/MasterCard		7.45
		Total			7.45
		Cash Change			0.00
		Tendered Amount			7,45
		Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



28th Feb. 2018

Name:

Liang Kai Kiat

Vehicle:

SLS4761T

NRIC:

S1701009C

Bank:

SG | POSB BANK *****9460

Earnings

Fares 1,514.00

Incentives 1,121.20

Miscellaneous Payments 8.00

SGD 2,643.20

Deductions

Commissions -302.80

Rental Fees -719.55

Vehicle Expenses 0.00

Adjustments 0.00

SGD -1,022.35

Weekly Total

sgD 1,620.85

Fares (incl. trip promos)

Subtotal

Fares Earned from Cash Rides

352.00

Fares Earned from GrabPay Rides

1,162.00

SGD 1,514.00



Name:

Liang Kai Kiat

Vehicle:

SLS4761T

NRIC:

S1701009C

Bank:

SG | POSB BANK *****9460

Earnings

Fares 1,651.00

Incentives 1,011.60

Miscellaneous Payments 6.00

SGD 2,668.60

Deductions

Commissions -330.20

Rental Fees -559.65

Vehicle Expenses 0.00

Adjustments 0.00

SGD -889.85

Weekly Total

SGD 1,778.75

Fares (incl. trip promos)

Subtotal

Fares Earned from Cash Rides

390.00

Fares Earned from GrabPay Rides

1,261.00

SGD 1,651.00





Name:

Liang Kai Kiat

Vehicle:

SLS4761T

NRIC:

51701009C

Bank:

SG | POSB BANK **** 9460

Earnings

Fares

1,638.50

Incentives

1.026.60

Miscellaneous Payments

10.00

SGD 2,675.10

Deductions

Commissions

-327.70

Rental Fees

-559.65

Vehicle Expenses

0.00

Adjustments

0.00

SGD -887.35

Weekly Total

SGD 1,787.75

Fares (incl. trip promos)

Subtotal

Fares Earned from Cash Rides

388.00

Fares Earned from GrabPay Rides

1,250.50

SGD 1,638.50





Name:

Liang Kai Kiat

Vehicle:

SLS4761T

NRIC:

S1701009C

Bank:

SG | POSB BANK ****9460

Earnings

Fares

1,586.50

Incentives

1,063.20

Miscellaneous Payments

9.00

SGD 2,658.70

Deductions

Commissions

-317.30

Rental Fees

-559.65

Vehicle Expenses

0.00

Adjustments

0.00

SGD -876.95

Weekly Total

SGD 1,781.75

Fares (incl. trip promos)

Subtotal

Fares Earned from Cash Rides

433.50

Fares Earned from GrabPay Rides

1,153.00

SGD **1,586.50**

Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report) Fastlane

LAIM SUB	FOLDER TRA	CKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Ad	j Submitted	Ins Auth'ed	Status	
Main	21 Mar 2018 Edit Reg		21 Mar 2018 00:00 Edit Adj Rpt	S\$6,146.5 Edit Estima		6,146.58 View Rpt		Pending for Report Cancel Ca	
	Main	R	eference	Clai	m Details		Documents		Show All
CLAIM SU	BFOLDER DE	TAILS				[Created	by adjuster]		
Insured:	LCRF PTE	LTD, Co. Reg. f	No.: 201604597K						
Main Claimant:	GRAB RE	NTALS PTE LTD,	Co. Reg. No.: 201	617200G					
Vehicle Re No.:	SLS476	1T		Di	ate of Loss		8 00:00 - :59 and 22 Days Fron	n LTA Reg Date	(Man Yr)]
Claim Type	TP / 213	5812699SG			licy/Cover ste No.:	099999477	1		
Vehicle Res No. (Insured):	SLQ4449	G			licy No. laimant):	A29069766	MKF		
				Ex	cess:				
Repairers	Pegasus	Engineering & T	rading Pte Ltd (HQ) 51 DEFU LA	VE 10, 539	216 Defu Lan	e - Tel: 68581846		
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expres	ss) - Tel: 65-6	419-3000	[Handled b	y Gan, Angle-GL] Angiegeokling	.Gan@aig.con
Claimant's Insurer:	MSIG Ins	urance (Singapo	ore) Pte. Ltd. (HQ)	- Tel: +65 68	27 7888				
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [H	andled by	MARCUS CH	JA] [Final R	pt due 02/04	/2018]
ASSOCIA	TED MAIL RE	CEIVED					Vie	w All Comp	se Case Mail
		/08/2018): Alert : TP GIA REPOR	- Adj Mandate App r	roved (S\$92	15.09) - !	SLS4761T - C	laim Handler: G	an, Angie	
ALL ASSO	CIATED TAS	ks⊟				View All S	iearch Tasks C	reate New Task	Complete
Due Dat	40.4	Type Task	Group Subject	t Handler	Assig	ned By	Completed On	Created C	n Done?

Merimen e-Claims Page 1 of 3

Claim Documents

*SLS4761T (2135812699SG)

[SLQ4449G]

TP

GRAB RENTALS PTE LTD

Mar 20 2018 12:00AM


[LCRF PTE LTD]

Pegasus Engineering & Trading Pte Ltd

Vic	leo		1 per	page 🔻	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1	Thumbnail	-
1	18/07/18 07:38	VIDEO FROM THIRD PARTY	0	Load MP4	
Let	ters/Corresponde	nces	1 per s	page V	~
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	La pro-	Thumbnail	-
1	(Draft)	Third Party Express Settlement - Payment Breakdown	0	Edit	
Ass	sessment Reports		1 per i	page 🔻	V
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	10000	Thumbnail	Print
1	22/03/18 12:14	Accident Statement From:SC + Reg. No: SLQ4449G, Claimant: LCRF PTE LTD	Ø	Load HTM	
Ph	otos/Images		3 per p	age V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	[S PCF]	Thumbnail	-
1	21/03/18 18:57	Chassis Number	0	Load JPG	V
2	21/03/18 18:57	General View	0	Load JPG	[2]
3	21/03/18 18:57	Odometer Reading	0	Load JPG	V
4	21/03/18 18:57	General View	0	Load JPG	V
5	21/03/18 18:57	General View	0	Load JPG	V
6	21/03/18 18:57	General View	0	Load JPG	V
7	21/03/18 18:58	General View	0	Load JPG	V
8	21/03/18 18:58	General View	0	Load JPG	V
9	21/03/18 18:58	General View	0	Load JPG	S
10	21/03/18 18:58	General View	0	Load JPG	V
11	21/03/18 18:58	General View	0	Load JPG	V
12	21/03/18 18:58	General View	0	Load JPG	V
13	21/03/18 18:58	General View	0	Load JPG	V
14	21/03/18 18:58	General View	0	Load JPG	N.
15	21/03/18 18:58	General View	0	Load JPG	V
16	21/03/18 18:58	General View	0	Load JPG	Ø
17	21/03/18 18:58	General View	0	Load JPG	V
18	21/03/18 18:58	General View	0	Load JPG	V
19	21/03/18 18:58	General View	0	Load JPG	V
20	21/03/18 18:58	General View	0	Load JPG	V
21	21/03/18 18:58	General View	0	Load JPG	V
22	21/03/18 18:58	General View	0	Load JPG	V
23	21/03/18 18:58	General View	0	Load JPG	V
24	21/03/18 18:58	General View	0	Load JPG	V
25	21/03/18 18:58	General View	0	Load JPG	V
26	21/03/18 18:58	General View	0	Load JPG	V
2.7	21/03/18 18:58	General View		Load JPG	

Vid			1 per page	v	V
Nο	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		mbnail	-
20	200200000000		0		Y
28	21/03/18 18:58	General View		nd JPG	✓
29	21/03/18 18:58	General View		nd JPG	V
30	21/03/18 18:58	General View	1000	d JPG	V
31	21/03/18 18:58	General View	① Loa	d JPG	V
32	21/03/18 18:58	General View		d JPG	V
33	21/03/18 18:58	General View		id JPG	V
34	21/03/18 18:58	General View	€ Loa	d JPG	V
35	21/03/18 18:58	General View	60.1	d JPG	V
36	21/03/18 18:58	General View	O Loa	d JPG	V
37	21/03/18 18:58	General View	O Loa	d JPG	V
38	21/03/18 18:58	General View	O Los	d JPG	V
39	21/03/18 18:58	General View	1 Loa	d JPG	V
40	21/03/18 18:58	General View	1 Loa	d JPG	V
41	21/03/18 18:58	General View	€ Loa	d JPG	V
42	21/03/18 18:58	General View	1 Loa	d JPG	☑
43	21/03/18 18:58	General View	O Loa	d JPG	V
44	21/03/18 18:58	General View	€ Loa	d JPG	V
45	21/03/18 18:58	General View	1 Loa	d JPG	V
45	21/03/18 18:58	General View	1.0a	d JPG	V
17	21/03/18 18:58	General View	● Loa	d JPG	V
18	21/03/18 18:58	General View	€ Loa	d JPG	V
19	21/03/18 18:58	General View		d JPG	V
50	21/03/18 18:58	General View		d JPG	V
51	21/03/18 18:58	General View		d JPG	V
52	21/03/18 18:58	General View		d JPG	V
53	21/03/18 18:58	General View		d JPG	V
54	21/03/18 18:58	General View		d JPG	V
55	21/03/18 18:58	General View		d JPG	V
56	21/03/18 18:58	General View		d JPG	V
57	21/03/18 18:58	General View		d JPG	V
8	21/03/18 18:58	General View		d JPG	Ø
9	21/03/18 18:58	General View		d JPG	V
50	21/03/18 18:58	General View		d JPG	V
1	05/04/18 16:50	Reinspection Photo		d JPG	V
52	05/04/18 16:50	Reinspection Photo		d JPG	V
53	05/04/18 16:50	Reinspection Photo		d JPG	V
14	05/04/18 16:50	Reinspection Photo		d JPG	V
55	05/04/18 16:50	Reinspection Photo		d JPG	N
55	05/04/18 16:50	- Control Cont		d JPG	V
7	05/04/18 16:50	Reinspection Photo Reinspection Photo		d JPG	<u>S</u>
	05/04/18 16:50	Dark Mary Drawn and Santis at			₹
8		Reinspection Photo		d JPG	-
9	05/04/18 16:50	Reinspection Photo		d JPG	V
0	05/04/18 16:50	Reinspection Photo		d JPG	3
1	05/04/18 16:50	Reinspection Photo		d JPG	V
2	05/04/18 16:50	Reinspection Photo		d JPG	V
3	05/04/18 16:50	Reinspection Photo		d JPG	V
4	05/04/18 16:50	Reinspection Photo		d JPG	V
5	05/04/18 16:50	Reinspection Photo		d JPG	V
6	05/04/18 16:50	Reinspection Photo	O Load	d JPG	V

Merimen e-Claims Page 3 of 3



Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured,			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TE			

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

venicle No:	_	19G (Insa ven	/	Model:		- 4	TOYOTA PRIUS 1.8 HYBRID
	SLS476	31T (TP veh)				K	CVT (A)
Date of Accident:	20/03/2	018					
						7	
Global Sum Settlem	nent :	[] Yes		[X] No			
Repair Estimate			: \$	11/5	980.17	4	
Final Repair Cost			:\$	6,	576.84	-	
Loss of Use			: \$		640.00	_	3.00 days at \$80.00 per day
Rental (if any)			: \$		639.60	8	days
LTA / GIA Search F	ee		:\$		7.45		
Others:			: \$		0.00		
			: \$				
Final Settlement Su	m		: \$	7,	863.89		
Is Third Party World below)	kshop Gl	A Registered	?	[] YE	s [x]	NO (Kindly indicate
A) For Non GIA R	egistered	Workshop:		Agreed l	iability		100(%)
B) For GIA Regist	ered Wo	rkshop:		BOLA A	plicab	le: Yes	No BOLA Scenario No:
BOLA Liability: * Assessed Liab		111000000000000000000000000000000000000	chain				(%) here BOLA does not apply.
		111000000000000000000000000000000000000	chain				(%) here BOLA does not apply.
* Assessed Liab Remarks	bility to be	filled only for					
* Assessed Liab Remarks Payment Instruction	on: Payee	filled only for	1		nd for c		here BOLA does not apply.
* Assessed Liab Remarks Payment Instruction 1) Pegasus Engir	on: Payee	filled only for	1		s s		
* Assessed Liab Remarks Payment Instruction	on: Payee	filled only for	1		nd for c		here BOLA does not apply.

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any) Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18005263/UPA3Q2

12/09/2018 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999994771

Claimant Vehicle No:

SLS4761T

Insured Vehicle No: SLQ4449G

Date of Loss:

20/03/2018

Nature of Claim: TP

Claim No: 2135812699SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLS4761T

Make & Model:

TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No:

2ZRS088523

42722 km

Reg. Date:

26/09/2017 (Man. Year: 2017)

Chassis No: Odometer:

JTDKB3FU503570833

Colour Engine Capacity:

1798 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES Front Tyre Size:

Front Left Side:

195/65 R15 Yokohama 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 195/65 R15 Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		8,176.42	3,896.58	4,279.84	52.34
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,020.00	2,250.00	770.00	25.50
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	11,196.42	6,146.58	5,049.84	45.10
	+ GST 7.00/7.00% (S\$)	783.75	430.26	353.49	45.10
	Nett Amount (S\$)	11,980.17	6,576.84	5,403.33	45.10
	+ Loss of Use (8.0 x S	\$\$80.00/day) (S\$)	640.00		
	+ Car Rental (8.0 x S	\$\$79.95/day) (S\$)	639.60		
	+ Doo	/Search Fee (S\$)	7.45		
	1	Nett Liability (S\$)	7,863.89		

INSPECTION

Date of Assignment:

21/03/2018

Date Inspected:

21/03/2018 Inspected At:

Pegasus Engineering & Trading Pte Ltd

51 DEFU LANE 10 Singapore 539216

Estimated Period of Repair:

6.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen ... 12/9/2018

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

R	ecor	nme	nder	1 Pa	rts
1	CCUI	111116	HUEL	1 - 0	113

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR GATE	Bent / Buckled	922.50 FL	*922.50 FL
2	1		*REAR GATE CENTRE LOGO	Necessary	43.80 FL	*43.80 FL
3	1		*REAR GATE PRIUS PLATE	Necessary	49.05 FL	*49.05 FL
4	1		*REAR GATE HYBRID PLATE	Necessary	51.05 FL	*51.05 FL
5	1		*REAR GATE LOCK	Twisted	47.70FL	*47.70 FL
8	1		*REAR GATE INNER RUBBER	Twisted / Necessary	340.80 FL	
7	1		*REAR WINDSCREEN MOULDING (TOP)	Necessary	62.81 FL	*62.81 FL
8	1		*REAR GATE OUTER GARNISH	Cut / Warped	866.50 FL	*866.50 FL
9	1		*REAR GATE GLASS MOULDING (LOWER)	Necessary	69.10 FL	*69.10 FL
10	1		*REAR GATE INNER TRIM BOARD (CENTRE)	Not Necessary	281.60 FL	*-FL
11	8		*REAR GATE INNER TRIM BOARD CLIPS	Necessary	67.20 FL	*67.20 FL
12	2		*REAR GATE INNER TRIM BOARD (SIDES) (NPA)	Not Necessary	0.00 FL	*-FL
13	1		*REAR BUMPER TOP	Distorted	464.00 FL	*464.00 FL
14	1		*REAR BUMPER RETAINER	O/S Bent	225.40 FL	*112.70 FL
15	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	349.00 FL	*349.00 FL
17	1		*REAR BUMPER (LOWER)	Distorted	552.80 FL	
18	2		*REVERSE SENSOR	Shorted	271.36 FS	
19	1		*REAR CORNER BUMPER RH	Distorted	125.30 FL	
20	2		*REAR TAIL LAMP (TOP)	Not Necessary	789.70 FL	*-FL
21	2		*REAR TAIL LAMP (LOWER)	Not Necessary	951.40 FL	*-FL
22	1		*REAR END PANEL	Repair	586.90 FL	*-FL
23	1		*REAR END PANEL TOP GARNISH	Twisted	121.60 FL	
24	6		*TOP GARNISH CLIPS	Not Necessary	33.00 FL	*- FL
25	1		*REAR SPARE TYRE BOARD COVER	Not Necessary	536.80 FL	*-FL
26	2		*REAR SPARE TYRE TOOLS TRAY		202.80 FL	*-FL
27	1		*REAR EXHAUST BOX	Not Necessary		*-FL
28	2		*REAR EXHAUST BOX RUBBER HOLDER	Repair Not Necessary	854.10 FL	*-FL
29	1		*REAR RH FENDER INNER COWLING JOINT		78.20 FL	
30	1		*REAR RH FENDER INNER COWLING	Not Necessary	190.72 FL	*-FL
31	10		*INNER COWLING CLIPS	Not Necessary	210.70FL	*-FL
32	1		*REAR FLOOR PANEL UNDER COVER	Not Necessary	55.00 FL	*-FL
	8			Distorted	197.10 FL	*197.10 FL
33	1		*REAR FLOOR PANEL UNDER COVER CLIPS	Not Necessary	44.00 FL	*-FL
			*REAR BUMPER TOWING COVER	Torn	65.50 FL	*65.50 FL
35	1		*REAR UNDER COVER O/S	Torn	190.20 FL	*190.20 FL
	1		*REAR WINDSCREEN GUM	Necessary	60.00FS	*40.00 FS
37	1		*REAR GATE GLASS GUM	Necessary	60.00 FS	*40.00 FS
38	1		*SET REAR NUMBER PLATE	Not Necessary	40.00 FS	*-FS
=Fra	nchise	part. S=Spc	Nett. L=List/temDisc.	Cub Tatal (CC)	40 440 00	F 400 44
			List Hom Discount Life	Sub Total (S\$)		5,102.11
		- List Item Discount on L Items 20.00/25.00% (S\$)			1,936.27	1,205.53

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	WIRE CHECKING	New	30.00	30.00
2	REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	REMOVE & REFIX REAR GATE GLASS (LOWER)	New	100.00	100.00
4	R&R REAR BOOT UPHOLSTERY TO FACILITATE TO REPAIR	New	150.00	80.00
5	CAVITY PROTECTION ON ALL AFFECTED AREAS	New	120.00	60.00
6	REMOVE & REFIX EXHAUST BOX	New	100.00	60.00
7	LABOUR CHARGE	New	1,300.00	800.00
8	SPRAY PAINTING	New	1,100.00	1,000.00
	Gross Labou	r Cost (S\$)	3,020.00	2,250.00
_	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >