

### REPAIR ESTIMATE\*

VEHICLE NO : SHB 6217Y

MAKE :

**MODEL : HYUNDAI SONATA**

Aigbia. - 4 sum

DATE 19/3/2018

LKK -

TS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 538.80
	Front Bumper Sponge			\$ 136.30
	Front Bumper Reinforcement			\$ 504.10
	Front Bumper Bracket Top (LH)			\$ 22.40
	Front Bumper Protector (LH)			\$ 29.20
	Headlamp (LH)			\$ 797.90
	Front Fender (LH)			\$ 593.00
	Front Fender Shield (LH)			\$ 86.00
	Front Fender Retainer			\$ 9.20
	SUB TOTAL			\$ 2,716.90
	LESS 20%			\$ 543.38
	DISCOUNTED TOTAL			\$ 2,173.52
	<b>Labour Charge</b>			
	Panel Beating			\$ 500.00
	Spray Painting Charge-Bumper/Fender			\$ 500.00
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 1,050.00
	ESTIMATE TOTAL			\$ 3,223.52

300  
360  
30

Rasul  
Hp 900 10068  
3 days  
43  
20/03/18 @ 1235  
Resy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.