

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

19-Mar-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8407 C

1pc	Front bumper	\$	811.11 <i>de</i>
1pc	Front bumper sponge	\$	218.03 ?
1pc	Front bumper reinforcement	\$	636.40 ?
1pc	Front bumper reinforcement lower	\$	223.88 ?
2 pcs	Front n/s & o/s bumper side bracket @\$32.51	\$	65.02 <i>na</i>
2 pcs	n/s & o/s headlamp @\$1531.57	\$	3,063.14 <i>LL-?, RH-na</i>
1pc	Bonnet grille	\$	566.46 <i>na</i>
1pc	Bonnet	\$	1,220.40 <i>bt</i>
2 pcs	Bonnet hinge @\$79.18	\$	158.36 <i>bt</i>
1pc	Support panel	\$	1,292.20 ? <i>photo</i>
1pc	Horn	\$	78.30 ?
1 pc	Aircon condensor	\$	745.00 ?
1 pc	Radiator	\$	670.60 ?
1 pc	Blower Assy	\$	423.60 ?
1 pc	Tailgate	\$	2,292.30 ?
1 pc	Tailgate lower garnish	\$	362.61 <i>ant</i>
1 pc	Emblem I30	\$	27.80 <i>na</i>
1 pc	Emblem CRDI	\$	29.40 <i>na</i>
1 pc	Emblem Hyundai	\$	29.40 <i>na</i>
1 pc	Rear bumper	\$	811.11 <i>de</i>
1 pc	Rear bumper sponge	\$	79.20 <i>de</i>
1 pc	Rear bumper reinforcement	\$	815.64 <i>bt</i>
1 pc	Rear bumper reinforcement centre	\$	79.20 ?
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40 <i>na</i>
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	\$	215.00 <i>ns</i>
		\$	15,018.56
	Less 20%	\$	3,003.71
		\$	12,014.85
S/NETT			
1 set	Rear bumper clips	\$	48.00 <i>na</i>
1 set	Front bumper clips	\$	48.00 <i>na</i>
1 set	Reverse sensor	\$	280.00 <i>na</i>
1 set	Tailgate sticker	\$	100.00 <i>na</i>
1 pc	Front no. plate	\$	50.00 <i>45 na</i>
1 pc	Rear no. plate	\$	50.00 <i>30 na</i>

19-Mar-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8407 C

Towing Fee	\$	50.00 ✓
Sundry	\$	50.00 30
To dismantle and replace reverse sensor and test system	\$	80.00 30
Top up gas	\$	120.00 100?
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, floorboard etc	\$	1,400.00 1200
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel, floorboard panel, front bumper, bonnet, bonnet grille	\$	1,600.00 1200
To apply rustproofing on the repaired and replaced panels	\$	250.00 100
Total	\$	16,140.85

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanglin 97495749
- WP
20/3/18 @ 4pm -
Resurvey before paint
Resurvey check items
9 days
see @ lkkauto.com.