

INS. CASE OWNER:

CC 3/CTI1800 5274, R1ub3n2

LKK:

IDAC:

Surveyor:

Rusul

DOI:

ASSIGNMENT

20/7/18

Date / Time:

20/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDN 8884P

Name of Insured:

WILUKE UM PETE SAN

Insured Tel No.:

HP:

88228822

Excess Sec II :\$

D.O.A.:

17/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SDN 18001198 (COMET) URS.

Policy No.:

DMPEN/101261801

Make / Model:

BMW

Place of Accident:

OUTSIDE ESTERA WARDEN

LONDO FLORA RO

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YDS / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SHC 7877E



INSRS:

WSP:

Tel:

Liability:

RMKS:

1045 W



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

22/7/18
11M

SHC 7877E - Y

SDN 8884P - Y

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

> THIN By Email
2/4

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

24/18.

Spoke to CI, she confirmed the accident details. Informed IP claim and she agree to settle.

RECEIVED 09 MAY 2018

RECEIVED 05 JUL 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

22/6/18

Confirm with:

William.

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

9

If NO or B 28, Ass. Lia:

Repair Cost:

SS

2033.00

Loss of Rental (LOR):

SS

775.32

(

6.5 days)

x

119.28

Loss of Use (LOU):

SS

325.00

(\$

50 x 6.5 days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search:

SS

7.49

Medical:

SS

Disbursement:

SS

(e.g. Tow / Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

3140.81

Global Sum SS:

3140.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3140.00

Name 1:

COMFORTDELGRO ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Rasul

REG


28396

Vehicle Inspection

From: _____ Date: _____
 To: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 At Workshop No: _____
 at _____
 Insured _____
 Policy No: _____
 Claim No: _____
 Sum Insured _____ Excess _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value _____
 IDAC Accident Report _____ Consistent? Yes or No _____
 GVA / PR Seen _____ Consistent? Yes or No _____
 Est. Repairs: 5 days Res: Yes or No _____
 Lmt Sum: 20 % 3 Val Yes or No _____

CA / REV / REP: / 24 HRS

Vehicle: IN / OUT

Date _____ Person Contacted _____

Vehicle No: SHC 7877E To Inspect: 2014 APR
 Type: M/Cat / 24 Cycle / Bus / Van / Lorry / Prime Mover /
 Truck / Trailer or

Make: Hyundai 2401.7 cc 1688
 Colour: Yellow Age: Insured / Std / NI / NA
 Sp Reading: 631846 Tyres: Insured / Std / NI / NA

Engine: _____
 C/No: KMHLB41WME 052411

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or WESTLAKG

Front _____ Rear _____
 R/Bal: 5 mm P/Bal: 5 mm
 L/Bal: 5 mm L/Bal: 5 mm
 D.O.A: 17/03/18 D.O: 20/03/18

Survey held at: COMFORT BELLAR

Des. of Damages: Frt / Rear / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

LIS - \$1900+ (Red: \$1907.08/50%)

Date-Time: On Panel: ☐ Profit Report

at: ☐ Final Report

Date-Time: On Panel: ☐

Days Of Repair: _____

Resurvey No. of Trip: _____

Report Format: _____

Group Sign: JLB L13

Add Fee: ☐ 15

☐ 15

☐ 15

☐ 15

Survey Fee: _____

Check position: _____

at: _____

at: _____

at: _____

at: _____

at: _____

at: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18005274/R1ub3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 21-03-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDN 8885P	Veh. Inspected	SHC 7877E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/03/2018	Inspection Date	20/03/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18005274/R1ub3

Date: 20.03.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC7877E


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.03.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,807.08
Revised Estimate Amount	: S\$	2,444.28
"Check" Items Amount	: S\$	1,052.80
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Shu Pei (LKKAUTO)

From: Jowyn Tay <jowyn.tay@sg.cntaiping.com>
Sent: Wednesday, 21 March 2018 6:33 PM
To: Shu Pei (LKKAUTO); Thin Thin (LKKAUTO)
Cc: Jowyn Tay; Admin A
Subject: RE: Direct Settlement - Accident Involving SDN8885P (OI : SNM18D01498/C02/5/LKKDS) and SHC7877E (TP : LKK REF - CC3/CTI18005274/R1ub3) on 17.03.2018
Attachments: SNM18D01498C02 20180321-TO INSD-APPT LKK AS SETTLEMENT AGENT.pdf; MCCA18037512-SDN8885P.pdf

Dear Thin Thin &/or Shu Pei,

Please refer to the attachments.

Thank you.

Regards,

Jowyn Tay

Deputy Claims Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6174
Fax: 6224 7175 / 6224 7478
Email: claimsdept@sg.cntaiping.com
jowyn.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 21 March, 2018 5:30 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Jowyn Tay <jowyn.tay@sg.cntaiping.com>; Joel Goh <joel.goh@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Thin Thin (LKKAUTO) <thinthin@lkkauto.com>
Subject: Direct Settlement - Accident Involving SDN8885P (OI : CTI - TBA) and SHC7877E (TP : LKK REF - CC3/CTI18005274/R1ub3) on 17.03.2018

WITHOUT PREJUDICE

Dear Jowyn,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 7877E at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaping.com

Co. Reg. No. 200208384E

Our Reference: **SNM18D01498/C02/5**

Date : **21 MARCH 2018**

via Ordinary & Registered Mail

**NICOLE LIM PECK SAN (LIN BISHAN)
BLK 19 QUEEN'S CLOSE
#02-115
SINGAPORE 140019**

Dear Sir / Madam

**ACCIDENT INVOLVING SDN8885P AND SHC7877E ON 17 MARCH 2018
ALONG FLORA ROAD & ESTELLA CONDO EXIT**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC7877E** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : THIN THIN

Ref : CC3/CTI18005274/R1ub3

Contact No : 68412360

via Email : thinthin@lkkauto.com

CC : Agent - (AN0570A) - M PRO CONSULTANCY

F01/LKKDS-2013

COMFORTDELGRO
ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6260 0755
Workshops
53 Laying Drive Singapore 608269 24 Serangoon Loop Singapore 758156
383 Sin Ming Drive Singapore 515717 7 Sungei Kadut Way Singapore 728791
45 Pandan Road Singapore 609286 6 Dafu Avenue 1 Singapore 539537
321 Upper Bukit Timah Road Singapore 678168

Date/Time: 19.03.2018 09:31 Page : 1

am: ARC Repair TP(CFSO)1 JOB CARD Sales Order: 3811404 JC NO: 305126133

OMER	REGN NO	MILEAGE
CITYCAB PTE LTD	SHC7877E	
IS 7010070	MAKE	FUEL
OMER NO 383 SIN MING DRIVE	HYUNDAI	E.....1/2.....F
RESS Singapore SINGAPORE 575717	MODEL	DATE/TIME IN
65551188	I-40	17.03.2018 14:30
(R)	YR OF MANU	TARGET DATE
(P)	09.04.2014	
	CHASSIS CODE	COMPLETION DATE/TIME:
	RHLB41UMEU052411	

COUNT CARD NO.

Accident Date: 17.03.2018
ATURE: 3P 17.03.18/B

JOB DESCRIPTION
RIGHT DOOR
CHINA.
SDN8885P

/NO LABOR CODE DESCRIPTION

IKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

ledgement Slip	Exit Pass
No.: SHC7877E FZ CHINA	Vehicle No.: SHC7877E
Signature/Date	Name of Service Advisor
turned to Service Reception upon collection	To be kept by Security Guard

REPAIR ESTIMATE*

DATE 19/3/2018 10:12

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door (RH)			\$ 1,403.00
	Front Door Gear / Regulator (RH)			\$ 785.50
	Front Door Power Motor			\$ 530.50
	Rocker Panel Outer Garnish			\$ 483.60
	SUB TOTAL		1886.60	\$ 3,202.60
	LESS 20%		20%	\$ 640.52
	DISCOUNTED TOTAL		1509.28	\$ 2,562.08
	Front Door Comfort Logo (RH)		75	\$ 75.00
	Labour Charge			
	Panel Beating			\$ 250.00
	Spray Painting Charge- Door x2/Rocker Panel			\$ 750.00
	Tuff Kote			\$ 50.00
	Transfer of Door			\$ 120.00
	TOTAL LABOUR		5 days	\$ 1,170.00
	ESTIMATE TOTAL		4/5	\$ 3,807.08
	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Post-Vok

COMFORT DELGRO ENGINEERING

Comfort Delgro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FC

Our Job Ref No : 305126133
Date : 23.03.2018

FINALIZATION FORM

To : LKK
Attn : RASUL
Vehicle Reg No. : SHC7877E

Fax: Encl - 23/3/18

Date of Accident : 17.03.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SDN8885P
2. The finalized amount shall be:


(a) Spare Parts after List discount	\$0.00
(b) Labour Charges	\$0.00
Total for Part-By-Part Repair Cost	\$0.00
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	\$1,900.00
Final Lumpsum Repair cost	\$1,900.00


3. Estimated normal period for repairs: 5 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : FAUZY BIN MOKHTAR
Tel : 62148319
Fax : 65468156

Signature : 
Name : Rasul
Date : 12/04/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day	119.28	YES		
2. Loss of Income Paid	560.00	N		
3. Survey Fees	/	/		
4. LTA Search Fee	7.49	Yes		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18005274/R1ub3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 06-07-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDN 8885P	Veh. Inspected	SHC 7877E	
Policy No.	DMPCSN1701261801	Coverage (\$)	0.00	
Claim No.	SNM18D01498/C02/5	Excess (\$)	0.00	
Assign From		Assign Date	20/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40 1.7	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KMHLB41UMEU052411	Colour	YELLOW	
Odometer	631846	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/03/2018	Inspection Date	20/03/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7877E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR (RH)	BUCKLED	1,403.00	1,403.00
1	FRONT DOOR GEAR / REGULATOR (RH)	SERVICEABLE	785.50	-
1	FRONT DOOR POWER MOTOR	SERVICEABLE	530.50	-
1	ROCKER PANEL OUTER GARNISH	SCRATCHED	483.60	483.60
	LESS 20% DISCOUNT		-640.52	-377.32
			2,562.08	1,509.28
<u>SPECIAL NETT ITEMS</u>				
1	FRONT DOOR COMFORT LOGO (RH) (SN)	NECESSARY	75.00	75.00
			75.00	75.00
<u>LABOUR</u>				
	PANEL BEATING .		250.00	250.00
	SPRAY PAINTING CHARGE -DOOR X2 /ROCKER PANEL .		750.00	460.00
	TUFF KOTE.		50.00	50.00
	TRANSFER OF DOOR .		120.00	100.00
			1,170.00	860.00
GRAND TOTAL			3,807.08	2,444.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00

Report Ref No. CC3/CT118005274/R1ub3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.