

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 03 Apr 2018

Preliminary Advice

Insured Vehicle No : SJR812K

TP Vehicle No : SHD5848Y

Accident Date : 25/03/2018

Make : RENAULT LATITUDE

Assignment Date : 29/03/2018

Date of Inspection : 29/03/2018

Est. Duration of Repair : 2.5

Inspection At : TRANS-CAB AUTO SERVICES PTE LTD (ANG MO KIO)
2, ANG MO KIO STREET 63
SINGAPORE 569111**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	45,547.07
Revised Amount	:S\$	7,498.75
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair (estimated)	:S\$	6,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.