

ASS. REC. BY:

REF: CS/MSG18005275/Urbn2 Special Instruction:

SURVEYOR: Marius. ASSIGNMENT (Office)

From (Person): Merimen Chbia Nyuk Pui of MSH Date/Time: 21/03/2018 10:43am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / ~~FD~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJC 5298R Insured: SKX 3765A

at Workshop m/s Jin Auto Tel: 6289 8126

of Blk 14 Dahu Lane 10 # 01-410

Policy No: 28854469DMA Claim No: 552913

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 20032018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpt H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 21/03/2018 Person Contacted: Juis Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SJC 5298R - CS / PDI 131121877 / Rqms u2 Dof: 191113
	SKX 3765A - x
<u>22/3/18</u>	<u>Informed Nyuk Pui pending workshop est by merimen</u>

(08/11/13) wef  
ASS. REC. BY: Merimen

REF:

MS16/

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJC 5298

at Workshop m/s Jin Awa

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 28500

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 30/11/2022

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SJC 5298R Yr Regn: 208

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Nissan Latio c.c. 1498

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 215 050 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JN15AA C1120009278

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65-R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 20/3/18 D.O.I. 21/3/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & RL

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>17A19702 9shy 800 net 8798</u>
<u>2/4/18</u>	<u>confund d/s &amp; 8500 with Jouis. (Red 7851.04, 4870)</u>
<u>3/4/18</u>	<u>Send preli revised by merimen</u>
	<u>RECEIVED 05 APR 2018</u>

Merimen  
3/4/2018

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2) 3/4 - typist

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee: 300

Transportation: 10

\$ + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

310

Report Format: merimen

Lump Sum / I.B.I: (\$ 8500)

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Chhia Nyuk Pui	Date: 03 Apr 2018

## Preliminary Advice

Insured Vehicle No	: SKX3765A		
TP Vehicle No	: SJC5298R	Accident Date	: 20/03/2018
Make	: NISSAN LATIO	Assignment Date	: 21/03/2018
Date of Inspection	: 22/03/2018	Est. Duration of Repair	: 10.00
Inspection At	: JIN AUTO SERVICES PTE LTD (DEFU) BLK 14 DEFU LANE 10, #01-410/412 SINGAPORE 539195		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear and front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,351.04
Revised Amount	:S\$	11,737.92
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair (estimated)	:S\$	8,500.00
-----------------------------	------	----------

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18005275/Uvb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 21-03-2018



Code : MSG

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 3765A	Veh. Inspected	SJC 5298R
Policy No.	28854469DMA	Coverage (\$)	0.00
Claim No.	552913	Excess (\$)	0.00
Assign From	MERIMEN (CHHIA NYUK PUI)	Assign Date	21/03/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	20/03/2018	Inspection Date	21/03/2018
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2018		21 Mar 2018 10:43 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS				[Created by insurer]																				
<b>Insured:</b>	FARLIYANIE KARIM, ID: S2013737A																							
<b>Main Claimant:</b>	TAN YONG KWANG, ID: S1362354F																							
<b>Vehicle Reg. No.:</b>	SJC5298R	<b>Date of Loss:</b>	20/03/2018 00:00 - :59																					
<b>Claim Type:</b>	TP / 552913	<b>Policy/Cover Note No.:</b>	28854469DMA (Comprehensive) Coverage: 08/12/2017 - 07/12/2018																					
<b>Vehicle Reg. No. (Insured):</b>	SKX3765A	<b>Policy No. (Claimant):</b>																						
		<b>Excess:</b>																						
<b>Repairer:</b>	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126																							
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]																							
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/03/2018]																							
<b>Adj Asg. Remarks:</b>	ON WP																							
<b>ASSOCIATED MAIL RECEIVED</b>				View All																				
There are no mail for this case.				Compose Case Mail																				
<div style="border: 1px solid black; padding: 5px;"> <p><b>ALL ASSOCIATED TASKS</b></p> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

*March*

## View Sent Message

This mail is associated with :

**\*SJC5298R (552913)**  
**[SKX3765A]**

TP  
TAN YONG KWANG  
Mar 20 2018 12:00AM  
[FARLIYANIE KARIM]  
Jin Auto Services Pte Ltd

Resend View Recipients Print Message Delete Message Forward

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **22/03/2018 16:11 PM.**  
**To** SGSGCNP  
**Subject** **PENDING ESTIMATE FROM REPAIRER**

Dear Nyuk Pui,

Please be informed that we have inspected the vehicle SJC 5298R on 21/3/2018.

We are pending estimate from repairer.

Best Regards,  
Veron Chen

### DOCUMENTS SUMMARY

There are no documents.

## Veron Chen (LKKAuto)

---

**From:** jouis <jouis@jinauto.com.sg>  
**Sent:** Wednesday, 21 March 2018 2:38 PM  
**To:** Marcus Chua (LKKAuto)  
**Cc:** Veron Chen (LKKAuto)  
**Subject:** RE: Accident Involving Vehicle SJC5298R and SKX3765A on 20/3/18  
**Attachments:** SJC5298R LATIO.xls

Marcus

Estimate attached

Thank you & Best Regards,  
Jouis Seow  
Jin Auto Services Pte Ltd  
Blk 14 #01-412 Defu Lane 10  
Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)

---

**From:** jouis [mailto:[jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)]  
**Sent:** Wednesday, 21 March 2018 10:59 AM  
**To:** Marcus Chua (LKKAuto)  
**Subject:** FW: Accident Involving Vehicle SJC5298R and SKX3765A on 20/3/18

Thank you & Best Regards,  
Jouis Seow  
Jin Auto Services Pte Ltd  
Blk 14 #01-412 Defu Lane 10  
Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)

---

**From:** Margaret Loh [mailto:[margaret\\_loh@sg.msig-asia.com](mailto:margaret_loh@sg.msig-asia.com)]  
**Sent:** Wednesday, 21 March 2018 10:39 AM  
**To:** [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)  
**Cc:** Chhia Nyuk Pui  
**Subject:** FW: Accident Involving Vehicle SJC5298R and SKX3765A on 20/3/18

Your Ref : SJC5298R  
Our Ref : 552913

Dear Jouis,

We refer to our tele-conversation dated 21.03.2018.

We have both agreed on a common surveyor **M/s LKK Auto Consultants Pte Ltd** to be the SJE (Single Joint Expert).

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Thank you.

Best Regards

**Margaret Loh**

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2553 | Direct fax +65 6225 7402 | [margaret\\_loh@sg.msig-asia.com](mailto:margaret_loh@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** jouis [<mailto:jouis@jinauto.com.sg>]

**Sent:** 20 March 2018 16:37

**To:** Claims <[claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)>

**Subject:** Accident Involving Vehicle SJC5298R and SKX3765A on 20/3/18

Dear Sir/Madam

Accident Involving Vehicle SJC5298R and SKX3765A on 20/3/18

We are assisting owner of SJC5298R handling his third party claim

recovery against SKX3765A Please arrange third party survey at our workshop.

Kindly establish liability for this case.

Thank you & Best Regards,

Jouis Seow

Jin Auto Services Pte Ltd

Blk 14 #01-412 Defu Lane 10

Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	2354F
<b>Vehicle Details</b>	
Vehicle No.:	SJC5298R
Vehicle to be Exported:	No
Intended De-registration Date:	21 Mar 2018
Vehicle Make:	NISSAN
Vehicle Model:	LATIO 1.5L T
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	HR15252482A
Chassis No.:	JN1BAAC11Z0009279
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$15,500.00
Original Registration Date:	22 Feb 2008
First Registration Date:	22 Feb 2008
Transfer Count:	2
Actual ARF Paid:	\$17,050.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$20,997.00
COE Rebate Amount:	\$19,702.00
<b>Total Rebate Amount:</b>	<b>\$19,702.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Mar 2018

OK

**Free Car Valuation**

Unsure of how much your car is worth?  
Let us tell you how much is the value - no charges & no obligations!

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

**Toyota Dyna 150 (M) Euro 6 Now At \$76,800.**



New Super Sale! Limited Sale!  
Ready Stock! 2017 New Facelift  
Euro 6 Borneo.  
Net Link Partners StarAd

Think One Automobile  
**NEW & USED COMMERCIAL VEHICLES**

Browse by Category

Sort by Date Posted 20 results/page

18 vehicles

nissan latio

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
nissan latio		Any	Any	2008	Any	Any	Any	Available
	Nissan Latio 1.5A (OPC) (New 5-yr COE)	\$33,899	\$6,780 /yr	01-Jul-2008	1,498 cc	99,000 km	Sedan	Available
1 Owner Low Mileage Beautiful Like New Mint Condition Nissan Latio 1.5 Auto Premium Model. Comes With New 5-Years COE. Low Depreciation. Spacious And Comfortable. Reliable And Low Fuel Consumption. Bu...								
Posted: 20-Mar-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan								
	Nissan Latio 1.5A	\$11,888	\$7,660 /yr	10-Oct-2008	1,498 cc	-	Sedan	Available
Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only								
Boeki Auto & Marine								
Posted: 20-Mar-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan								
	Nissan Latio 1.5A Premium	\$8,200	N.A	02-Jun-2008	1,498 cc	-	Sedan	Available
Calculated \$15 Dollars Per Day. Minimum Paper Value \$7344. Welcome Export Dealers, Scrap Dealers And Rental Company For Enquiry. Message / Watsapp For Viewing Arrangement.								
Posted: 19-Mar-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan								
	Nissan Latio 1.5A Sports Premium (New 5-yr COE) (OPC)	\$31,800	\$6,360 /yr	19-Sep-2008	1,498 cc	76,145 km	Hatchback	Available
Monthly At \$400 Plus! Avg Clocked 8000km/Yr! Agent Maintained! Extended Warranty Available! 1 Owner Only! Rare Find, Well Kept In Tip Top Condition That You Will Be Amazed With. See It For Yourself To...								
Dickson Automobile								
Posted: 19-Mar-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan								
Car Buying	Car Selling	Car Ownership	Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation					
Car Aftermarket	On The Move	Lifestyle						
	Nissan Latio 1.5A (New 5-yr COE)	\$33,800	\$6,760 /yr	25-Mar-2008	1,498 cc	75,000 km	Sedan	Available
1 Single Owner Only! Amazing Condition With A Low Mileage Of 75k Km Done Only, This Car Is Ideal For Short Term Low Depreciation Drive Or For COE Renewal Due To Under Utilization, Serviced Regularly A...								
Posted: 17-Mar-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan								
	Nissan Latio 1.5A (New 5-yr COE)	\$30,800	\$6,160 /yr	25-Apr-2008	1,498 cc	-	Sedan	Available
Original Condition, 100% Loan Available, Car Ready For Viewing, Please Call Us Now For Viewing.								
Posted: 14-Mar-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan								
Compare	\$9,888	N.A	28-Mar-2008	1,498 cc	-	Sedan	Available	

# JIN AUTO SERVICES PTE LTD

Blk 14 #01-412 Defu Lane 10  
Singapore 539195  
Tel:62898126 Fax :62870590

*Not Allowed  
now  
1/5 \$8500/-  
10 day.*

Your ref :  
Our Ref :

Date: 21/3/2018

DEAR SIR/MADAM

ESTIMATED REPAIR COST FOR SJC 5298R NISSAN LATIO

NETT ITEM

QTY	UNIT	DESCRIPTION	REMARKS	NETT ITEM
1	1 PC	Bonnet	3uc	\$ 893.60 ✓
2	1 PC	BONNET INSULATOR	woqub	\$ 119.40 ✓
3	1 PC	Bonnet lock	ym	\$ 56.60 ✓
4	1 PC	BRACE PANEL	5uf	\$ 45.10 ✓
5	2 PCS	Horn	11	\$ 197.20 X
6	2 PCS	Front headlamp	one	\$ 744.00 ✓
7	1 PC	GRILLE	one	\$ 157.50 ✓
8	1 PC	GRILLE CLIPS	11	\$ 40.00 X
10	1 PC	Front bumper	DIS	\$ 456.30 ✓
11	1 PC	Front bumper clip (1 set)	rec	\$ 40.00 ✓
13	1 PC	Front bumper reinforcement	DO	\$ 446.30 ✓
14	1 PC	Front Bumper Sponge	711	\$ 215.30 ✓
15	2 PCS	Front bumper side retainer	5uf	\$ 47.20 ✓
16	1 PC	Front bumper lower skirt	11	\$ 776.00 X
17	1 PC	Front bumper badge	rec	\$ 50.70 ✓
18	2 PCS	Front fender	MSA o/s 3uc	\$ 1,270.00 ✓
19	2 PCS	Front fender inner shield	634.50 re/1011	\$ 202.60 ✓
20	1 PC	Support panel air duct	ym	\$ 80.40 ✓
21	1 PC	Front support panel	5uf	\$ 308.50 ✓
22	1 PC	wiper tank	11	\$ 225.40 X
23	1 PC	AIRCON CONDENSER	5uf/1011	\$ 658.20 ✓
24	1 PC	RADIATOR	pan/1011	\$ 687.40 ✓
25	1 PC	RADIATOR FAN MOTOR	11	\$ 456.30 X
26	1 PC	RADIATOR FAN COWLING	11	\$ 116.40 X
27	1 PC	RADIATOR BLADE	11	\$ 98.10 X
28	1 PC	RADIATOR SPARE TANK	Re	\$ 88.00 ✓
29	1 PC	Radiator Mounting Bracket	11	\$ 14.00 X
30	1 PC	REAR BOOT LID	5uf/3uc	\$ 787.50 ✓
		BAL C/F		\$ 9,278.00

	BAL B/F		\$ 9,278.00
31	1 PC	BOOTLID BADGE	net \$ 50.70 ✓
32	1 PC	REAR BOOT "LATI" EMBLEM 73.60	net 80.9 ✓
33		BOOTLID NUMBER PLATE CHROME	11 \$ 270.60 x
34	1 PC	REAR BOOT LID RUBBER	721 \$ 88.40 ✓
35	2 PC	REAR LH & RH LAMP	CR \$ 556.80 ✓
36	1 PC	REAR BUMPER 456.50	721 \$ 532.40 ✓
37	1 PC	REAR BUMPER CLIPS	net \$ 40.00 ✓
38	1 PC	REAR BUMPER SIDE RETAINER	net \$ 66.60 ✓
39	1 PC	REAR BUMPER SIDE RETAINER BIG	11 \$ 66.60 x
40	1 PC	REAR BUMPER LOWER SKIRT 554.60	721 \$ 588.00 ✓
41	1 PC	BOOT LOCK	721 \$ 132.00 ✓
42	1 PC	BOOT LOCK CATCH	11 \$ 63.70 x
43	1 PC	REAR END PANEL	4.5.10 \$ 434.40 ✓
44	1 PC	REAR END PANEL GARNISH	DE \$ 92.40 ✓
45	1 PC	Rear floor panel top board 495	CR \$ 509.80 ✓
			\$ 12,851.30
			\$ (1,285.13)
			\$ 11,566.17
	LESS 20%		9759.9
			2807.92
47	1 SET	REVERSE SENSOR	shub \$ 250.00 200
48	2 SET	SEALANT	11 \$ 80.00 x
49	Dismantle	SENSOR LABOUR	\$ 80.00 50
50		TOWING	\$ 80.00 50
51		SPRAY PAINTING FRONT PORTIONS	\$ 1,750.00 800
52		LABOUR CHARGE TO REMOVE AND RENEW FRONT PARTS	\$ 900.00 600
53		REMOVE AND REFIX AIRCON PARTS REFILL FREON GAS	\$ 160.00 100
54		CHECK WIRING	\$ 35.00 15
55		TO REMOVE AND REFIX CARPET, GARNISH, SEAT	\$ 120.00 80
56		CHECK WIRING (REAR)	\$ 35.00 15
57		TUFF KOTE	\$ 120.00 ✓
58		LABOUR CHARGE TO RENEW DAMAGE PARTS	\$ 960.00 900
59		TO SPRAY PAINTING FOR REAR (INCLUDE REAR DOORS)	\$ 1,500.00 1000
			\$ 17,636.17

16,351.04      3930  
 (117) 7-52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005275/UVBN2

Date: 04/04/2018

**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28854469DMA
Claimant Vehicle No :	SJC5298R	Insured Vehicle No :	SKX3765A
Date of Loss:	20/03/2018	Nature of Claim:	TP
		Claim No:	552913

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SJC5298R	Engine No:	HR15252482A
Make & Model:	NISSAN LATIO, 1.5 (A)	Chassis No:	JN1BAAC11Z0009279
Reg. Date:	22/02/2008 (Man. Year: 2007)	Odometer:	215050 km
Colour:	Brown		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,611.04	8,007.92	2,603.12	24.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,740.00	3,730.00	2,010.00	35.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,351.04</b>	<b>11,737.92</b>	<b>4,613.12</b>	<b>28.21</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,500.00</b>		
	(S\$) 16,351.04	8,500.00	7,851.04	48.02
+ GST 7.00/7.00% (S\$)	1,144.57	595.00	549.57	48.02
<b>Nett Amount (S\$)</b>	<b>17,495.61</b>	<b>9,095.00</b>	<b>8,400.61</b>	<b>48.02</b>

**INSPECTION**

Date of Assignment:	21/03/2018		
Date Inspected:	21/03/2018	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	10.0 days		

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 2 of 5

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2018)
<b>Parts:</b> 144	NISSAN LATIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJC5298R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	893.60 FL	*893.60 FL
2	1		*BONNET INSULATOR	Warped	119.40 FL	*119.40 FL
3	1		*BONNET LOCK	Twisted	56.60 FL	*56.60 FL
4	1		*BRACE PANEL	Bent	45.10 FL	*45.10 FL
5	2		*HORN	Not Necessary	197.20 FL	*- FL
6	2		*FRONT HEADLAMP	Cracked	744.00 FL	*744.00 FL
7	1		*GRILLE	Cracked	157.50 FL	*157.50 FL
8	1		*GRILLE CLIPS	Not Necessary	40.00 FL	*- FL
9	1		*FRONT BUMPER	Distorted	456.30 FL	*456.30 FL
10	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
11	1		*FRONT BUMPER REINFORCEMENT	Dented	446.30 FL	*446.30 FL
12	1		*FRONT BUMPER SPONGE	Torn	215.30 FL	*215.30 FL
13	2		*FRONT BUMPER SIDE RETAINER	Bent	47.20 FL	*47.20 FL
14	1		*FRONT BUMPER LOWER SKIRT	Repair	776.00 FL	*- FL
15	1		*FRONT BUMPER BADGE	Necessary	50.70 FL	*50.70 FL
16	1		*FRONT FENDER	O/s Buckled/N/s Repair	1,270.00 FL	*634.50 FL
17	2		*FRONT FENDER INNER SHIELD	Deformed/Torn	202.60 FL	*202.60 FL
18	1		*SUPPORT PANEL AIR DUCT	Twisted	80.40 FL	*80.40 FL
19	1		*FRONT SUPPORT PANEL	Bent	308.50 FL	*308.50 FL
20	1		*WIPER TANK	Not Necessary	225.40 FL	*- FL
21	1		*AIRCON CONDENSER	Bent/Punctured	658.20 FL	*658.20 FL
22	1		*RADIATOR	Punctured/Cracked	687.40 FL	*687.40 FL
23	1		*RADIATOR FAN MOTOR	Not Necessary	456.30 FL	*- FL
24	1		*RADIATOR FAN COWLING	Not Necessary	116.40 FL	*- FL
25	1		*RADIATOR BLADE	Not Necessary	98.10 FL	*- FL
26	1		*RADIATOR SPARE TANK	Deformed	88.00 FL	*88.00 FL
27	1		*RADIATOR MOUNTING BRACKET	Not Necessary	14.00 FL	*- FL
28	1		*REAR BOOT LID	Bent/Buckled	787.50 FL	*787.50 FL
29	1		*BOOTLID BADGE	Necessary	50.70 FL	*50.70 FL
30	1		*REAR BOOT LATIO EMBLEM	Necessary	80.90 FL	*73.60 FL
31	1		*BOOTLID NUMBER PLATE CHROME	Not Necessary	270.60 FL	*- FL
32	1		*REAR BOOT LID RUBBER	Twisted	88.40 FL	*88.40 FL
33	2		*REAR LH & RH LAMP	Cracked	556.80 FL	*556.80 FL
34	1		*REAR BUMPER	Distorted	532.40 FL	*456.30 FL
35	1		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
36	1		*REAR BUMPER SIDE RETAINER	Bent	66.60 FL	*66.60 FL
37	1		*REAR BUMPER SIDE RETAINER BIG	Not Necessary	66.60 FL	*- FL
38	1		*REAR BUMPER LOWER SKIRT	Torn	588.00 FL	*554.60 FL
39	1		*BOOT LOCK	Twisted	132.00 FL	*132.00 FL
40	1		*BOOT LOCK CATCH	Not Necessary	63.70 FL	*- FL
41	1		*REAR END PANEL	Badly Dented	434.40 FL	*434.40 FL
42	1		*REAR END PANEL GARNISH	Deformed	92.40 FL	*92.40 FL
43	1		*REAR FLOOR PANEL TOP BOARD	Cracked	509.80 FL	*495.00 FL
44	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
45	2		*SET SEALANT	Not Necessary	80.00 FS	*- FS	
			F=Franchise part. S=SpcNett. L=ListItemDisc.				
					<b>Sub Total (S\$)</b>	<b>13,181.30</b>	<b>9,959.90</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>2,570.26</b>	<b>1,951.98</b>
					<b>Total Parts (S\$)</b>	<b>10,611.04</b>	<b>8,007.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DISMANTLE SENSOR LABOUR	New	80.00	50.00
2	TOWING	New	80.00	50.00
3	SPRAY PAINTING FRONT PORTIONS	New	1,750.00	800.00
4	LABOUR CHARGE TO REMOVE AND RENEW FRONT PARTS	New	900.00	600.00
5	REMOVE AND REFIX AIRCON PARTS REFILL FREON GAS	New	160.00	100.00
6	CHECK WIRING	New	35.00	15.00
7	TO REMOVE AND REFIX CARPET,GARNISH,SEAT	New	120.00	80.00
8	CHECK WIRING (REAR)	New	35.00	15.00
9	TUFF KOTE	New	120.00	120.00
10	LABOUR CHARGE TO RENEW DAMAGE PARTS	New	960.00	900.00
11	TO SPRAY PAINTING FOR REAR (INCLUDE REAR DOORS)	New	1,500.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,740.00</b>	<b>3,730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >