

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7693Z**AAD1803-137***Not Authenik*
11 Lm @ 2850/

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7693Z

KL1LA69RJB078418

CHEVROLET

EPICA 2.0

17.3.2018

AIG**PART****LIST**

1	1	Front Shock Absorber Assy RH	\$	SH 216.17	X
2	1	Front Shock Absorber Top Mounting RH	\$	SH 48.32	X
3	1	Front Lower Arm RH	\$	SH 283.00	X
4	1	Front Knuckle Arm RH	\$	SH 230.00	X
5	1	Front Hub Unit	\$	SH 376.00	X
6	1	Front Fender RH	\$	Buc 837.60	
7	1	Front Fender Liner RH	\$	SH 47.00	X
8	1	Fender Insulation RH	\$	SH 39.00	X
9	1	Front Fender RR Bracket RH	\$	N 7.10	X
10	1	Front Fender Inner Wheel House Panel RH	\$	N 1,437.00	} X
11	1	Front Door RH	\$	N 1,133.00	
12	1	Front Door Glass Guide RH Chrome Moulding	\$	SH 60.00	
13	1	Front Door Outer Moulding	\$	SH 220.00	
14	1	Front Door Outer Handle	\$	SH 125.00	
15	1	Front Door Handle Support	\$	SH 3.00	
16	1	Front Door outer handle inner seal	\$	SH 89.15	
17	1	Front Door outer key lock	\$	SH 25.00	
18	1	Front Door Hinge Upper	\$	N 65.00	
19	1	Front Door Hinge Lower	\$	N 65.00	
20	1	Front Door inner lock	\$	N 586.00	
21	1	Front Door Inner Lock Latch RH	\$	N 206.00	
22	1	Front Door Check / Arrestor	\$	SH 67.50	
23	1	Front Door Weatherstrip RH	\$	SH 138.79	
24	1	Front Door glass channel weatherstrip	\$	SH 160.00	
25	1	Front Door inner trim board	\$	SH 455.69	
26	1	Front Door window glass	\$	SH 456.12	
27	1	Front Door Power Window Motor (Master) RH	\$	SH 284.97	
28	1	Front Door power window motor switch	\$	SH 145.00	
29	1	Front Door Window Regulator Gear RH	\$	SH 84.58	

Trans-cab Auto Services Pte Ltd

AAD1803-137

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7693Z

TOTAL	\$	7,890.99
10%	\$	789.10
	\$	7,101.89

Specical Nett

1 Set Front Bumper Fastener Clip	\$	<i>na</i>	24.00	✓
1 Set Front licence plate with holder	\$	<i>na</i>	192.00	X
1 Set Radiator Grille clip	\$	<i>na</i>	35.00	✓
1 Set Front Fender Liner clip	\$	<i>na</i>	30.00	X
1Set Rear Fender Inner Trim Clip LH	\$	<i>na</i>	30.00	X
1 Front door logo 'Trans-cab'	\$	<i>na</i>	80.00	X

TOTAL	\$	391.00
--------------	-----------	---------------

TOTAL PARTS	\$	7,492.89
--------------------	-----------	-----------------

To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
---	----	--------	------------

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	<i>4001</i>
---	----	----------	-------------

LABOUR

Putty and spray painting of the affected portion.	\$	3,200.00	<i>4001</i>
---	----	----------	-------------

Towing Fees.	\$	<i>na</i>	120.00	X
--------------	----	-----------	--------	---

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>na</i>	380.00	X
---	----	-----------	--------	---

To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	X
---	----	-----------	--------	---

To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	170.00	X
--	----	-----------	--------	---

To rust-proofing of the affected areas.	\$	170.00	<i>301</i>
---	----	--------	------------

Trans-cab Auto Services Pte Ltd**AAD1803-137**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7693Z

To check steering geometry and computer wheel alignment

\$ *~* 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ *~* 170.00 X

To transfer of door fittings, attachment and perform water seepage test.

\$ *~* 170.00 X

To transfer of fender fittings, attachment and perform water seepage test.

\$ *~* 170.00 X**TOTAL** \$ **8,660.00****Over All Total** \$ **16,152.89****Repair Days***10 Days**2 days*LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

AAD1803-137

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7693Z

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7693Z

KL1LA69RJBB078418

CHEVROLET

EPICA 2.0

17.3.2018

AIG**SUPPLEMENTARY**

		PART	LIST	
1	1	Front Bumper	\$	<i>Bu/no</i> 1,202.00 ✓
2	1	Front Bumper Retainer LH	\$	<i>D.1</i> 102.00 ✓
3	1	Headlamp RH	\$	<i>Gr</i> 816.00 ✓
4	1	Headlamp RH inner panel	\$	<i>n</i> 611.16 X
5	1	Front headlamp bracket	\$	<i>su</i> 85.00 X
TOTAL			\$	2,816.16
10%			\$	281.62
			\$	2,534.54

Specical Nett

1 Set	Front Bumper Fastener Clip	\$	<i>Repect</i> 24.00 X
1 Set	Front licence plate with holder	\$	<i>nn</i> 192.00 X
1 Set	Radiator Grille clip	\$	<i>nn</i> 35.00 X
1 Set	Front Fender Liner clip	\$	<i>nn</i> 30.00 X
TOTAL		\$	281.00
TOTAL PARTS		\$	2,815.54