

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7920T**AAD1803-135***Not Authorised*
11 Sep 8 2700

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB 7920T
 KL1LA69RJB109972
 CHEVROLET
 EPICA 2.0
 16.3.2018
China TP

PART**LIST**

1	1	Rear Bumper	\$	<i>Bur</i> 1,202.00 ✓
2	1	Rear Bumper Beam	\$	<i>R</i> 239.94 X
3	1	Rear Bumper Centre Absorber	\$	<i>Sn</i> 260.00 X
4	1	Rear Bumper Side Retainer RH	\$	<i>Dis</i> 68.76 ✓
5	1	Rear Bumper Side Retainer LH	\$	<i>Sn</i> 68.76 X
6	1	Rear Bumper Reflectors RH	\$	<i>Sn</i> 119.74 X
7	1	Rear Bumper Reflectors LH	\$	<i>Sn</i> 119.74 X
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i> 93.00 X
9	1	Rear End Panel Outer	\$	<i>R</i> 623.76 X
10	1	Rear End Panel Inner Trim	\$	<i>Sn</i> 263.84 X
11	1	Rear Luggage Floor Panel	\$	<i>R</i> 973.00 X
12	1	Rear Luggage Floor Panel Insulator	\$	<i>Sn</i> 63.50 X
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sn</i> 378.00 X
14	1	Bootlid	\$	<i>Bur</i> 973.00 X
15	1	Bootlid inner trim board	\$	<i>Sn</i> 400.00 X
16	1	Bootlid Weatherstrip	\$	<i>Sn</i> 344.28 X
17	1	Bootlid Lock - Top	\$	<i>R</i> 466.56 X
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>Sn</i> 120.62 ✓
19	1	Bootlid Logo	\$	<i>Sn</i> 138.84 ✓
20	1	Bootlid 'EPICA LT' Badge	\$	<i>Sn</i> 119.84 ✓
21	1	Bootlid Reflector Centre	\$	<i>Sn</i> 217.97 X
22	1	Bootlid Reflector RH	\$	<i>CMS</i> 128.40 ✓
23	1	Bootlid Reflector LH	\$	<i>Sn</i> 128.40 X
24	1	Rear Tail Lamp RH	\$	<i>CMS</i> 479.30 ✓
25	1	Rear Tail Lamp LH	\$	<i>Sn</i> 479.30 X
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00 X
27	1	Rear Fender RH	\$	<i>R</i> 1,145.00 X
28	1	Rear Fender Inner Trim RH	\$	<i>Sn</i> 418.44 ✓
29	1	Rear Fender LH	\$	<i>R</i> 1,145.00 X

Trans-cab Auto Services Pte Ltd

AAD1803-135

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7920T

30	1	Rear Fender Inner Trim LH	\$	Sn 418.44 X
----	---	---------------------------	----	-------------

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Specical Nett

1	1Set	Bootlid inner trim board Clip	\$	na 40.00 X
2	1Set	Rear Bumper Parking Sensor	\$	na 300.00 ✓
3	1Set	Rear Bumper Fastener Clip	\$	na 44.00 ✓
4	1Set	Rear Fender Inner Trim Clip LH	\$	na 30.00 X
5	1Set	Rear Bumper End Dust Cover Clip	\$	na 30.00 X
6	1	Rear Boot Sticker 'Trans-cab'	\$	na 30.00 ✓
7	1	Rear Boot Sticker '6555-3333'	\$	na 30.00 ✓
8	1	Rear Exhaust Mounting	\$	Sn 10.00 X
9	2	Rear Windscreen Sealant	\$	na 80.00 X
10	1	Rear Windscreen Inner Sponge Seal	\$	na 100.00 X
11	1	Spare Tyre	\$	Sn 180.00 X
12	1	Spare Wheel Rim	\$	Sn 126.74 X

TOTAL	\$	1,000.74
--------------	-----------	-----------------

TOTAL PARTS	\$	12,437.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,500.00	400
----	----------	-----

To Check Electrical Lighting Concerned.

\$	170.00	200
----	--------	-----

To Rust-Proofing Of The Affected Areas.

\$	170.00	300
----	--------	-----

Putty And Spray Painting Of The Affected
Portion.

\$	3,200.00	400
----	----------	-----

To reinstall rear bumper parking sensor.

\$	170.00	600
----	--------	-----

Trans-cab Auto Services Pte Ltd**AAD1803-135**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7920TTo transfer of end panel fittings and conduct
water seepage test.\$ *nn* 170.00 *X*To transfer of boot fittings and conduct water
seepage test.\$ 170.00 *601*To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair.\$ *nn* 380.00 *X*To check steering geometry and computer
wheel alignment\$ *nn* 220.00 *X*

\$ **8,150.00**

TOTAL \$ 20,587.43

(Lump Sum)**Repair Days***10 Days**2 1/2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: