## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO: SHA 3830B

MAKE

MODEL : HYUNDAI i40

LTD AIGHSIA - CPP)

DATE 17/3/2018 (SO

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper		PX	\$ 603.60	
	Rear Bumper Clips 10 pcs		4/14	\$ 22.00	
	Rear Wheel Hup-Cap (LH)		aux	\$ 150.70	
	SUB TOTAL			\$ 776.30	1
	LESS 20%			\$ 155.26	l
	DISCOUNTED TOTAL			\$ 621.04	1
	DISCOUNTED TO THE				
	Rear Bumper Advertisement Logo Rear Bumper Rubber Mat		100	\$ 50.00 \$ × 50.00	N
	Rear Fender Advertisement Logo (LH/RH)	-	\$ 100.00	\$ 200.00	N
	Rear Door Comfortdelgro & Apps Sticker (LH)		WH	\$ ¥ 80.00	N
	Front Door Coloured Comfort Logo (LH)		Kel	\$ 75.00	N
				\$ 455.00	1
					1
	Labour Charge				
	Panel Beating- Repair Fender			\$ -500.00	1
	Spray Painting Charge	Listen	1,	\$ 750.00	1
	Tuff Kote PIP DR	2001		\$ 50.00	
	Remove/Refix Reverse Sensor	1	1 XIS	\$ 120.00	×
		Park	of pools	\$ 120.00	1
	Rear Wheel Alignment	Down	MB)	\$ 120.00	ľ
		10/0/	A 0	6 1540.00	+
	TOTAL LABOUR	CNO	0	\$ 1,540.00	+
	EGENALEE TOTAL	2W	days	6 2 (1 ( 0 4	1
	ESTIMATE TOTAL		10	\$ 2,616.04	-
	LKK Auto Consultants hence notify	171	RIZOLY		
	To see every before/after spray painting	101	8/2018		
	display damaged part(s) during resurvey	161			
	- arts prices are subject to confirmation				
	hird party survey is on a "Without Prejudice" basis     hip diegal modification(s) is allowed				
	mentary item(s) must be resurveyed and				
	and bject to final approval from Insurance Company				
	- knowledged by Repairer				
	Signature:				
	1:e:				

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.