

# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKE2290J/1803061

19<sup>th</sup> March 2018

The Manager  
Motor Claim Department  
AXA Insurance Pte Ltd  
8 Shenton Way,  
#27-01 AXA Tower  
Singapore 068811

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized  
LKK  
L/S#  
4 days  
29/3/18

Date of Accident : 18<sup>th</sup> March 2018  
Location : Johor Immigration Checkpoint To Singapore  
Third Party Claim Vehicle No : SKE 347 T  
Repair Cost For Vehicle No : SKE 2290 J Jaguar XF 3.0

## Estimate Supply of Parts & Labours

| No. | Particulars                        | Qty   | Price    | Amounts       |
|-----|------------------------------------|-------|----------|---------------|
| 1   | Rear bumper fascia                 | 1     | 2,160.00 | \$ 2,160.00 ✓ |
| 2   | Rear bumper sensor                 | 4     | 192.00   | \$ 768.00 ?   |
| 3   | Rear bumper bracket L&RH           | 2     | 56.00    | \$ 112.00 ?   |
| 4   | Rear bumper reinforcement          | 1     | 1,376.00 | \$ 1,376.00 ? |
| 5   | Rear bumper sponge                 | 1     | 136.00   | \$ 136.00 ?   |
| 6   | Rear end panel                     | 1     | 1,552.00 | \$ 1,552.00 ? |
| 7   | Rear end panel inner garnish       | 1     | 320.00   | \$ 320.00 ✓   |
| 8   | Rear end panel inner garnish clips | 1 set | 50.00    | \$ 50.00 ✓    |
| 9   | Rear boot cover w/strip            | 1     | 128.00   | \$ 128.00 ✓   |
| 10  | Rear end panel sealer (s/net)      | 1     | 80.00    | \$ 80.00 ✓    |
|     |                                    |       |          | \$ 6,682.00   |

## Labour Charges :-

|                                                                                                                               | Amounts       |
|-------------------------------------------------------------------------------------------------------------------------------|---------------|
| Cut out, renew, knocking & welding rear end panel, remove & install all damage parts, straighten rear chassis & re-align body | \$ 980.00 450 |
| Tuff-kote on damage parts                                                                                                     | 11 \$ 40.00 X |
| Spray painting on damage parts                                                                                                | \$ 880.00 600 |
| Remove & install rear bumper sensor                                                                                           | \$ 100.00 50  |
| Check all lighting after repairs                                                                                              | \$ 80.00 20   |
| Diagnostic & reset rear bumper sensor                                                                                         | \$ 300.00 100 |
| Labour Charge                                                                                                                 | \$ 2,380.00   |
| Total Amount                                                                                                                  | \$ 9,062.00   |
| GST will be reflected in the final bills.                                                                                     |               |