

ASS. REC. BY:

REF: CS/MS(18005304/Kvbnz) Special Instruction:

SURVIVOR

ASSIGNMENT (Office)

merimen

From (Person):

Fievel Foo

of

msch

Date/Time: 21032018 8:01am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 7038E

Insured:

YN 2879Z

at Workshop m/s

Cheng Hoe Motor

Tel:

6765 642

of

Blk 1019 Yishun Ind Park A #01-374

Policy No:

B28669813MKC

Claim No:

502719

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16032018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 21032018 10:03am

Person Contacted:

Efreda

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKU 7038E - X

YN 2879Z - CC3 / MSG / 7009280 / Ugher

DUA: 120317

2/4/18

Send preli. revised by merimen

2616 @ 2931.20 Confirm Time (Red 540.56, 1690)

ASS. REC. BY:

REF: *MSG*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s *Cheng Hoe*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *04* days Res.: Yes or NoLum Sum: *1-B.1* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SKU 70385* Yr Regn: *08, 15*Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: *Mazda 3* C.C. *1.4 PB*Colour: *M-Black* A/C: Insured / Std / NI / NASp. Reading: *60766* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JM 8BM 42 A8 E0 814075*Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: *205/60R16*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. *7* mmL/Bal. *7* mmD.O.A. *16/3/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

OLS body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/3 *File pass to Catherine**[Signature]**26/6/2018*

RECEIVED 26 JUN 2018

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) *26/6 - typist*Days Of Repair: *4*Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

*merimen**2931.20**210*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18005304/Kvb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 21-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 2879Z	Veh. Inspected	SKU 7038E
Policy No.	B28669813MKC	Coverage (\$)	0.00
Claim No.	552719	Excess (\$)	0.00
Assign From	MERIMEN (FIEVEL FOO)	Assign Date	21/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/03/2018	Inspection Date
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	19 Mar 2018		21 Mar 2018 08:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

AW ZHAN JIE(OU ZHANJIE), ID: S8035997G

Main Claimant:

SKU7038E

Vehicle Reg. No.:

TP / 552719

Claim Type:

Y2879Z

Vehicle Reg. No. (Insured):

Cheng Hoe Motor Pte Ltd (Yishun) Bk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142

Repairer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]

Handling Insurer:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/03/2018]

Adjuster:

NASIRUDEEN BIN SHAUL HAMEED (), NRIC: S1595741G, Tel: +6596874075

Driver/Custodian (Insured):

request Kenneth Kong for survey

Adj Asg. Remarks:

View All

Compose Case Mail

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

21/3/2018 @ 10:08am
Elected vehicle in

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Fievel Foo Wenya	Date: 02 Apr 2018
Preliminary Advice	

Insured Vehicle No	: YN2879Z		
TP Vehicle No	: SKU7038E	Accident Date	: 16/03/2018
Make	: MAZDA 3	Assignment Date	: 21/03/2018
Date of Inspection	: 28/03/2018	Est. Duration of Repair	: 4.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,471.76
Revised Amount	:S\$	2,931.20
Check Items (Estimated)	:S\$	300.56
Total	:S\$	3,231.76
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐	The vehicle is economical/not economical for repair.
☒	The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5997G
Vehicle Details	
Vehicle No.:	SKU7038E
Vehicle to be Exported:	Yes
Intended De-registration Date:	16 Mar 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	P520299739
Chassis No.:	JM6BM42A8G0314075
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,005.00
Original Registration Date:	12 Aug 2015
First Registration Date:	12 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$12,005.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Aug 2025
PARF Rebate Amount:	\$9,003.00
Intended COE Rebate Details	
COE Expiry Date:	11 Aug 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,209.00
COE Rebate Amount:	\$41,612.00
Total Rebate Amount:	\$50,615.00

The information contained herein is correct as at 16 Mar 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

Estimate No: ES1890316

Date: 28 Mar 2018

Policy No: MP306908

Veh Reg No: SKU7038E

Make/Model: MAZDA MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 16/03/2018

TP Veh Reg No: YN2879Z

Chassis No: JM6BM42A8G0314075

Engine No: P520299739

Reg. Date: 12/08/2015

Estimate Repair Cost to Vehicle No :SKU7038E

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT RH DOOR	1,143.00	1 PC	1,143.00	✓
2 FRONT RH DOOR INNER RUBBER	106.00	1 PC	106.00	✓
3 FRONT RH DOOR TOP MOULDING	64.80	1 PC	64.80	✓
4 REAR RH DOOR	996.00	1 PC	996.00	✓
5 REAR RH DOOR INNER RUBBER	120.70	1 PC	120.70	✓
6 REAR RH DOOR TOP MOULDING	84.20	1 PC	84.20	✓
			2,514.70	
	Less 20%		502.94	2,011.76
Labour				
7 TO REMOVE AND REFIX FRT & REAR RH DOORS, TRANSFER DOOR ATTACHMENT, ALL LOCK ASSY, KNOCK AND REPAIR RH DOOR PILLAR AND RE-ALIGN TO SAME	600.00	1 LA	600.00	480
8 REMOVE AND REFIX FRT & RR RH DOOR GLASS AND CHECK CENTRAL LOCKING AND POWER MIRROR	120.00	1 LA	120.00	✓
9 PUTTY AND RESPRAY ON FRT & RR RH DOORS, RH DOOR PILLAR AND ALL AFFECTED AREAS	680.00	1 LA	680.00	560
10 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,460.00	1,460.00
			Total	S\$ 3,471.76
			Add GST @ 7%	243.02
			Total Amount Payable	S\$ 3,714.78

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005304/KVBN2

Date: 27/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28669813MKC
Claimant Vehicle No :	SKU7038E	Insured Vehicle No :	YN2879Z
Date of Loss:	16/03/2018	Nature of Claim:	TP
		Claim No:	552719

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU7038E	Engine No:	P520299739
Make & Model:	MAZDA 3, 1.5 SEDAN L SP.6EAT (A)	Chassis No:	JM6BM42A8G0314075
Reg. Date:	12/08/2015 (Man. Year: 2015)	Odometer:	60766 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,011.76	1,711.20	300.56	14.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	1,220.00	240.00	16.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,471.76	2,931.20	540.56	15.57
+ GST 7.00/7.00% (S\$)	243.02	205.18	37.84	15.57
Nett Amount (S\$)	3,714.78	3,136.38	578.40	15.57

INSPECTION

Date of Assignment:	21/03/2018	
Date Inspected:	28/03/2018	Inspected At:
		Cheng Hoe Motor Pte Ltd (Yishun)
		Blk 1019 #01-374/382, Yishun Industrial Park A
		Singapore 768761
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2018)
Parts: 143	MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU7038E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent	1,143.00 FL	*1,143.00 FL
2	1		*FRONT RH DOOR INNER RUBBER	Serviceable	106.00 FL	*- FL
3	1		*FRONT RH DOOR TOP MOULDING	Serviceable	64.80 FL	*- FL
4	1		*REAR RH DOOR	Bent	996.00 FL	*996.00 FL
5	1		*REAR RH DOOR INNER RUBBER	Serviceable	120.70 FL	*- FL
6	1		*REAR RH DOOR TOP MOULDING	Serviceable	84.20 FL	*- FL
					Sub Total (\$\$)	2,514.70
					- List Item Discount on L Items 20.00/20.00% (\$\$)	502.94
					Total Parts (\$\$)	2,011.76
						1,711.20

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.