

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4,  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 53350112A  
GIFTED CREATIONS  
NO

SINGAPORE  
TEL : FAX :  
PH :  
ATTN :

Term:

## ESTIMATE BILL

Number : EB00004773  
Date : 21/03/2018  
Case No : AD00009622  
Vehicle No : SJL9011C  
Chassis : KMHDU41BR9U63448  
Year of Mfr : 2008  
Policy No : 5096554054  
Model : HYUNDAI HD  
AVANTE 1.6 A

| Sn                                   | DESCRIPTION                              | QTY | U PRICE | DISC | AMOUNT   |
|--------------------------------------|------------------------------------------|-----|---------|------|----------|
| 1                                    | BOOTLID                                  | 1.0 | 985.00  | 20   | 788.00   |
| 2                                    | BOOTLID LOGO - S                         | 1.0 | 27.00   | 20   | 21.60    |
| 3                                    | BOOTLID LOGO - AVANTE                    | 1.0 | 31.00   | 20   | 24.80    |
| 4                                    | BOOTLID EMBLEM                           | 1.0 | 29.00   | 20   | 23.20    |
| 5                                    | TAIL LAMP LH                             | 1.0 | 282.00  | 20   | 225.60   |
| 6                                    | TAIL LAMP RH                             | 1.0 | 282.00  | 20   | 225.60   |
| 7                                    | TAIL LAMP CLIP LH                        | 4.0 | 3.50    | 20   | 11.20    |
| 8                                    | TAIL LAMP CLIP RH                        | 4.0 | 3.50    | 20   | 11.20    |
| 9                                    | TAIL LAMP PANEL LH                       | 1.0 | 175.00  | 20   | 140.00   |
| 10                                   | END PANEL                                | 1.0 | 581.00  | 20   | 464.80   |
| 11                                   | END PANEL TOP GARNISH                    | 1.0 | 52.00   | 20   | 41.60    |
| 12                                   | REAR BUMPER WITH RETAINER                | 1.0 | 447.00  | 20   | 357.60   |
| 13                                   | REAR BUMPER REINFORCEMENT                | 1.0 | 270.00  | 20   | 216.00   |
| 14                                   | REAR BUMPER SPONGE                       | 1.0 | 129.00  | 20   | 103.20   |
| 15                                   | REAR BUMPER BRACKET RH                   | 1.0 | 79.00   | 20   | 63.20    |
| 16                                   | REAR BUMPER BRACKET LH                   | 1.0 | 79.00   | 20   | 63.20    |
| 17                                   | REAR FENDER INNER SHIELD RH              | 1.0 | 27.00   | 20   | 21.60    |
| 18                                   | REAR FENDER INNER SHIELD CLIP RH         | 8.0 | 3.50    | 20   | 22.40    |
| 19                                   | REAR RADIO ANTENNA                       | 1.0 | 94.00   | 20   | 75.20    |
| List Price - Parts Sub Total         |                                          |     |         |      | 2,900.00 |
| 20                                   | REAR FENDER LH - REPAIR                  | 1.0 |         |      |          |
| 21                                   | REAR FENDER RH - REPAIR                  | 1.0 |         |      |          |
| 22                                   | SPARE TYRE PANEL - REPAIR                | 1.0 |         |      |          |
| 23                                   | REVERSE SENSOR                           | 1.0 | 280.00  | 0    | 280.00   |
| Special Nett Price - Parts Sub Total |                                          |     |         |      | 280.00   |
| Parts Total                          |                                          |     |         |      | 3,180.00 |
| 24                                   | LABOUR TO REMOVE & REFIT NECESSARY PARTS | 1.0 | 900.00  | 0    | 900.00   |
| 25                                   | SPRAY PAINT ON THE AFFECTED AREAS        | 1.0 | 900.00  | 0    | 900.00   |
| 26                                   | ANTI-RUST COATING                        | 1.0 | 250.00  | 0    | 250.00   |
| 27                                   | WIRING                                   | 1.0 | 80.00   | 0    | 80.00    |
| 28                                   | TO REMOVE & REFIT REVERSE SENSOR         | 1.0 | 150.00  | 0    | 150.00   |
| Labour 1 Sub Total                   |                                          |     |         |      | 2,280.00 |

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE \* Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

AUTHORISED SIGNATURE

\* N = Item not subjected to GST

Acknowledged by Repairer

Signature:

Date:

Page 1 of 2

Issued by : Anysia

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4,  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 53350112A  
GIFTED CREATIONS  
NO

SINGAPORE  
TEL : FAX :  
PH :  
ATTN :

## ESTIMATE BILL

Number : EB00004773  
Date : 21/03/2018  
Case No : AD00009622  
Vehicle No : SJL9011C  
Chassis : KMH DU41BR9U63448  
Year of Mfr 2008  
Policy No 5096554054  
Model : HYUNDAI HD  
AVANTE 1.6 A

Term:

| Sn                                                                              | DESCRIPTION | QTY | U PRICE     | DISC | AMOUNT   |
|---------------------------------------------------------------------------------|-------------|-----|-------------|------|----------|
|                                                                                 |             |     |             |      |          |
| SINGAPORE DOLLARS : FIVE THOUSAND EIGHT HUNDRED FORTY-TWO AND CENTS TWENTY ONLY |             |     | Less Excess |      | 0.00     |
|                                                                                 |             |     | SUBTOTAL    |      | 5,460.00 |
|                                                                                 |             |     | GST 7.00%   |      | 382.20   |
|                                                                                 |             |     | TOTAL       |      | 5,842.20 |

Date of accident : 21/03/2018 07:30 AM. Place : SLIP ROAD OF BUKIT TIMAH ROAD FROM CTE

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE