

INS. CASE OWNER:

Irene

CC6/CTI18005309 / Aes3

LKK:

IDAC:

Surveyor:

AARAN

DOI:

20/03/18

Date / Time:

20/03/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKN 4726J

Claim No.:

SNM19001493C02

Name of Insured:

LIM LI BENG

Policy No.:

DMPCCN3051201700

Insured Tel No.:

HP: 9682 3002

Make / Model:

TOYOTA ESTIMA AERAS 2.4A

Excess Sec II :\$

D.O.A: 16/03/18

Place of Accident:

WOODLANDS TOWARDS MALAYSIA
CAUSEWAY

Is driver the owner?

(YES/NO)

Nature of Accident:

If NO, Driver Name / Age: LIM KOK UEN 77

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Driver Tel No.:

9339 8226

(V/L YES / NO)

Insured Liability:

Final ? Yes / No

SKX 1884C



INSRS:

WSP: MG Solutions

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

20/03/18 (Ashur)

SKX 1884C - X, SKN 4726J - X
*Paddy Gst & PA.

OID REPORTED NO ACCIDENT.

PENDING EVIDENCE FROM TP.

Email WSP for TO REQUEST FOR EVIDENCE.

CTI HERE REQUEST TO SUMMIT "Up" map.

TP SUBMITTED LOD VIA SOLICITOR.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

\$

Loss of Rental (LOR):

\$

(\$

(days)

Loss of Use (LOU):

\$

(\$

x

days)

Loss of Income (LOI):

\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent)

Legal Cost

\$

Total:

\$

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

Name 1:

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

1) Claim status: Normal/Reject/Private Settle /wp

2) Report Format:

3) Survey fee:

TP

-350

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

31/08/12

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKX1884C Yr Regn: 2008/Re.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suban Legacy. C.C. 1994

Colour: White. A/C: Insured / Std / NI / NA

Sp. Reading: 137298. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JFIBL5K5586038490.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R18.

R: 225/45R18.

BS / DUN / EXNOVA ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 20/03/18.

Survey held at: MG Solution.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP China.
	45:19,500 (RED: +5,099.44 537.1)
	MV: 171C
	PV: 11K
	Nett: 61C.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photos: _____

Others: _____

TOTAL

Report Format: _____

Lump Sum / I.B.I.: (\$ _____)

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18005309/Aes3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 21-03-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKN 4726J	Veh. Inspected	SKX 1884C	
Policy No.	DMPCSN3091201700	Coverage (\$)	0.00	
Claim No.	SNM18D01493C02	Excess (\$)	0.00	
Assign From		Assign Date	21/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	16/03/2018	Inspection Date	20/03/2018	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: CHINA TAIPING	DATE	: 19/03/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SKX1884C		
MODEL	: SUBARU LEGACY SEDAN 2.0		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 16-Mar-18
		TIME	: 12:45HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

1	BOOT LID <i>Buckled</i>	1	\$	780.00	\$	780.00	✓
2	BOOT LID LOGO <i>new</i>	1	\$	64.60	\$	64.60	✓
3	BOOT LID EMBLEM 'SUBARU' <i>new</i>	1	\$	49.40	\$	49.40	✓
4	BOOTLID TOP LOCK <i>Repld</i>	1	\$	210.00	\$	210.00	✓
5	BOOT LID LOWER LOCK <i>Repld</i>	1	\$	55.00	\$	55.00	✓
6	BOOT LID HINGE <i>new</i>	2	\$	78.00	\$	156.00	✓
7	BOOT LID WEATHERSTRIP <i>new</i>	1	\$	180.00	\$	180.00	✓
8	BOOT LID OUTER GARNISH <i>cracked</i>	1	\$	664.00	\$	664.00	✓
9	REAR BUMPER <i>Repld</i>	1	\$	755.30	\$	755.30	✓
10	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$	52.00	\$	104.00	✓
11	REAR BUMPER SIDE GARNISH <i>new</i>	2	\$	92.00	\$	184.00	✓
12	REAR BUMPER REINFORCEMENT <i>Bent</i>	1	\$	366.80	\$	366.80	✓
13	REAR BUMPER TOP BEAM <i>Bent</i>	1	\$	164.30	\$	164.30	✓
14	TAIL LAMP <i>cracked</i>	2	\$	570.00	\$	1,140.00	✓ 924.
15	TAIL LAMP LOWER BRACKET <i>new</i>	2	\$	76.00	\$	152.00	✓
16	REAR END PANEL <i>Repld</i>	1	\$	486.40	\$	486.40	✓
17	REAR END PANEL TOP GARNISH <i>Repld</i>	1	\$	185.00	\$	185.00	✓

TOTAL PRICE \$ 5,696.80

LESS 20% \$ 1,139.36

444140
335792

SUB TOTAL PRICE \$ 4,557.44

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>not in</i>	1	\$ 50.00	\$ 50.00
2	WHOLE CAR STICKERS <i>new</i>	1	\$ 1,400.00	\$ 1,400.00
3	BOOT LID EMBLEM <i>new</i>	1	\$ 60.00	\$ 60.00
4	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
5	TAIL LAMP CLIP <i>new</i>	1	\$ 20.00	\$ 20.00
6	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 22.00	\$ 22.00
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00
8	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00

TOTAL \$ 1,912.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,200.00	600	
2	TO SPRAY PAINT AFFECTED AREA	\$1,000.00	700	
3	TUFF COAT	\$200.00	X.	
4	WIRING CHECK	\$50.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$180.00	20	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$150.00	50	
7	REMOVE AND REFIX PETROL TANK TO FACILITATE FENDER REPLACEMENT	\$100.00	X	
8	TRANSFER BOOTLID MECHANISM	\$100.00	X	
9	CONDUCT WATER LEAKAGE TEST	\$150.00	X.	

TOTAL

\$3,130.00

1400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and after spray painting.
- To display car in a safe area during resurvey.
- Parts provided are subject to inspection and approval by the Repairer.
- Third party's liability is not covered by the Insurance Company.
- No illegal modifications are allowed.
- Supplemental work should be resurveyed and is subject to final approval by the Insurance Company.

ESTIMATE REPORT

Acknowledged by Repairer:

Signature:

Date:

TOTAL PARTS COST : \$ 6,469.44

TOTAL LABOUR COST : \$ 3,130.00

TOTAL REPAIR COST : \$ 9,599.44

Adrian Lij
4/5 20/03/18.
04 days
Total: \$667.92
c/s 4.51c



APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Year Coe Renewal Toyota Wish 1.8A



\$2800 Downpayment Monthly
From \$668 Onwards. Lowest
3.68%PA 12GV Cars Financing
GV Credit Pte Ltd StarAd



**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997

[VIEW OUR CARS](#)

Browse by Category

Sort by Date Posted

20 results/page

4 vehicles

Legacy

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Legacy	Any	Any	2008	Any	Any	Any	Available
	Subaru Legacy 2.5A GT	\$21,000	N/A	27-Aug-2008	2,457 cc	170,000 km	Luxury	Available
A Great Car Not To Be Missed. Regularly Serviced. Very Good Condition. Well Maintained Interior. Sporty Red With Black Interior. BodyKit Which Makes It Much More Sporty Than Other Units In The Market....								
Posted: 07-Feb-2018 Tags: 2008 Subaru Legacy, Subaru Legacy, Subaru, Legacy, Used Subaru								
	Subaru Legacy 2.0R	\$16,988	\$11,230 /yr	20-Oct-2008	1,994 cc	162,324 km	Luxury	Available
Well Maintained And Serviced By Pro-Subaru Workshop, Powerful And Smooth Gearbox, Brembo Brakes, Price Slightly Negotiable.								
Posted: 19-Mar-2018 Tags: 2008 Subaru Legacy, Subaru Legacy, Subaru, Legacy, Used Subaru								
	Subaru Legacy Wagon 2.5A GT	\$20,800	\$9,380 /yr	23-Oct-2008	2,457 cc	140,000 km	Stationwagon	Available
Safe Buy, 4 Months Ago Changed All Oil Gaskets, So Engine Is Tip Top And Dry, Good Gearbox As Car Not Abused, Changed Maf Sensor, 2 Sensors, Car Does Not Lose Oil Or Water, Have All Repair Receipts Of ...								
Posted: 06-Mar-2018 Tags: 2008 Subaru Legacy, Subaru Legacy, Subaru, Legacy, Used Subaru								
	Subaru Legacy Wagon 2.5A GT	\$23,999	\$11,290 /yr	29-Dec-2008	2,457 cc	137,000 km	Stationwagon	Available
6 Months Warranty On Gearbox. Must Sell!								
Posted: 15-Feb-2018 Tags: 2008 Subaru Legacy, Subaru Legacy, Subaru, Legacy, Used Subaru								

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Legacy, Legacy Singapore, used Legacy Singapore, used Legacy, used vehicles Singapore or even buy used Legacy Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tin

- About Us
- Careers
- Contact Us
- Sitemap

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2976J
Vehicle Details	
Vehicle No.:	SKX1884C
Vehicle to be Exported:	Yes
Intended De-registration Date:	20 Mar 2018
Vehicle Make:	SUBARU
Vehicle Model:	LEGACY SEDAN 4DR 2.0R 4AT AWD ABS
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	EJ20D356753
Chassis No.:	JF1BL5K558G038490
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$20,866.00
Original Registration Date:	31 Dec 2008
First Registration Date:	31 Dec 2008
Transfer Count:	4
Actual ARF Paid:	\$20,866.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Dec 2018
PARF Rebate Amount:	\$10,433.00
Intended COE Rebate Details	
COE Expiry Date:	30 Dec 2018
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$12,001.00
COE Rebate Amount:	\$589.00
Total Rebate Amount:	\$11,022.00

The information contained herein is correct as at 20 Mar 2018

OK

Shirley Hiew (LKK Auto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Friday, 23 March 2018 4:01 PM
To: Shirley Hiew (LKK Auto)
Subject: RE: Direct Settlement - Accident Involving SKN4726J (OI : CTI - SNM18D01493C02) AND SKX1884C (TP : LKK REF - CC6/CTI18005309/Aes3) on 16/03/2018
Attachments: leeSZ_SNM18D01493C02-SKN4726J-
LKKDirectSettlementAccidentLtr_CLCR95.922.pdf; MJAS18037152-SKN4726J.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6181
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Thursday, 22 March, 2018 10:46 AM
To: Claims Dept of CTI; Irene Tay; Lucas Lee; Asher Sng (LKKAuto)
Cc: Admin A; Vic (LKKAuto)
Subject: Direct Settlement - Accident Involving SKN4726J (OI : CTI - TBA) AND SKX1884C (TP : LKK REF - CC6/CTI18005309/Aes3) on 16/03/2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SKX 1884C at M/s MG Solution Pte Ltd - Kaki Bukit.

Enclosed for your perusal is:
- TP GIA report

We will revert preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 13 April 2018 11:56 AM
To: 'MG Solution'
Subject: ACCIDENT INVOLVING SKX 1884C & SKN 4726J ON 16/03/2018
Attachments: OI SKETCH PLAN.pdf

Without Prejudice

Your Ref: SKX 1884C
Our Ref: CC6/CTI18005309/Aea3

Dear Sirs,

ACCIDENT INVOLVING SKX 1884C & SKN 4726J ON 16/03/2018

We refer to the above matter.

Please be informed that liability is unclear for this matter. Our insured driver reported **NO COLLISION / NO ACCIDENT**. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of **video footage/witness statement/scene photos**(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

B1k 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18005309/Aea3q2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 30-08-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKN 4726J	Veh. Inspected	SKX 1884C
Policy No.	DMPCSN3091201700	Coverage (\$)	0.00
Claim No.	SNM18D01493C02	Excess (\$)	0.00
Assign From		Assign Date	20/03/2018
2. Vehicle Particulars & Condition			
Make & Model	SUBARU LEGACY	c.c	1994
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JF1BL5KS58G038490	Colour	WHITE
Odometer	137298	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R18	GOODYEAR	6 mm
L/H Front Tyre	225/45 R18	GOODYEAR	6 mm
R/H Rear Tyre	225/45 R18	GOODYEAR	6 mm
L/H Rear Tyre	225/45 R18	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/03/2018	Inspection Date	20/03/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 1884C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	BUCKLED	780.00	780.00
1	BOOT LID LOGO	NECESSARY	64.60	64.60
1	BOOT LID EMBLEM 'SUBARU'	NECESSARY	49.40	49.40
1	BOOTLID TOP LOCK	DAMAGED	210.00	210.00
1	BOOT LID LOWER LOCK	NOT NECESSARY	55.00	-
2	BOOT LID HINGE @\$78.00	NOT NECESSARY	156.00	-
1	BOOT LID WEATHERSTRIP	CUT	180.00	180.00
1	BOOT LID OUTER GARNISH	CRACKED	664.00	664.00
1	REAR BUMPER	DEFORMED	755.30	755.30
2	REAR BUMPER SIDE RETAINER @\$52.00	NECESSARY	104.00	104.00
2	REAR BUMPER SIDE GARNISH @\$92.00	NOT NECESSARY	184.00	-
1	REAR BUMPER REINFORCEMENT	BENT	366.80	366.80
1	REAR BUMPER TOP BEAM	BENT	164.30	164.30
2	TAIL LAMP @\$570.00	CRACKED	1,140.00	924.00
2	TAIL LAMP LOWER BRACKET @\$76.00	NOT NECESSARY	152.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	486.40	-
1	REAR END PANEL TOP GARNISH	DEFORMED	185.00	185.00
	LESS 20% DISCOUNT		-1,139.36	-889.48
			4,557.44	3,557.92
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	WHOLE CAR STICKER (SN)	NECESSARY	1,400.00	400.00
1	BOOT LID EMBLEM (SN)	NECESSARY	60.00	60.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	TAIL LAMP CLIP (SN)	NECESSARY	20.00	20.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	22.00	10.00
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	120.00	-
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			1,912.00	710.00

Report Ref No. CC6/CTI18005309/Aea3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING ,REMOVAL AND REPLACING PARTS INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,200.00	600.00
	TO SPRAY PAINT AFFECTED AREA.		1,000.00	700.00
	TUFF COAT.	NOT NECESSARY	200.00	-
	WIRING CHECK.		50.00	30.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.		180.00	30.00
	RMEOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		150.00	50.00
	REMOVE AND REFIX PETROL TANK TO FACILITATE FENDER REPLACEMENT .	NOT NECESSARY	100.00	-
	TRANFER BOOTLID MECHANISM.	NOT NECESSARY	100.00	-
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	150.00	-
			3,130.00	1,410.00
	GRAND TOTAL		9,599.44	5,677.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CC6/CT118005309/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.