

22/03/2003

ASS. REC. BY:

REF: CS/CTI18005317 / Atd326

Special Instruction:

Surveyor:
Mennen

Achran

ASSIGNMENT (Office)

From (Person):

ehong Boon Sen

of

CTI

Date/Time: 20/3/18 @ 12:55pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 8610 H

Insured:

SJB 50414

at Workshop m/s

Kah Motor (ubi)

Tel:

68465671

of

15 Ubi Road 4

Policy No:

DMHCSN1743851700

Claim No:

SNM18 D01432C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/3/2018

CA / REV / REP. / REV 24 HRS

lwp

26/2/18 @ 2pm OW

H.O.D. Endorsement:

Date/Time:

3:48pm @ 20/3/18

Person Contacted:

Steven

Vehicle-IN/

OUT

Date/Time

Action/Instruction

(✓) Estimate

SLG 8610 H - X

SJB 50414 - X

Vehicle not sent in for repair

& Submit valid report.

REF: CTI

ASSIGNMENT

From: _____ Date: 26/3/18

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 8610 H

at Workshop m/s: Kah Motor (UBI)

of: 15 ubi Rd 4

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Steven

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Wp

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLG 8610 H Yr Regn: 2016 Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey c.c. 2356

Colour: White A/C: Insured / Std / NI / NA

Sp.Reading: 4917. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMR C18S06 C206885.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: 215/55R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 26/03/18

Survey held at: Kah Motor.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Ching.

Date/Time File Pass to?



Preli. Report

1) 5110 Typist

Final Report

Date/Time File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S - RS SI

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Tech Invs \$☐ Weekend \$Report Format: TP

Lump Sum / I.B.I: \$

210210

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Jing Tong Choo [mailto:jtchoo@autoncars.com.sg]

Sent: 19 March, 2018 3:00 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: Accident involving YL111D AND VEHICLE SHC1844P ON 13/03/18

Hi Gabriel,

We would like LKK auto to contact the joint survey.

I would also like to exchange report with you. I have attached my clients GIA report here.

On Mon, Mar 19, 2018 at 2:41 PM, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18005564/Aqd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 26-03-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FY 3960G	Veh. Inspected	SKD 9846R
Policy No.	MSD/VM7/17-367771-CA	Coverage (\$)	0.00
Claim No.	MSC/V/18-000434	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	26/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/03/2018	Inspection Date	26/03/2018
Survey held at	HO BENG TRADING BLK 3020A, UBI ROAD 1 #01-33 SINGAPORE 408714		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2018		20 Mar 2018 12:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	KAH MOTOR CO. SDN BHD
Vehicle Reg. No.:	SLG8610H
Claim Type:	TP / SNM18D01432C02
Vehicle Reg. No. (Insured):	SJB5041U
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/03/2018]

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Lim Chou Siong <cslim@honda.com.sg>
Sent: Wednesday, 3 October 2018 6:25 PM
To: Denise Tay (LKKAuto)
Subject: SLG8610H / TP / CHINA TAI PING / DOA: 15/3/2018

Hi Denise,

Have Check No Idle Is It Still Claiming Cause No Record In The Quotation And No Repair History, Thanks.

Best Regards,

Lim Chou Siong
Bodyshop Service Advisor
Kah motor Co. Sdn Bhd
15, Ubi Road 4
Singapore 408610
E-mail : cslim@honda.com.sg
Fax : 67480770 DID : 68465671 H/P : 81006303

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Wednesday, 3 October, 2018 2:43 PM
To: Lim Chou Siong <cslim@honda.com.sg>
Subject: SLG8610H / TP / CHINA TAI PING / DOA: 15/3/2018

Dear Mr Lim,

This case advisor should be Mr Steven.

Can check for me SLG 8610H is still claiming? Any repair done? Finalization

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Chong Boon Sen

From: Steven Chui <stevenchui@honda.com.sg>
Sent: Tuesday, 20 March, 2018 11:44 AM
To: Chong Boon Sen
Subject: SLG8610H
Attachments: SLG8610H ESTIMATE.pdf

Dear Boon Sen,

Attached the estimate for the car SLG8610H, kindly arrange for a survey.

Steven Chui
Bodyshop Service Advisor
Kah Motor Co. Sdn Bhd
15 Ubi Road 4
Singapore 408610
E-mail: stevenchui@honda.com.sg

Contact : 68465672
H/phone:90721766



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/03/2018 15:28
Date Of Accident	15/03/2018 08:45
Exact Location Of Accident	ALONG ESPLANADE DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG8610H
Insured/Policyholder	
Name Of Registered Owner	TAN BOON PHENG
NRIC No	S1807185A
Email Address	WILSONBPTAN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97498478
Alternative Phone No	OFFICE-97498478

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 EX-S (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD16V13939/VPC2/R00
Cover Note Number	

Driver

Name of Driver	TAN BOON PHENG
NRIC No	S1807185A
Date Of Birth	16/04/1967
Occupation	INDOOR
Date Of Driving Pass	04/06/1985
Driving Experience	32 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97498478
Fax Number	
Contact Number	OFFICE-97498478
EMail Address	WILSONBPTAN@HOTMAIL.COM



Address	93 MEYER ROAD #04-02
Postcode	437986
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : YATI NOI SHIN GENDER: : FEMALE
Passenger 2	NAME: : TAN YI SHAN GENDER: : FEMALE
Passenger 3	NAME: : TAN SHI YAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER LIST

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJB5041U
Vehicle Make/Model/Colour	HONDA DARK GREY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Sketch Plan Pg. 1

Vehicle No SLG 8610H

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



Please continue to Annex E

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Steven Clark
stevenc@hunder.com.sg
90121766

Vehicle No SLG 8610 H

Annex E

Describe Circumstances of the Accident

I was travelling along Esplanade Dr where there was a slight congestion & travelling quite slowly. I switch lane & successfully switch to the next (right) lane & as the vehicle in front suddenly braked, I had to brake as well but from rear blackvue camera from my car, the vehicle SJB 5041 U instead ~~accelerated~~ accelerated & did not brake in time but sway to his right & resulted in a bad scratch on the rear right side of my vehicle.

Instead of signalling me that he/she had scratched my rear right side, he/she quickly distance his/her vehicle (SJB 5041 U) by not moving & also switch lane so that as to act as if nothing happened at all.

Review of rear blackvue video footage is good evidence that this Uber Driver is possibly distracted by his/her apps for customer call & ~~accelerated~~ accelerated his/her vehicle (SJB 5041 U) thus it's his/her fault.

In addition, his/her hit & run behaviour is also good enough to assume him/her is guilty.

Declaration

We declare the foregoing particulars are true in every respect.

15/3/2018

3:15 pm

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18001129	Page	1
	3 ANSON ROAD #16-00	Date	: 16. Mar 2018		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	:		
Registration No	: SLG8610H	Engine No	: K24W72013060		
Chassis No	: JHMRC1890GC206995	Date Time	: 16. Mar 2018 10:20:34 AM		
Model	: ODYSSEY 2.4 EXV-S 16YM	Surveyor Name	:		
Owner's Name	: TAN BOON PHENG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 15/3/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: OWNER:TAN BOON PHENG OWNER INSURER:LIBERTY INS ACC DATE:15/03/2018 SURVEYED BY: DATE: REF NO: TP INSURER:CHINA TAI PING TP VEH:SJB5041U						
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
90103-TA0-000	SCREW TAPPING 5 X 20	4	3.90	25	11.70	0.82	12.52
04715-T6A-900ZZ	FACERR.BUMPER	1	557.20	25	417.90	29.25	447.15
	Sum Item				443.62	31.05	474.67
BKBU02R	REMOVE & RENEW RR BUMPER.	1	900.00		900.00	63.00	963.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	600.00		600.00	42.00	642.00
	Sum Labor				1500.00	105.00	1,605.00

Survey By	Adrian	Total Amount	1,943.62	136.05	2,079.67
Date & Time	26/03/18	Total (Inclusive of GST)			2,079.67
Excess					
Status	Not Authorised				
Signature	[Signature]				

03 Days

Printed on 26/3/2018 2:42:56 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)















...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Mar 2018		20 Mar 2018 12:55 Edit Adj Rpt	S\$1,427.90 Edit Estimates	S\$1,427.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: KAH MOTOR CO. SDN BHD									
Vehicle Reg. No.: SLG8610H		Date of Loss: 15/03/2018 00:00 - :59 [16 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D01432C02		Policy/Cover Note No.: DMHCSN1743851700							
Vehicle Reg. No. (Insured): SJB5041U		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/03/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLG8610H (SNM18D01432C02)**
[SJB5041U]
TP
KAH MOTOR CO. SDN BHD
Mar 15 2018 12:00AM
[-]
Kah Motor Co Sdn Bhd

Upload Documents Upload Photos Compose New Letter			View View in Browser <input type="button" value="v"/>	
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/10/18 14:48	General View	 Load JPG	<input checked="" type="checkbox"/>
2	05/10/18 14:48	General View	 Load JPG	<input checked="" type="checkbox"/>
3	05/10/18 14:48	General View	 Load JPG	<input checked="" type="checkbox"/>
4	05/10/18 14:48	General View	 Load JPG	<input checked="" type="checkbox"/>
5	05/10/18 14:48	General View	 Load JPG	<input checked="" type="checkbox"/>
6	05/10/18 14:48	General View	 Load JPG	<input checked="" type="checkbox"/>
7	05/10/18 14:48	General View	 Load JPG	<input checked="" type="checkbox"/>
8	05/10/18 14:48	General View	 Load JPG	<input checked="" type="checkbox"/>
9	05/10/18 14:48	General View	 Load JPG	<input checked="" type="checkbox"/>
10	05/10/18 14:48	General View	 Load JPG	<input checked="" type="checkbox"/>
11	05/10/18 14:48	General View	 Load JPG	<input checked="" type="checkbox"/>
12	05/10/18 14:48	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/03/18 12:57	REPAIR ESTIMATE	 Load PDF	
2	20/03/18 12:57	CONTACT DETAIL	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18005317/ATD3E2

Date: 08/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1743851700

Claimant Vehicle
No: SLG8610HInsured Vehicle
No: SJB5041U

Date of Loss: 15/03/2018

Nature of Claim: TP

Claim
No: SNM18D01432C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG8610H

Make & Model: HONDA ODYSSEY, 2.3 Luxury (RA6) (A)

Engine No: K24W72013060

Reg. Date: 17/10/2016 (Man. Year: 2016)

Chassis No: JHMRC1890GC206995

Colour: White

Odometer: 4917 km

Engine Capacity: 2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	443.62	417.90	25.72	5.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	1,010.00	490.00	32.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,943.62	1,427.90	515.72	26.53
+ GST 7.00/7.00% (S\$)	136.05	99.95	36.10	26.53
Nett Amount (S\$)	2,079.67	1,527.85	551.82	26.53

INSPECTION

Date of Assignment: 20/03/2018

Date Inspected: 26/03/2018

Inspected At: Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$11.70 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2018)
Parts:	M1-MPV	HONDA ODYSSEY 2.3 Luxury (RA6) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG8610H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPACERL.RR.BUMPER SIDE	Not Necessary	14.02 FS	*- FS
2	4		*SCREW TAPPING 5 X 20	* Check	11.70 FS	*- FS
3	1		*FACERR.BUMPER	Deformed	417.90 FS	*417.90 FS
Total Parts (S\$)					443.62	417.90

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & RENEW RR BUMPER	New	900.00	560.00
2	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	New	600.00	450.00
Gross Labour Cost (S\$)			1,500.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >