

12/03/2002

ASS. REC. BY:

REF:

CS/FCI18005327 / K qd3 n2

Special Instruction:

Surveyor

EWS

From (Person):

Kenneth

May Chua

ASSIGNMENT (Office)

of FCI

Date/Time: 21/3/18 @ 12:56pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8JY 732X

Insured:

SH 8670X

at Workshop m/s

Motor Image

Tel:

9299 2693

of

19 Tuning & Tona Payoh

Policy No:

Claim No:

D18002222MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/3/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

2:15pm @ 21/3/18

Person Contacted:

Sayed

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

8JY 732X - CE4 / CTIL7014344 / Rea3

D.O.A.: 16/7/2017

SH 8670X - NS / INC17027278 / H1 + BM2

D.O.A.: 11/01/17

28/3/18 @ 4.70pm VLVISED to May Chua by email.

81604.44 Confirmed (Red 82740.44, 63%.)

REF: FCI

ASSIGNMENT

From: Date: 27032018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJY 732X

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

after 10am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SJY 732X Yr Regn: 02, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suban Fourer Wagon

C.C.

1995

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

44036

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

J1-18J5KC5GG066808

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

R:

225/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5 mm

R/Bal.

6 mm

L/Bal.

5 mm

L/Bal.

6 mm

D.O.A.

16/13/18

D.O.I.

27/13/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/3 All parts to Catherine

RECEIVED 07 SEP 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 09/09 2018

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

1604.44

135

50

50 + 50

19

304



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005327/Kqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 8670X	Veh. Inspected	SJY 732X
Policy No.		Coverage (\$)	0.00
Claim No.	D18002222MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	21/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/03/2018	Inspection Date	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D1800222MFSH

Date: 28 March 2018

Our Ref: CS/FCI18005327/Kqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJY 732X.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/03/2018 at the premises of M/s MOTOR IMAGE, and have the following to report:-

Workshop Estimate Amount	: S\$ 4,344.88 .
Revised Estimate Amount	: S\$ 1,458.64 .
"Check" Items Amount	: S\$ 481.20 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	19-03-2018	Our Ref No. D18002222MFSH
Accident Date	16-03-2018	Claim Type. Third Party
Insured Vehicle	SH8670X	Third Party Vehicle. SJY732X
Survey Location	19 LORONG 8 TOA PAYOH	
Contact Person.	KUAN WEI LOONG	
Contact No.	0/ 90903323	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOTOR IMAGE ENTERPRISES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236074)



PRI Documents



Close



PRI Header Details

Claim No	D18002222MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & MOTOR IM
Workshop Name	MOTOR IMAGE ENTERPRISES PTE LTD (Contact Person : KUAN WEI LOONG)	Survey Location & Contact Details	19 LORONG 8 TOA PAYOH Mobile: 90903323 , Phone: 0 , Fax: 0 EmailId: WEILOONG@MOTORIMAGE.NET		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH8670X	TP Vehicle No	SJY732X
PRI Recieved Date	19-03-2018 04:02:04 PM	Surveyor Appointed Date	21-03-2018 12:55:32 PM	Surveyor Accept Date	21-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	21-03-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 7 September 2018 12:06 PM
To: 'Kuan Wei Loong'; assignments
Cc: Sayedinah; Daniel Lim; SUR
Subject: RE: SJY732X-3RD PARTY CLAIM-AIG-TP(SH8670X)FIRST CAPITAL-SURVEY-27/03/2018-AFTER 1100 HRS *** LKK REF: CS/FCI18005327/qd3

Dear Wei Loong,

WITHOUT PREJUDICE

Confirm final fig \$1,604.44 before GST and 2 repair days.

Kindly send the relevant documents to First Capital Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kuan Wei Loong <weiloong@motorimage.net>
Sent: Thursday, 2 August 2018 6:32 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Sayedinah <sayedinah@motorimage.net>; Daniel Lim <daniellim@motorimage.net>; SUR <sur@lkkauto.com>
Subject: RE: SJY732X-3RD PARTY CLAIM-AIG-TP(SH8670X)FIRST CAPITAL-SURVEY-27/03/2018-AFTER 1100 HRS ***
LKK REF: CS/FCI18005327/qd3
Importance: High

Hi Claims Team,

Attached for your finalize and follow up.

Thank You,

Best Regards
Kuan Wei Loong
Claims Advisor
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP: 86113195
Email:weiloong@motorimage.net
Website:www.tanchong.com :: www.motorimage.net

From: Shiau Chan (LKKAUTO) [<mailto:siewsc@lkkauto.com>]
Sent: 2 August, 2018 4:30 PM
To: Kuan Wei Loong <weiloong@motorimage.net>; assignments <assignments@lkkauto.com>
Cc: Sayedinah <sayedinah@motorimage.net>; Daniel Lim <daniellim@motorimage.net>; SUR <sur@lkkauto.com>
Subject: RE: SJY732X-3RD PARTY CLAIM-AIG-TP(SH8670X)FIRST CAPITAL-SURVEY-27/03/2018-AFTER 1100 HRS ***
LKK REF: CS/FCI18005327/qd3

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 28 March 2018 4:26 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D1800222MFSH/1
Attachments: CSFCI18005327Kqd3.pdf

Dear May,

Enclosed herewith preliminary advice of SJY 732X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Wednesday, 21 March 2018 3:11 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D1800222MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Wednesday, 21 March 2018 12:55 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D1800222MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0695/2018
DATE : 16-MAR-2018

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : TAN YAM KHOON
ADDRESS : BLK 106 RIVERVALE WALK
#14-124
S(540106)
TELEPHONE NO : 96705575

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100454186-02
VEHICLE NO : SJY732X
MODEL CODE : SJ5DK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20Y196101
CHASSIS NO : JF18J5KC5GG066868
MILEAGE : 1 KM
DATE IN : 16/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 16/03/2018

Print Date : 23/03/2018
Print Time : 08:32:42

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJY732X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED	SURVEYOR'S
			CHARGES	RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM FIRST CAPITAL LACATION:OLD AIR PORT CAR PARK DATE:06/03/2018 TIME:1145 HRS		
3	ZZ/002	REPAIR/REPLACE FRT BUMPER AND FRT PANEL	1120.00	2801 /
4	ZZ/003	RESPRAY FRT BUMPER AND FRT PANEL	840.00	4201 /
5	ZZ/004	TO CONDUCT FRT LIGHTING TEST	50.00	301 /
6	ZZ/005	TO CONDUCT FRT PROTECTANT COATING	500.00	2501 /
7	ZZ/006	REMOVE/REFIX FRT HEADLAMP WASHER AND PIPING	nn 150.00	X X
8	ZZ/007	SUNDRIES	nn 100.00	X
TOTAL LABOUR CHARGES			2760.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJY732X

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
1	RAD PNL COMPL RPR	53029SG0019P	Sn 360.00	X		
2	BRKT SD F RH	57707SG020	Sn 12.60	X		
3	BRKT SD F LH	57707SG030	Sn 12.60	X		
4	FRT BUMPER	57709SG030A	Bu 594.00			
5	BACK BEAM CPL F	57711SG0009P	N 288.00	?		
6	ENERGY ABSOR F	57722SG020	Bu 126.00			
7	COVER HOOK F STD	57731SG220	Nu 4.30			
8	FOG LAMP ASSY F	84501AJ060	Sn 544.00	X		
9	BRKT F FOG ASSY RH	PDI PARTS 84927SG020A	Sn 19.80	X		
10	BRKT F FOG ASSY LH	PDI PARTS 84927SG030A	Sn 19.80	X		
SUB TOTAL			1981.10	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			396.22	0.00	0.00	0.00
GRAND TOTAL			1584.88	0.00	0.00	0.00
OVERALL TOTAL			1584.88			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJY732X

TOTAL LABOUR CHARGES	2760.00
TOTAL SPARE PARTS CHARGES	1584.88
GRAND TOTAL	4344.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

*Not Authorise
Resurvey B4 paint
2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kg

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0695/2018
DATE : 16-MAR-2018

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : TAN YAM KHOON
ADDRESS : BLK 106 RIVERVALE WALK
#14-124
S(540106)
TELEPHONE NO : 9670 5575

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100454186-02
VEHICLE NO : SJY732X
MODEL CODE : SJ5DK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20Y196101
CHASSIS NO : JF1SJ5KC5G0066868
MILEAGE : 44038 KM
DATE IN : 16/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 16/03/2018

Print Date : 11/07/2018
Print Time : 19:11:33

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJY732X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM FIRST CAPITAL LACATION:OLD AIR PORT GAR PARK DATE:06/03/2018 TIME:1145 HRS		
3	ZZ/002	REPAIR/REPLACE FRT BUMPER AND FRT PANEL	1120.00	280.00
4	ZZ/003	RESPRAY FRT BUMPER AND FRT PANEL	840.00	420.00
5	ZZ/004	TO CONDUCT FRT LIGHTING TEST	50.00	30.00
6	ZZ/005	TO CONDUCT FRT PROTECTANT COATING	500.00	250.00
7	ZZ/006	REMOVE/REFIX FRT HEADLAMP WASHER AND PIPING	150.00	.00
8	ZZ/007	SUNDRIES	100.00	.00
TOTAL LABOUR CHARGES			2760.00	980.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJY732X

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	RAD PNL COMPL RPR	53029SG0019P	360.00			X
2	BRKT SD F RH	57707SG020	12.60			X
3	BRKT SD F LH	57707SG030	12.60			X
4	FRT BUMPER	57709SG030A	594.00			OK
5	BACK BEAM CPL F	57711SG0009P	288.00			X
6	ENERGY ABSOR F	57722SG020	126.00			B ₁ OK
7	COVER HOOK F STD	57731SG220	4.30			OK
8	FOG LAMP ASSY F	84501AJ060	544.00			X
9	BRKT F FOG ASSY RH	PDI PARTS 84927SG020A	19.80			X
10	BRKT F FOG ASSY LH	PDI PARTS 84927SG030A	19.80			X
11	FRONT NUMBER PLATE (SUPP)	WM001		Del	45.00	OK ✓
SUB TOTAL			724.30	0.00	45.00	0.00
LESS DISCOUNT (NETT-20 %)			144.86	0.00	0.00	0.00
GRAND TOTAL			579.44	0.00	45.00	0.00
OVERALL TOTAL			624.44			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SJY732X

NETT ITEM 724.30
LESS 20 % -144.86
NETT AMOUNT 579.44

LIST ITEM 0.00
LESS 50 % 0.00
LIST AMOUNT 0.00

SPECIAL NETT AMOUNT 45.00

S/LIST ITEM 0.00
LESS 30 % 0.00
S/LIST AMOUNT 0.00

TOTAL LABOUR CHARGES 980.00
TOTAL SPARE PARTS CHARGES 624.44

TOTAL CHARGES 1604.44
ADD 7 % GST 112.31

GRAND TOTAL 1716.75

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005327/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8670X	Veh. Inspected	SJY 732X	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002222MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	21/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JF1SJ5KC5GG066868	Colour	METALLIC SILVER	
Odometer	44036	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	YOKOHAMA	5 mm	
L/H Front Tyre	225/60 R17	YOKOHAMA	5 mm	
R/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/03/2018	Inspection Date	27/03/2018	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 732X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RAD PNL COMPL RPR (N)	SERVICEABLE	360.00	-
1	BRKT SD F RH (N)	SERVICEABLE	12.60	-
1	BRKT SD F LH (N)	SERVICEABLE	12.60	-
1	FRT BUMPER (N)	BUCKLED	594.00	594.00
1	BACK BEAM CPL F (N)	TO REPAIR SEE LABOUR	288.00	-
1	ENERGY ABSOR F (N)	BENT	126.00	126.00
1	COVER HOOK F STD (N)	DENTED	4.30	4.30
1	FOG LAMP ASSY F (N)	SERVICEABLE	544.00	-
1	BRKT F FOG ASSY RH (N)	SERVICEABLE	19.80	-
1	BRKT F FOG ASSY LH (N)	SERVICEABLE	19.80	-
	LESS 20% DISCOUNT		-396.22	-144.86
			1,584.88	579.44
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
1	FRONT NUMBER PLATE (ADDITIONAL)(SN)	DENTED	45.00	45.00
			145.00	45.00
LABOUR				
	REPAIR/REPLACE FRT BUMPER AND FRT PANEL.INCLUSIVE OF THE REPAIR OF BACK BEAM CPL F.		1,120.00	280.00
	RESPRAY FRT BUMPER AND FRT PANEL.		840.00	420.00
	TO CONDUCT FRT LIGHTING TEST.		50.00	30.00
	TO CONDUCT FRT PROTECTANT COATING.		500.00	250.00
	REMOVE/REFIX FRT HEADLAMP WASHER AND PIPING.	NOT NECESSARY	150.00	-
	-		-	-
	-		-	-
	-		-	-
			2,660.00	980.00
GRAND TOTAL			4,389.88	1,604.44

Report Ref No. CS/FCI18005327/Kqd3n2



RECOMMENDED COST OF REPAIRS			1,604.44
-----------------------------	--	--	----------

Report Ref No. CS/FCI18005327/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.