

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Haicyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES000007

Date : 17/03/2018

Vehicle Num. : SLQ 3064P (LCR)

Make/Model : TOYOTA PRIUS HYBRID 1.8S

Chassis/Eng# :

Accident Date : 17/03/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS :		
2.		REAR DOOR - RH R		1,323.80
		REAR FENDER RH R		800.00
		List TotalS\$:		2,123.80
		25.00% Discount S\$:		530.95
				1,592.85
1.	1 SET	SPECIAL NETT ITEMS :		
		TRIM CLIP X		40.00
		Special Nett Total S\$:		40.00
		LABOUR :		
		TRANSFER DOOR MECHANISM		180.00 X
		TO LABOUR FOR REMOVING R/R BUMPER, R/R FENDER, R/R		900.00 400
		DOOR OUT TO FACILITATE AND REPLACEMENT OF DAMAGE PARTS.		
		TO PUTTY & SPRAY R/R BUMPER, R/R FENDER, R/R DOOR, SIDE		1,250.00 600
		SKIRT, WHEEL CAP.		
		Labour Total S\$:		2,330.00

3 days

for WORLD AUTO PTE LTD

Sebastian .

20/3/18

- Part by part repair

- Photo Before & After

Paint .

90036121

Sebastianyang@lkkauto.com

E. & O.E.

Total S\$:

3,962.85

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: