

ASS. REC. BY:

REF CS/FCI 005338 / Avd 3 n2 Special Instruction

Surveyor:

Adrian

ASSIGNMENT (Office)

CWS

From (Person):

May chua

of

FCI

Date/Time:

21/3/18 @ 3:04pm

Estimated Cost:

Bill to:

OD / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGK 2205Y

Insured:

SHD 7060P

at Workshop m/s

Modern Automotive

Tel:

G 748 4422

of

Blk 3023 A Ubi Road 1 # 01-58/61

Policy No:

Claim No:

D18002297MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/03/2018

CA / REV / REP. / REV 24 HRS

lup?

H.O.D. Endorsement:

Date/Time:

3:15pm @ 21/3/18

Person Contacted:

Grace

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGK 2205Y -x

SHD 7060P - cc11AXA16009470/H1ba392

D.O.A: 22/05/16

22/3/18

Informed FCI pending workshop est by email

3/5/18

Adrian confirmed LS \$23,600 (Red 14,269.66, 37%)

4/5/18

Send preli revised by email

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGK22057 Yr Regn: 2008, JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E200K c.c. 1796Colour: Boonze A/C: Insured / Std / NI / NASp. Reading: 192708 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDB2110412B318360Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/45R17R: 245/45R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 21/03/18Survey held at ModernDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cp.

COE Expiry: 31/03/28. To print LTA rebate after 31/03/18.

Notes: MV: 76K
RV: 45K
Nett: 31K.

RECEIVED 04 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 4/5 - typistReport Format: CWSLump Sum / I.B.I. (\$) 23,600/-Days Of Repair: 18Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos: 580Others: ESP

TOTAL

415/18

27x15 405

170+4055050+50172897



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005338/Avd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 22-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 7060P	Veh. Inspected	SGK 2205Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18002297MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	22/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	19/03/2018	Inspection Date	21/03/2018
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	20-03-2018	Our Ref No. D18002297MFSH
Accident Date	19-03-2018	Claim Type. Third Party
Insured Vehicle	SHD7060P	Third Party Vehicle. SGK2205Y
Survey Location	BLK 3023A UBI ROAD 1 #01-58/61	
Contact Person.	GRACE CHIN	
Contact No.	67484422/ 0	Fax No. 67476720
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MODERN AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236171)



PRI Documents



Close



PRI Header Details

Claim No	D18002297MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & MODERN
Workshop Name	MODERN AUTOMOTIVE PTE LTD (Contact Person : GRACE CHIN)	Survey Location & Contact Details	BLK 3023A UBI ROAD 1 #01-58/61 Mobile: 0 , Phone: 67484422 , Fax: 67476720 EmailId: CHIN@MODERNAUTOMOTIVE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD7060P	TP Vehicle No	SGK2205Y
PRI Recieved Date	20-03-2018 09:13:21 PM	Surveyor Appointed Date	21-03-2018 03:04:37 PM	Surveyor Accept Date	22-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	22-03-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 4 May 2018 9:53 AM
To: 'Claim Workflow System'
Cc: 'MAYCHUA@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18002297MFSH/1, SGK 2205Y
Attachments: SGK 2205Y PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGK 2205Y
Date of survey: 21/3/2018
Number of days: 18 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 12 April 2018 10:19 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'MAYCHUA@MSFIRSTCAPITAL.COM.SG' <MAYCHUA@MSFIRSTCAPITAL.COM.SG>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002297MFSH/1, SGK 2205Y

Dear Sir/Madam,

Please provides us OI GIA report.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 11 April 2018 9:47 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'MAYCHUA@MSFIRSTCAPITAL.COM.SG' <MAYCHUA@MSFIRSTCAPITAL.COM.SG>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002297MFSH/1, SGK 2205Y

Dear Sir/Madam,

Please provides us OI GIA report.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 22 March 2018 3:16 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>

Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18002297MFSH/1, SGK 2205Y

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGK 2205Y on 21/3/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 22 March 2018 8:09 AM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18002297MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Wednesday, 21 March 2018 3:04 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18002297MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002297MFSH
Our ref: CS/FCI18005338/Avd3

Date : 4/5/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGK 2205Y


We thank you for your instruction on 21/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21/3/2018 at the premises of M/s MODERN AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$37,869.66
Revised Estimate Amount	: S\$23,600.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear poriton



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8765J
Vehicle Details	
Vehicle No.:	SGK2205Y
Vehicle to be Exported:	No
Intended De-registration Date:	01 Aug 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200K
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	27195631050034
Chassis No.:	WDB2110412B318360
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$51,261.00
Original Registration Date:	30 Jul 2008
First Registration Date:	30 Jul 2008
Transfer Count:	3
Actual ARF Paid:	\$51,261.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jul 2018
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$44,998.00
COE Rebate Amount:	\$43,485.00
Total Rebate Amount:	\$43,485.00

The information contained herein is correct as at 04 May 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8765J
Vehicle Details	
Vehicle No.:	SGK2205Y
Vehicle to be Exported:	No
Intended De-registration Date:	01 Apr 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200K
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	27195631050034
Chassis No.:	WDB2110412B318360
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$51,261.00
Original Registration Date:	30 Jul 2008
First Registration Date:	30 Jul 2008
Transfer Count:	3
Actual ARF Paid:	\$51,261.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jul 2018
PARF Rebate Amount:	\$25,630.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$44,998.00
COE Rebate Amount:	\$44,985.00
Total Rebate Amount:	\$70,615.00

The information contained herein is correct as at 22 Mar 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8765J
Vehicle Details	
Vehicle No.:	SGK2205Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	21 Mar 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200K
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	27195631050034
Chassis No.:	WDB2110412B318360
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$51,261.00
Original Registration Date:	30 Jul 2008
First Registration Date:	30 Jul 2008
Transfer Count:	3
Actual ARF Paid:	\$51,261.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jul 2018
PARF Rebate Amount:	\$25,630.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$44,998.00
COE Rebate Amount:	\$505.00
Total Rebate Amount:	\$26,135.00

The information contained herein is correct as at 21 Mar 2018

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New Honda Vezel 1.5 X Honda Sensing.



Ready Stock For Delivery!
Guaranteed COE Package. Call
Now!
Apex Trading Pte Ltd StarAd

Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

16 vehicles

e200

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	e200	Any	Any	2008	Any	Any	Any	Available



**Mercedes-Benz E-Class E200K
Avantgarde (New 10-yr COE)**

\$88,800

\$8,870 /yr

27-Feb-2008

1,796 cc

176,000 km

Luxury

Available

C&C Unit, Regularly Serviced By Owner. Low Mileage, PARF \$28014, Body \$2800, 5 Years COE Renewal \$68800 With Depreciation Better Than Car Rental, We Assist New Exterior Paintwork At \$800 Only! Well Ma...

Posted: 29-Jan-2018 Tags: 2008 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz, E200K, Used Mercedes-Benz



**Mercedes-Benz E-Class E200K
Avantgarde (New 10-yr COE)**

\$79,800

\$7,970 /yr

01-Apr-2008

1,796 cc

154,762 km

Luxury

Available

1 Owner, Under Utilized, Religiously Serviced And Maintained By C&C Agent, Excellent Condition, Original Paint, Shelter Parking Since New, Lowest Depreciation Of \$8500 Yearly, View By Appointment Only...

Posted: 14-Mar-2018 Tags: 2008 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz, E200K, Used Mercedes-Benz

DIRECT OWNER



Mercedes-Benz E-Class E200K

\$30,800

N.A

02-Apr-2008

1,796 cc

95,179 km

Luxury

Available

No Repair Needed, Good Condition.

Posted: 17-Mar-2018 Tags: 2008 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz, E200K, Used Mercedes-Benz

DIRECT OWNER



**Mercedes-Benz E-Class E200K
(New 10-yr COE)**

\$79,500

\$7,940 /yr

16-Jun-2008

1,796 cc

155,000 km

Luxury

Available

Tip Top Condition, See To Believe.

Posted: 20-Mar-2018 Tags: 2008 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz, E200K, Used Mercedes-Benz

DIRECT OWNER

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



**Mercedes-Benz E-Class E200K
Avantgarde (New 10-yr COE)**

\$76,800

\$7,670 /yr

23-Jun-2008

1,796 cc

159,733 km

Luxury

Available

Well Maintained! Quiet Engine And Smooth Transmission, New 10 Years COE, Low Mileage At 159733Km Done, Sports Rims, Leather Seats, Factory Fitted Audio System, Multi Functional Steering Control. Key...

Posted: 11-Mar-2018 Tags: 2008 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz, E200K, Used Mercedes-Benz



**Mercedes-Benz E-Class E200K
Avantgarde (New 10-yr COE)**

\$79,500

\$7,940 /yr

27-Jun-2008

1,796 cc

136,200 km

Luxury

Available

C&C Service Record, Avantgarde Model.

Posted: 15-Mar-2018 Tags: 2008 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz, E200K, Used Mercedes-Benz



**Mercedes-Benz E-Class E200K
(New 10-yr COE)**

\$77,800

\$7,770 /yr

11-Sep-2008

1,796 cc

150,000 km

Luxury

Available

Renew 10 Years COE Cheapest In Town Call For Appointment.

Posted: 19-Mar-2018 Tags: 2008 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz, E200K, Used Mercedes-Benz

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 22 March 2018 3:16 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002297MFSH/1, SGK 2205Y

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGK 2205Y on 21/3/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 22 March 2018 8:09 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002297MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 21 March 2018 3:04 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002297MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

MS First Capital Insurance Ltd

36 Robinson Road
#16-01 City House
Singapore 068877
Tel: 6507 - 3843
Fax: 6507 - 3849

Quotation

DATE : 28.03.2018
VEH NO : SGK2205Y
MODEL : Merc E200K
D O A : 19.03.2018
YR REF : SHD7060P

Attn: Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE: ESTIMATE FOR ACCIDENT REPAIR SGK2205Y (MERCEDES E200K)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Rear Number Plate Lamp - LH & RH <i>nt m</i>	2	106.00 ✓
2	Rear Bumper <i>Distorted</i>	1	1,358.50 ✓
3	Rear Bumper Side Holder - LH & RH <i>nt</i>	2	116.00 ✓
4	Rear Bumper Clips <i>nt</i>	1 set	30.00 ✓
5	Rear Bumper Chrome Moulding - Centre <i>3 Distorted</i>	1	185.60 ✓
6	Rear Bumper Chrome Moulding (side) - LH & RH	2	390.00 ✓
7	Rear Bumper Reinforcement <i>Best</i>	1	585.00 ✓
8	Rear Bumper Reinforcement Stay - LH & RH <i>Best</i>	2	210.00 ✓
9	Rear End Panel <i>Distorted</i>	1	765.30 ✓
10	Rear End Panel Top Garnish <i>Distorted</i>	1	189.40 ✓
11	Tail Lamp - LH & RH <i>Smashed</i>	2	1,270.20 ✓
12	Tail Lamp Back Gasket - LH & RH <i>nt</i>	2	50.00 ✓
13	Tail Lamp Side Garnish - LH & RH <i>nt</i>	2	104.40 ✓
14	Tail Lamp Side Garnish Clips <i>nt</i>	1 set	30.00 ✓
15	Tail Lamp Panel - LH & RH <i>Distorted</i>	2	448.00 ✓
16	Bootlid <i>Distorted</i>	1	1,923.90 ✓
17	Bootlid Lock <i>nt</i>	1	195.90 ✓
18	Bootlid Weatherstrip <i>nt</i>	1	196.70 ✓
19	Bootlid Hinges - LH & RH <i>Best</i>	2	258.00 ✓
20	Bootlid Outer Garnish <i>Distorted</i>	1	532.00 ✓
21	Bootlid Outer Garnish Chrome Moulding <i>nt</i>	1	145.20 ✓
22	Bootlid Outer Garnish Clips <i>nt</i>	1 set	25.00 ✓
23	Bootlid Centre Reflector <i>nt</i>	1	198.40 ✓
24	Bootlid Inner Trim Cover <i>nt</i>	1	296.50 ✓
25	Bootlid Inner Trim Cover Clips <i>nt</i>	1 set	30.00 ✓
26	Bootlid Lock Actuator <i>Distorted</i>	1	255.00 ✓
27	Bootlid Inner Lock Garnish <i>Distorted</i>	1	105.00 ✓
28	Bootlid Lock Catch <i>Best</i>	1	64.20 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SGK2205Y (MERCEDES E200K)

29	Mercedes Benz Logo	1	84.00	✓
30	E200 Wording	1	68.60	✓
31	Kompressor Wording	1	98.00	✓
32	Cycle and Carriage Logo	1	45.00	✓
33	Rear Fender - LH & RH <i>Buckled</i>	2	4,394.00	✓
34	Rear Fender Inner Shield - LH & RH <i>3 new</i>	2	324.00	✓
35	Rear Fender Inner Shield Clips - LH & RH	1 set	60.00	✓
36	Rear Fender Inner Trim - LH & RH <i>crumpled</i>	2	624.00	✓
37	Rear Fender Inner Trim Clips - LH & RH <i>new</i>	1 set	60.00	✓
38	Rear Windscreen Moulding <i>new</i>	1	288.00	✓
39	Spare Tyre Panel <i>torn</i>	1	579.00	✓
40	Spare Tyre Panel Top Cover <i>deformed</i>	1	379.80	✓
41	Spare Tyre Wheel Nut Tray <i>crushed</i>	1	79.80	✓
42	Jack Container <i>deformed</i>	1	126.40	✓
43	Rear Exhaust Pipe - LH <i>3 bent</i>	1	1,708.00	✓
44	Rear Exhaust Pipe - RH	1	1,635.00	✓
45	Rear Exhaust Mounting - LH & RH <i>new</i>	2	91.00	✓
46	Rear Exhaust Heat Shield - LH & RH <i>crumpled</i>	2	344.00	✓
47	Rear Door - LH & RH <i>4 pins</i>	2	4,100.00	✓
48	Rear Door Lock - LH & RH <i>3 new</i>	2	831.00	✓
49	Rear Door Weatherstrip - LH & RH	2	552.00	✓
50	Front Seat Headrest - LH & RH <i>3 Activated</i>	2	1,088.00	✓
51	Front Seat Bent Buckles - LH & RH	2	778.00	✓
52	Air Bag Sensor <i>Activated</i>	2	508.60	✓
53	Air Bag ECU <i>Activated</i>	1	1,275.00	✓
54	Rear Seat Belt - LH & RH <i>Activated</i>	2	792.00	✓

29254.5

21829.05

Less 10%

\$ 30,977.40

(3,097.74)

\$ 27,879.66

S/NET ITEMS

1	Rear Number Plate <i>but</i>	1	\$ 30.00	✓
2	Rear Number Plate Holder <i>deformed</i>	1	\$ 30.00	✓
3	Reverse Sensor <i>damaged</i>	4	\$ 1,000.00	✓
4	Rear End Panel Sealant <i>3 new</i>	1	\$ 60.00	✓
5	Rear Windscreen Sealant	1	\$ 60.00	✓
6	Spare Tyre Panel Sealant <i>new</i>	1	\$ 60.00	✓
7	Rear Camera <i>damaged</i>	1	\$ 580.00	✓
			1690	
			\$ 1,820.00	

TOTAL PARTS

\$ 29,699.66

LABOUR CHARGE

RE : ESTIMATE FOR ACCIDENT REPAIR SGK2205Y (MERCEDES E200K)

1	To knocking & pull out rear portion and renew damage parts	\$	2,500.00 2200
2	To putty & spray up paint works	\$	2,000.00 1600
3	To check wiring system	\$	100.00 50
4	To underseal	\$	200.00 100
5	To remove reverse sensor	\$	100.00 60
6	To remove rear camera	\$	100.00 50
7	To remove upholstery and rear seat	\$	300.00 250
8	To remove entire exhaust system	\$	380.00 160
9	To remove rear windscreen	\$	180.00 120
10	To remove entire rear undercarriage to facilitate repairs	\$	580.00 450
11	To transfer rear LH & RH door fittings	\$	300.00 X
12	To transfer bootlid fittings	\$	150.00 80
13	To perform wheel alignment	\$	150.00 80
14	To remove headrests and seat belt buckles	\$	380.00 300
15	To reset air bag configuration	\$	200.00 150
16	To perform dianogstic test	\$	200.00 100
17	To utilise chassis alignment bench	\$	350.00 280
		\$	8,170.00

GRAND TOTAL \$ 37,869.66

total: 29549.05

4/5 236K

180 days

NOTE: GST will be reflected in the final bills
LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a written request basis
- No illegal modifications
- Supplementary item(s) must be removed and is subject to final approval from insurance company

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN

THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY

WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE

FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005338/Avd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-05-2018	
			Code : FC12	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 7060P	Veh. Inspected	SGK 2205Y	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002297MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	21/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E200K	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	WDB2110412B318360	Colour	BRONZE	
Odometer	192708	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R17	SUMITOMO	6 mm	
L/H Front Tyre	245/45 R17	SUMITOMO	6 mm	
R/H Rear Tyre	245/45 R17	SUMITOMO	6 mm	
L/H Rear Tyre	245/45 R17	SUMITOMO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/03/2018	Inspection Date	21/03/2018	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		18 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGK 2205Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	REAR NUMBER PLATE LAMP-LH & RH	NOT NECESSARY	106.00	-
1	REAR BUMPER	DISTORTED	1,358.50	1,358.50
2	REAR BUMPER SIDE HOLDER-LH & RH	NECESSARY	116.00	116.00
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	REAR BUMPER CHROME MOULDING-CENTRE	DISTORTED	185.60	185.60
2	REAR BUMPER CHROME MOULDING (SIDE)- LH & RH	DISTORTED	390.00	390.00
1	REAR BUMPER REINFORCEMENT	BENT	585.00	585.00
2	REAR BUMPER REINFORCEMENT STAY-LH & RH	BENT	210.00	210.00
1	REAR END PANEL	DISTORTED	765.30	765.30
1	REAR END PANEL TOP GARNISH	DEFORMED	189.40	189.40
2	TAIL LAMP-LH & RH	SMASHED	1,270.20	1,270.20
2	TAIL LAMP BACK GASKET-LH & RH	NECESSARY	50.00	50.00
2	TAIL LAMP SIDE GARNISH-LH & RH	CUT	104.40	104.40
1	SET TAIL LAMP SIDE GARNISH CLIPS	NECESSARY	30.00	30.00
2	TAIL LAMP PANEL-LH & RH	DENTED	448.00	448.00
1	BOOTLID	DISTORTED	1,923.90	1,923.90
1	BOOTLID LOCK	JAMMED	195.90	195.90
1	BOOTLID WEATHERSTRIP	CUT	196.70	196.70
2	BOOTLID HINGES-LH & RH	BENT	258.00	258.00
1	BOOTLID OUTER GARNISH	DISTORTED	532.00	532.00
1	BOOTLID OUTER GARNISH CHROME MOULDING	NECESSARY	145.20	145.20
1	SET BOOTLID OUTER GARNISH CLIPS	NECESSARY	25.00	25.00
1	BOOTLID CENTRE REFLECTOR	NOT NECESSARY	198.40	-
1	BOOTLID INNER TRIM COVER	NOT NECESSARY	296.50	-
1	SET BOOTLID INNER TRIM COVER CLIPS	NOT NECESSARY	30.00	-
1	BOOTLID LOCK ACTUATOR	DAMAGED	255.00	255.00
1	BOOTLID INNER LOCK GARNISH	NOT NECESSARY	105.00	-
1	BOOTLID LOCK CATCH	BENT	64.20	64.20
1	MERCEDES BENZ LOGO	NECESSARY	84.00	84.00
1	E200 WORDING	NECESSARY	68.60	68.60
1	KOMPRESSOR WORDING	NECESSARY	98.00	98.00

Report Ref No. CS/FCI18005338/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CYCLE AND CARRIAGE LOGO	NECESSARY	45.00	45.00
2	REAR FENDER-LH & RH	BUCKLED	4,394.00	4,394.00
2	REAR FENDER INNER SHIELD-LH & RH	NOT NECESSARY	324.00	-
1	SET REAR FENDER INNER SHIELDCLIPS-LH & RH	NOT NECESSARY	60.00	-
2	REAR FENDER INNER TRIM-LH & RH	CRUMPLED	624.00	624.00
1	SET REAR FENDER INNER TRIM CLIPS-LH & RH	NECESSARY	60.00	60.00
1	REAR WINDSCREEN MOULDING	NECESSARY	288.00	288.00
1	SPARE TYRE PANEL	TORN	579.00	579.00
1	SPARE TYRE PANEL TOP COVER	DEFORMED	379.80	379.80
1	SPARE TYRE WHEEL NUT TRAY	CRACKED	79.80	79.80
1	JACK CONTAINER	DEFORMED	126.40	126.40
1	REAR EXHAUST PIPE-LH	BENT	1,708.00	1,708.00
1	REAR EXHAUST PIPE-RH	BENT	1,635.00	1,635.00
2	REAR EXHAUST MOUNTING-LH & RH	NOT NECESSARY	91.00	-
2	REAR EXHAUST HEAT SHIELD-LH & RH	CRUMPLED	344.00	344.00
2	REAR DOOR-LH & RH	TO REPAIR SEE LABOUR	4,100.00	-
2	REAR DOOR LOCK-LH & RH	NOT NECESSARY	831.00	-
2	REAR DOOR WEATHERSTRIP-LH & RH	NOT NECESSARY	552.00	-
2	FRONT SEAT HEADREST-LH & RH	ACTIVATED	1,088.00	1,088.00
2	FRONT SEAT BENT BUCKLES-LH & RH	ACTIVATED	778.00	778.00
2	AIR BAG SENSOR	ACTIVATED	508.60	508.60
1	AIR BAG ECU	ACTIVATED	1,275.00	1,275.00
2	REAR SEAT BELT-LH & RH	ACTIVATED	792.00	792.00
	LESS 10% DISCOUNT		-3,097.74	-2,428.35
			27,879.66	21,855.15
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	BENT	30.00	30.00
1	REAR NUMBER PLATE HOLDER (SN)	DEFORMED	30.00	30.00
4	REVERSE SENSOR (SN)	DAMAGED	1,000.00	1,000.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	SPARE TYRE PANEL SEALANT (SN)	NECESSARY	60.00	60.00

Report Ref No. CS/FCI18005338/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR CAMERA (SN)	DAMAGED	580.00	450.00
			1,820.00	1,690.00
	LABOUR			
	TO KNOCKING & PULL OUT REAR PORTION AND RENEW DAMAGE PARTS, INCLUSIVE OF THE REPAIR OF REAR DOOR-LH & RH.		2,500.00	2,200.00
	TO PUTTY & SPRAY UP PAINT WORKS.		2,000.00	1,600.00
	TO CHECK WIRING SYSTEM.		100.00	50.00
	TO UNDERSEAL.		200.00	100.00
	TO REMOVE REVERSES ENSOR.		100.00	60.00
	TO REMOVE REAR CAMERA.		100.00	50.00
	TO REMOVE UPHOLSTERY AND REAR SEAT.		300.00	250.00
	TO REMOVE ENTIRE EXHAUST SYSTEM.		380.00	160.00
	TO REMOVE REAR WINDSCREEN.		180.00	120.00
	TO REMOVE ENTIRE REAR UNDERCARRIAGE TO FACILITATE REPAIRS.		580.00	450.00
	TO TRANSFER REAR LH & RH DOOR FITTINGS.	NOT NECESSARY	300.00	-
	TO TRANSFER BOOTLID FITTINGS.		150.00	80.00
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
	TO REMOVE HEADRESTS AND SEAT BELT BUCKLES.		380.00	300.00
	TO RESET AIR BAG CONFIGURATION.		200.00	150.00
	TO PERFORM DIANOGSTIC TEST.		200.00	100.00
	TO UTILISE CHASSIS ALIGNMENT BENCH.		350.00	280.00
			8,170.00	6,030.00
GRAND TOTAL			37,869.66	29,575.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				23,600.00

Report Ref No. CS/FCI18005338/Avd3n2

MARKET VALUE: \$76,000.00 (EST)-PAPER VALUE: \$45,000.00=NETT VALUE: \$31,000.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.