

REPAIR ESTIMATE*

VEHICLE NO : SHD 4036E

DATE 19/3/2018 14:59

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (LH)			\$ 797.90
	Front Fender (LH)			\$ 593.00
	Front Fender Shield (LH)			\$ 86.00
	Front Fender Retainer			\$ 9.20
	SUB TOTAL			\$ 1,486.10
	LESS 20%			\$ 297.22
	DISCOUNTED TOTAL			\$ 1,188.88
	Frt Fender Advertisement Logo (LH)			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 500.00
	Spray Painting Charge- Fender/Bumper			\$ 500.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 1,100.00
	ESTIMATE TOTAL			\$ 2,388.88
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				