

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO : SHD 3060R

DATE 16/3/2018 15:04

MAKE :

DDA: 15-03-18

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 603.60
	Rear Bumper Reinforcement			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket			\$ 49.00
	Rear Bumper Clips			\$ 22.00
	Rear Bumper Sponge			\$ 143.40
	Rear Bumper Under Cover			\$ 225.00
	<b>SUB TOTAL</b>			<b>\$ 1,907.35</b>
	<b>LESS 20%</b>			<b>\$ 381.47</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,525.88</b>
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Bumper Rubber Mat			\$ 50.00
				<b>\$ 185.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	R/Refix Reverse Sensor			\$ 120.00
	<b>TOTAL LABOUR</b>			<b>\$ 770.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,481.58</b>

Larry Ng

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Rashid

4p 20010068

3 days

P/P

20/03/18 @ 11:55

Reg by post

Nett

Nett

300

180

X

60