

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0360/2018/GW
Date : 23-Mar-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Dr. Wong Chong Yu Kelvin
Address : 9B Marlene Avenue
Singapore 556621
Telephone : HP +65 81265822
Type of Claim : Third Party Claims
Policy No. : 1800022575
Vehicle No : **SLW 9160 Z**
Model Code : Audi A4 Sedan 2.0 TFSI
Model / Year : Mar-18
Engine No : CVK 052310
Chassis No : WAUZZZF41JA086181
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Mar-18
Place of Accident : 501 Stirling Road MDIS

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 9160 Z.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlights washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, rhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 1250 .	
3	To respray front bumper and rhs front fender.	\$ 1,500.00 1100	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>4,152.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 9160 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	\$ 1,849.00	✓
2	FRONT BUMPER AIR GUIDE-RH ?	\$ 73.00	?
3	FRONT BUMPER GUIDE SECTION-RH <i>Byd</i>	\$ 32.00	✓
4	FRONT BUMPER AIR GUIDE-RH <i>Deformed</i>	\$ 118.00	✓
5	FRONT FENDER-RH <i>Dented</i>	\$ 665.00	✓
6	FRONT FENDER CLOSING ELEMEN-RH ?	\$ 44.00	?
7	FRONT FENDER BRACKET-RH ?	\$ 31.00	?
8	FRONT FENDER DEFORMATION BRACKET-RH ?	\$ 43.00	?
9	FRONT FENDER BRACE-RH <i>Best</i>	\$ 103.00	✓
10	FRONT FENDER LEDGE COVER-RH <i>me</i>	\$ 20.00	✓
11	FRONT FENDER COVER <i>me</i>	\$ 27.00	✓
12	LED HEADLIGHT-RH <i>cut</i>	\$ 6,973.00	✓
13	FRONT WHEEL SPOILER-RH ?	\$ 63.00	?
14	STONE CHIP GUARD-RH <i>me</i>	\$ 44.00	✓
15	FRONT FENDEER EXTENSION BRACKET-RH ?	\$ 31.00	?
16	FRONT WHEEL HOUSING LINER-RH <i>tom</i>	\$ 209.00	✓
17	WHEELS HOUSING LINER ATTACHMENT PART ?	\$ 78.00	?
18	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		\$ 10,803.00	
TOTAL LABOUR CHARGES		\$ 4,152.00	
GRAND TOTAL		\$ 14,955.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian *Wij*
Surveyed Date : 28/03/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : ~~Adrian Wij~~ are Authorised, 05 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant