

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0360/2018/GW  
Date : 23-Mar-18

**Vehicle NOT IN workshop. Kindly arrange for survey.**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

Owner's Name : Dr. Wong Chong Yu Kelvin  
Address : 9B Marlene Avenue  
Singapore 556621  
Telephone : HP +65 81265822  
Type of Claim : Third Party Claims  
Policy No. : 1800022575  
Vehicle No : **SLW 9160 Z**  
Model Code : Audi A4 Sedan 2.0 TFSI  
Model / Year : Mar-18  
Engine No : CVK 052310  
Chassis No : WAUZZZF41JA086181  
Mileage : -  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 21-Mar-18  
Place of Accident : 501 Stirling Road MDIS

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLW 9160 Z.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlights washer assy.	S/N \$ 360.00	
2	To dismantle and renew front bumper, rhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00	
3	To respray front bumper and rhs front fender.	\$ 1,500.00	
4	To carry out diagnostic check.	S/N \$ 192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 4,152.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLW 9160 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,849.00	
2	FRONT BUMPER AIR GUIDE-RH	\$ 73.00	
3	FRONT BUMPER GUIDE SECTION-RH	\$ 32.00	
4	FRONT BUMPER AIR GUIDE-RH	\$ 118.00	
5	FRONT FENDER-RH	\$ 665.00	
6	FRONT FENDER CLOSING ELEMEN-RH	\$ 44.00	
7	FRONT FENDER BRACKET-RH	\$ 31.00	
8	FRONT FENDER DEFORMATION BRACKET-RH	\$ 43.00	
9	FRONT FENDER BRACE-RH	\$ 103.00	
10	FRONT FENDER LEDGE COVER-RH	\$ 20.00	
11	FRONT FENDER COVER	\$ 27.00	
12	LED HEADLIGHT-RH	\$ 6,973.00	
13	FRONT WHEEL SPOILER-RH	\$ 63.00	
14	STONE CHIP GUARD-RH	\$ 44.00	
15	FRONT FENDEER EXTENSION BRACKET-RH	\$ 31.00	
16	FRONT WHEEL HOUSING LINER-RH	\$ 209.00	
17	WHEELS HOUSING LINER ATTACHMENT PART	\$ 78.00	
18	SUNDRIES	\$ 400.00	
	<b>TOTAL SPARE PARTS</b>	<b>\$ 10,803.00</b>	
	<b>TOTAL LABOUR CHARGES</b>	<b>\$ 4,152.00</b>	
	<b>GRAND TOTAL</b>	<b>\$ 14,955.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant