



Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 25151300M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
21/3/2018	MAIN	41980

OWN DAMAGE CLAIM			
ESTIMATE COST OF REPAIR FOR VEHICLE NO: SKW4429U			
Make/Model	DOA	Policy No	Chassis No.
MERCEDES BENZ ML350	19/03/2018@1000	GA082800/1	WDC1641862A614219 (2010)


Qty	Unit	Description	Amount
1.00	pc	Front Bonnet	1,950.00 bt
1.00	pc	Front Bonnet Logo	55.00 net
13.00	pc	Front Bonnet Sponge Clips @ \$5	65.00 7 X ny
1.00	pc	Front Fender LH	1,045.00 bu
1.00	pc	Front Fender Inner Shield (FRONT)	280.00 de
1.00	pc	Front Fender Inner Shield (REAR)	230.00 de
8.00	pc	Front Fender Inner Shield Clips @ \$5	40.00 net
1.00	pc	Front Bumper	1,610.00 de
1.00	pc	Front Bumper Retainer LH	42.00 dis
1.00	pc	Front Bumper Inner Garnish/Tray	500.00 dis
12.00	pc	Front Bumper Inner Garnish/Tray rivets @ \$5	60.00 net
1.00	pc	Front Bumper Foglight LH	230.00 dis
1.00	pc	Front Bumper Sponge LH	165.00 net
1.00	pc	Front Bumper Lower Garnish	285.00 de
1.00	pc	Front Bumper Lower Metal Cover	920.00 bt
1.00	pc	Front Bumper Sensor Far LH	160.00 dis
1.00	pc	Front Bumper Sensor Far CTR LH	160.00 de
1.00	pc	Front Bumper Sensor Wiring	130.00 dis
1.00	pc	Front Bumper Nozzle LH	160.00 dis
1.00	pc	Front Bumper Nozzle Cover LH	60.00 dis
1.00	pc	Front Bumper Nozzle Hose	85.00 net
1.00	pc	Front Grille	800.00 net
1.00	pc	Front Headlamp LH	2,800.00 net
1.00	pc	Front Headlamp Balast LH	1,240.00 7 dis
1.00	pc	Front Headlamp Top Panel LH	715.00 bt
1.00	pc	Wiper Tank	200.00 de
1.00	pc	Wiper Tank Sensor	30.00 7 dis

CHARN'S CUSTOMCRAFT

Subtotal

GST 7%

Total



Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 25151300M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
21/3/2018	MAIN	41980

OWN DAMAGE CLAIM			
ESTIMATE COST OF REPAIR FOR VEHICLE NO: SKW4429U			
Make/Model	DOA	Policy No	Chassis No.
MERCEDES BENZ ML350	19/03/2018@1000	G4082800/1	WDC1641862A614219 (2010)

Qty	Unit	Description	Amount
1.00	pc	Front W/S wiper nozzle hose	160.00 ✓ <i>ant</i>
1.00	pc	Radiator Spare Tank	200.00 ✓ <i>car</i>
1.00	pc	Front Kunkle LH	1,570.00 ✓ <i>bt</i>
1.00	pc	Front Kunkle Bearing LH	230.00 ✓ <i>nn</i>
1.00	pc	Front Lower Arm LH	1,150.00 ✓ <i>bt</i>
1.00	pc	Front Top Arm LH	550.00 ✓ <i>bt</i>
1.00	pc	Front Shock Absorber LH	590.00 ✓ <i>bt</i>
		Subtotal - PARTS ONLY	18,467.00
			<i>old damage</i> 35.00 ✓
1.00	pc	Front No. Plate (S/NETT)	304 80% 380.00 <i>pushed</i> ✓
1.00	pc	Front Tyre LH (S/NETT)	0.00 <i>del</i>
1.00	pc	Front Rim LH (S/NETT) - TBA	\$80
		Check wiring function	40.00 30 ✓
		Alignment	60.00 ✓
		Labour to remove and replace undercarriage front LH	280.00 150? <i>photo</i>
		Remove necessary parts: jacking, panel beating, repair and straighten front inner panel, front headlamp top panel LH, front headlamp side panel LH, front bonnet, front fender LH/RH, front bumper, front door LH, front wsside pillar and wheel housing LH (BULKHEAD SHIFTED)	1,200.00 900
		Putty and respray front inner panel, front bonnet, front fender LH/RH, front bumper, front door LH, front ws side pillar and wheel housing LH.	900 1,000.00

CHARN'S CUSTOMCRAFT

Subtotal

GST 7%

Total



Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 25151300M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
21/3/2018	MAIN	41980

OWN DAMAGE CLAIM			
ESTIMATE COST OF REPAIR FOR VEHICLE NO: SKW4429U			
Make/Model	DOA	Policy No	Chassis No.
MERCEDES BENZ ML350	19/03/2018@1000	GA082800/1	WDC1641862A614219 (2010)

Qty	Unit	Description	Amount
-----	------	-------------	--------

Note: The above is an estimate only. If other parts requested during the course of repair, we will inform you accordingly.

All new/O.E.M/used parts are subject to availability.

Tan Jiah 97495749
Exp \$400
Removal before paint
22/3/18 @ 1700
Sua @ (Removal) 1700
Johays
Authorised: [Signature]
22/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CHARN'S CUSTOMCRAFT

[Signature]

Subtotal	\$21,462.00
GST 7%	\$1,502.34
Total	\$22,964.34

24,309